## **EQUIPMENT**

PP0TX-01

Dial indicator	Commutator runout
High-temperature grease	
Magnetic finger	Steel ball
Press	Magnetic switch terminal kit
Pull scale	Brush spring
Sandpaper	Commutator
Torque wrench	
V-block	Commutator
Vernier calipers	Commutator, Brush