

Paint Application Guide

This guide outlines best practices for applying paint to vehicle surfaces, ensuring a high-quality finish, long-lasting protection, and accurate color matching.

1. Surface Preparation

- Clean the surface thoroughly to remove dirt, grease, and contaminants.
 - Sand the area to create a smooth, even base for paint adhesion.
 - Repair dents or imperfections using approved fillers, then sand to match panel contours.
 - Mask surrounding areas to protect components not being painted.
-

2. Primer Application

- Apply a suitable primer to the prepared surface.
 - Ensure even coverage to promote adhesion and prevent corrosion.
 - Allow the primer to dry fully according to manufacturer specifications.
 - Sand lightly if necessary to create a smooth base for the top coat.
-

3. Base Coat Application

- Match the paint using the factory paint code to ensure accurate color.
 - Apply the base coat in thin, even layers.
 - Allow each layer to flash off (partially dry) before applying the next.
 - Avoid over-spraying, which can lead to runs or uneven texture.
-

4. Clear Coat Application

- Apply a clear coat to protect the base color and provide gloss.
- Ensure even coverage and smooth finish.
- Allow sufficient drying or curing time between layers.
- Inspect for any surface imperfections and lightly sand if needed before the final coat.

5. Drying and Curing

- Follow manufacturer-recommended drying and curing times.
- Avoid handling or exposing the surface to moisture or dust until fully cured.
- Use controlled environments where possible to prevent contamination and achieve uniform finish.

6. Finishing and Polishing

- Once cured, inspect the surface for minor imperfections.
- Use polishing and buffing techniques to achieve a uniform gloss.
- Remove masking materials carefully to avoid scratching or chipping the fresh paint.

7. Safety and Handling

- Always wear protective gear including gloves, masks, and eye protection.
- Work in well-ventilated areas to reduce exposure to fumes.
- Store paints and chemicals in a controlled environment according to manufacturer instructions.

8. Documentation and Quality Control

- Record paint code, batch number, and process details for reference.
- Take before-and-after photos to verify quality.