

Refinish Procedures

This guide outlines the steps required to properly refinish vehicle surfaces after repairs, ensuring durability, appearance, and accurate color matching.

1. Surface Preparation

- Clean the area thoroughly to remove dirt, grease, and contaminants.
 - Sand the damaged or repaired area to create a smooth surface for paint adhesion.
 - Repair any dents or imperfections using approved fillers, then sand to match surrounding contours.
 - Mask off adjacent panels, trim, and components to prevent overspray.
-

2. Primer Application

- Apply an appropriate primer to the prepared surface.
 - Ensure complete and even coverage to promote adhesion and prevent corrosion.
 - Allow primer to dry completely according to manufacturer instructions.
 - Lightly sand primer if needed to achieve a smooth base for the top coat.
-

3. Base Coat Application

- Match the paint using the vehicle's factory paint code for accurate color.
 - Apply the base coat in thin, even layers.
 - Allow each layer to partially dry (flash off) before applying the next.
 - Avoid heavy coats to prevent runs or uneven texture.
-

4. Clear Coat Application

- Apply a clear coat to protect the base color and provide gloss.
- Ensure even coverage and smooth finish.
- Allow sufficient drying or curing time between layers.
- Inspect for minor imperfections; lightly sand if necessary before the final coat.

5. Drying and Curing

- Follow manufacturer-recommended drying and curing times.
- Avoid exposing freshly painted surfaces to moisture, dust, or direct contact.
- Use controlled environments where possible to maintain consistent results.

6. Finishing and Polishing

- Once the coating is fully cured, inspect the surface for imperfections.
- Use polishing and buffing to achieve a uniform gloss.
- Remove masking materials carefully to avoid chipping or scratches.

7. Safety Considerations

- Wear gloves, masks, and eye protection while sanding and painting.
- Work in well-ventilated areas to reduce exposure to fumes.
- Store paints, solvents, and chemicals in appropriate conditions according to manufacturer guidelines.

8. Documentation and Quality Control

- Record paint codes, batch numbers, and process details for future reference.
- Capture before-and-after images to verify finish quality.
- Ensure that the refinished surface meets manufacturer standards for appearance, color match, and durability.