
(a) slalom at 0.6 m/s, 36 m, wheel encoders read at 2 Hz
y [m]
x [m]
true path (continuous)
exact exp, at samples
Euler: move, then turn
RK2: midpoint heading
(b) zoom on the last 4 m
(c) error caused by the integrator alone
error vs. exact [cm]
time [s]
Euler, 10 Hz
Euler, 2 Hz
RK2, 10 Hz
RK2, 2 Hz