

**14. Ghim Moh** (27 nos.)

| Dialysis Centre | Condenser             | Model      | Serial  | FCU No.                    | Fan Coil                               | Serial                        | Location   |
|-----------------|-----------------------|------------|---------|----------------------------|--|-------------------------------|--|
| Daikin          | <u>Area 1</u><br>CU 6 | 3MKS71ESGE | E009634 | FCU 6A<br>FCU 6B<br>FCU 6C | FTKS25DVM<br>FFQ25BV1B9<br>FTKS 25 DVM | E014150<br>E006271<br>E014119 | Bi Carb<br>Re Use<br>NM Office                                     |
| Daikin          | CU 7                  | 3MKS71ESGE | E009628 | FCU 7A<br>FCU 7B<br>FCU 7C | FTKS25DVM<br>FTKS25DVM<br>FFQ35BV1B    | E014147<br>E014109<br>E001365 | Isolation Room<br>Isolation Room<br>Patient Area-Wear Reprocessing |
| Daikin          | CU 8                  | 4MKS80ESGE | E005482 | FCU 8A<br>FCU 8B           | FFQ60BV1B9<br>FFQ50BV1B9               | E010465<br>E019500            | Patient Area - Stn 2<br>Patient Area - Stn 19 ~ 20                 |
| Daikin          | CU 9                  | 4MKS80ESGE | E005474 | FCU 9A<br>FCU 9B           | FFQ60BV1B<br>FFQ60BV1B                 | E001975<br>E001976            | Patient Area - Stn 4<br>Patient Area - Stn 17                      |
| Daikin          | CU 10                 | 4MKS80ESGE | E005481 | FCU 10A<br>FCU 10B         | FFQ60BV1B<br>FFQ60BV1B                 | E001972<br>E002027            | Patient Area - Stn 5 ~ 6<br>Patient Area - Stn 15                  |
| Daikin          | CU 11                 | 4MKS80ESGE | E005476 | FCU 11A<br>FCU 11B         | FFQ60BV1B<br>FFQ60BV1B                 | E001996<br>E001956            | Patient Area (Nursing Counter Upside) Patient Area- Stn 12 ~ 14    |
| Daikin          | CU 12                 | 4MKS80ESGE | E005482 | FCU 12A<br>FCU 12B         | FFQ60BV1B<br>FFQ60BV1B                 | E001970<br>E001971            | Patient Area - Stn 8 ~ 9 Patient Area - Stn 10 ~ 11                |
| Daikin          | CU 13                 | RKS50AVMG  | E000428 | FCU 13A                    | FFQ50BV1B                              | E019500                       | Waitinig Area  |
| Daikin          | Area 2<br>CU 1        | 3MKS71ESGE | E009635 | FCU 1A<br>FCU 1B           | FTKS35DVM<br>FTKS35DVM                 | E106016<br>E106023            | Staff Room<br>Staff Room   |
| Daikin          | CU 2                  | RKS50GVMG  | E003064 | FCU 2A                     | FTKS50GVMG                             | E003217                       | RO Room  |
| Daikin          | CU 3                  | RKS50GVMG  | E003052 | FCU 3A                     | FTKS50GVMG                             | E003214                       | RO Room  |
| Daikin          | CU 4                  | 3MKS71ESGE | E009644 | FCU 4A<br>FCU 4B<br>FCU 4C | FTKS25DVM<br>FTKS25DVM<br>FTKS25DVM    | E014148<br>E014143<br>E014113 | BME Room<br>Waiting Area<br>Corridor                               |
| Daikin          | CU 5                  | 3MKS71ESGE | E009650 | FCU 5A<br>FCU 5B<br>FCU 5C | FTKS25DVM<br>FTKS25DVM<br>FTKS25DVM    | E014146<br>E014145<br>E014100 | Office 1<br>Waiting Area<br>Consulation Room                       |

| 15. Hot | ugang I | (16 nos.) |
|---------|---------|-----------|
|         |         |           |

| Dialysis Centre | Condenser | Model      | Serial  | FCU No.      | Fan Coil           | Serial             | Location                                 |
|-----------------|-----------|------------|---------|--------------|--------------------|--------------------|--|
| Daikin          | CU 1      | RZR125MYM  | E005446 | 1            | FHYC125KVE5        | E010574            | Patient Area - Near Stn 11               |
| Daikin          | CU 2      | RZR125MYM  | E002819 | 2            | FCQ125KAVEA        | E008078            | Patient Area - Nurse Stn 2, 18 ~ 19      |
| Daikin          | CU 3      | RZR125LUV1 | E002032 | 3            | FCQ125LUV1         | E006228            | Patient Area - Nurse Stn 1 & 2           |
| Daikin          | CU 4      | R125KY 1   | 6700085 | 4            | FHYC125KVE 5       | E006090            | Patient Area - Stn 10 Near Nurse Counter |
| Daikin          | CU 5      | RZR100LUV1 | E003112 | 5            | FCQ100LUV1         | E005054            | Main Entrance-Waiting Area               |
| Daikin          | CU 6      | R50GV1G    | E012248 | 6            | FT50GV1G           | E012231            | Water Treatment Room                     |
| Daikin          | CU 6A     | R50GV19    | 2900111 | 6            | FT50KD50FVM        | E031416            | Water Treatment Room                     |
| Daikin          | CU 7      | R60GV1G    | E000667 | 7            | FT60GV1G           | E000515            | Pantry                                   |
| Daikin          | CU 8      | RKD50BVM   | E031904 | 8            | FT50GAVE           | 0903242            | Doctor Room                              |
| Daikin          | CU 9      | R25GV1     | 4900697 | 9            | FT25BSG            | 4903643            | Technician Room                          |
| Daikin          | CU 10     | RZR125MYM  | E005446 | 10           | FCQ125KAVEA        | E010574            | Bi-Carb Corridor                         |
| Daikin          | CU 11-1   | R35DV1     | E037883 | 11-1         | FT 35DVM           | E042190            | Hep Wash Bay                             |
| Daikin          | CU 11-2   | RKS50GVMG  | E019113 | 11-2         | FTKS50GVMG         | E017566            | Re-Processing Room                       |
| Daikin          | CU 12     | R100KYI    | 6700178 | 12           | FHYC100KVE 5       | E001832            | DCCN Corridor                            |
| Daikin          | CU 13     | MA56EV16   | 4901361 | 13-1<br>13-2 | FT25BSG<br>FT25BSG | 4905620<br>4905649 | DCCN Room (System 2)                     |



**16. Hougang II** (27 nos.)

| 16. Hougang II  | (27 nos.) |               |          |  |  |                      |  |
|-----------------|-----------|---------------|----------|--|--|----------------------|--|
| Dialysis Centre | Condenser | Model         | Serial   | FCU No.  | Fan Coil   | Serial               | Location   |
| Toshiba         | CU 1A     | RAVSM1102AT-E |          | FCU 1A-2   | RAVSM562 UT-E  |                      | Activity Corner  |
| Daikin          | CU 1C     | R71LUV15      | E031205  | FCU 1C   | FHYC71KVE5   | E014465              | Waiting Area   |
| Daikin          | CU 2A     | R71LUV15      | E029991  | FCU 2A   | FHYC71KVE5   | E014039              | Patient Area Stn 1,2   |
| Toshiba         | CU 3A     | RAV-SM802AT-E |          | FCU 3A   | RAV-SM802UT-E  |                      | Patient Area   |
| Toshiba         | CU 4A     | RAV-SM802AT-E |          | FCU 4A   | RAV-SM802UT-E  |                      | Patient Area   |
| Toshiba         | CU 5A     | RZR60LVVM     | E003477  | FCU 5A   | FCQ60LUV1  | E004283              | Patient Area (Station 13 & 14)                                 |
| Toshiba         | CU 6A     | RAV-SM802AT-E |          | FCU 6A   | RAV-SM802UT-E  |                      | Patient Area   |
| Daikin          | CU 6C     | R71LUV15      | E030005  | FCU 6C   | FHYC71KVE5   | E013971              | Patient Area Stn 10,11,12                                      |
| Daikin          | CU 7A     | RZR71LVVMG    | E001269  | FCU 7A   | FCQ71LUV1  | E011021              | Patient Area   |
| Toshiba         | CU 8A     | RZR71LVVMG    | E006720  | FCU 8A   | FCQ71LUV1  | E026789              | Patient Area   |
| Toshiba         | CU 9A     | RAV-SM802AT-E |          | FCU 9A   | RAV-SM802UT-E  |                      | Patient Area   |
| Toshiba         | CU 10A    | RAV-SM562AT-E |          | FCU 10A  | RAV-SM562UT-E  |                      | Dialysis Room  |
| Toshiba         | CU 11A    | RAV-SM562AT-E |          | FCU 11A  | RAV-SM562UT-E  | 706A0160             | Re-Processing Room   |
| Toshiba         | CU 12A    | MCY-MAP0501HT | 706C0115 | FCU 12A-1<br>FCU 12A-2<br>FCU 12A-3<br>FCU 12A-4 | MMK-AP0121H<br>MMK-AP0181H<br>MMK-AP0121H<br>MMU-AP0091H |                      | Bi-Carb Room<br>Storage<br>Nurse Manager Room<br>Nurse Station |
| Toshiba         | CU 1B     | MCY-MAP0401HT | 706C0278 | FCU 1B-1<br>FCU 1B-2<br>FCU 1B-3                 | MMK-AP0181H<br>MMK-AP0121H<br>MMK-AP0091H                |                      | Staff Partry<br>Consultation Room<br>Activity Room             |
| Toshiba         | CU 2B     | RAS-3M23YACV  | 708P0364 | FCU 2B-1<br>FCU 2B-2                             | RAS-M13NKCV<br>RAS-M13NKCV                               | 73000022<br>73000017 | Counselling Room<br>Entrance                                   |
| Toshiba         | CU 3B     | RAS-10SAV-E   | 72800448 | FCU 3B   | RAS-10SKV-E  | 72800880             | BME Room   |
| Toshiba         | CU 4B     | RAV-SM562AT-E |          | FCU 4B   | RAV-SM562UT-E  |                      | Water Treatment Room   |
| Daikin          | CU 4B-1   | R50GV1G       | E013324  | FCU 4B-1   | FT50GV1G   | E013089              | Water Treatment Room   |
| Toshiba         | CU 5B     | RAS-3M23YACV  | 708P0383 | FCU 5B-1<br>FCU 5B-2                             | RAS-M13NKCV<br>RAS-M13NKCV                               | 73000030<br>73000035 | Common Corridor<br>Common Corridor                             |

17. Integrated Renal Centre @ Level 1 (19 nos.)

| Dialysis Centre | Condenser | Model     | Serial           | FCU No.   | Fan Coil | Serial  | Location                        |
|-----------------|-----------|-----------|------------------|-----------|----------|---------|---------------------------------|
| Daikin          | VCU/1-6   | RXQ22TAS  | E003115, E001750 | VFU/1-6C  | FXFQ63S  | C002089 | Registration Counter            |
| Daikin          | VCU/1-7   | RXQ10TAYM | E001693          | VFU/1-7C  | FXFQ63S  | C002080 | Registration Counter            |
| Daikin          | VCU/1-8   | RXQ14TAYM | E001725          | VFU/1-8A  | FXFQ50L  | E017194 | New Centralized Pallet Stores 2 |
|                 |           |           |                  | VFU/1-8B  | FXFQ50L  | E017259 |                                 |
|                 |           |           |                  | VFU/1-8C  | FXFQ50L  | E017193 |                                 |
|                 |           |           |                  | VFU/1-8D  | FXFQ50L  | E017195 |                                 |
|                 |           |           |                  | VFU/1-8F  | FXFQ63L  | E025778 | New Centralized Pallet Stores 1 |
|                 |           |           |                  | VFU/1-8H  | FXAQ25P  | E020079 | New FCC Rm                      |
|                 |           |           |                  | VFU/1-8I  | FXFQ50L  | E017758 | Corridor Outside New M.T.       |
| Daikin          | VCU/1-9   | RXQ12TAYM | E003097          | VFU/1-9A  | FXAQ25P  | E020151 | New Pantry                      |
|                 |           |           |                  | VFU/1-9B  | FXFQ125L | E036307 | New Therapy Space               |
|                 |           |           |                  | VFU/1-9C  | FXFQ125L | E020148 |                                 |
| Daikin          | VCU/1-10  | RXQ16TAYM | E001369          | VFU/1-10A | FXFQ125L | E020150 | New Therapy Space               |
|                 |           |           |                  | VFU/1-10B | FXFQ125L | E020153 |                                 |
|                 |           |           |                  | VFU/1-10C | FXFQ125L | E020152 |                                 |
|                 |           |           |                  |           |          |         |                                 |
|                 |           |           |                  |           |          |         |                                 |
| Daikin          | SCU/1-2   | RZR50LVVM | E006353          | SFU/1-2   | FCQ50L   | E006684 | Ante Room                       |
| Daikin          | SCU/1-3   | RZR50LVVM | E006326          | SFU/1-3   | FCQ50L   | E006679 |                                 |
| Daikin          | SCU/1-4   | RKS25     | E035631          | SFU/1-4   | FTKS25   | E200765 | MDF RM                          |
| Daikin          | SCU/1-5   | RKS25     | E035580          | SFU/1-5   | FTKS25   | E200808 | FCC Rm                          |



| Integrated Renal Ce<br>Dialysis Centre | Condenser | Model       | Serial   | FCU No.              | Fan Coil           | Serial             | Location                                     |
|--|-----------|-------------|----------|----------------------|--------------------|--------------------|--|
| Daikin                                 | VCU/3-1   | RXQ18TAYM   | E001395  | VFU/3-1A             | FXFQ50L            | E018087            | New Admin Office 1                           |
| Jaikin                                 | VCU/3-1   | RAQIOTATIVI | E001395  | VFU/3-1A<br>VFU/3-1B | FXFQ50L<br>FXFQ50L | E018251            | New Admin Office 1                           |
|  |           |             |          | VFU/3-1B<br>VFU/3-1C | FXFQ80L            | E020892            | New Datient Thereny Area                     |
|  |           |             |          |                      |                    |                    | New Patient Therapy Area                     |
|  |           |             |          | VFU/3-1D             | FXFQ40L            | E009508            | New Admin Office 1                           |
|  |           |             |          | VFU/3-1E             | FXFQ25L            | E008942            | New Admin Office 1 Pantry                    |
|  |           |             |          | VFU/3-1F             | FXFQ50L            | E018252            | New Admin Office 1                           |
|  |           |             |          | VFU/3-1G             | FXFQ80S            | C001767            | New Patient Therapy Area                     |
|  |           |             |          | VFU/3-1H             | FXFQ50L            | E018446            | New Admin Office 1                           |
| Daikin                                 | VCU/3-2   | RXQ18TAYM   | E001614  | VFU/3-2A             | FXFQ50L            | E018253            | New Admin Office 1                           |
|  |           |             |          | VFU/3-2B             | FXFQ50L            | E018450            |  |
|  |           |             |          | VFU/3-2C             | FXFQ50L            | E018254            |  |
|  |           |             |          | VFU/3-2D             | FXFQ80S            | C001753            | New Patient Therapy Area                     |
|  |           |             |          | VFU/3-2E             | FXFQ80S            | C001768            |  |
|  |           |             |          | VFU/3-2F             | FXFQ80S            | C001747            |  |
|  |           |             |          | VFU/3-2G             | FXFQ80S            | C001743            |  |
| Daikin                                 | VCU/3-3   | RXQ16TAYM   | E001634  | VFU/3-3A             | FXFQ80S            | C001774            | New Patient Therapy Area                     |
| Jainiii                                | VCO/3-3   | IXXQIDIATM  | L001034  | VFU/3-3B             | FXFQ80S            | C001774<br>C001772 | New Falletit Therapy Area                    |
|  |           |             |          | VFU/3-3B<br>VFU/3-3C | FXFQ80S            | C001772            |  |
|  |           |             |          | VFU/3-3D             |                    |                    |  |
|  |           |             |          |                      | FXFQ80S            | C001744            |  |
|  |           | DV0074144   |          | VFU/3-3E             | FXFQ80S            | C001752            | I.T. 0                                       |
| Daikin                                 | VCU/3-4   | RXQ8TAYM    | E002309  | VFU/3-4A             | FXHQ100            | E015996            | IT Server Rm                                 |
|  |           |             |          | VFU/3-4B             | FXHQ100            | E017995            |  |
| Daikin                                 | VCU/3-5   | RXQ8TAYM    | E002301  | VFU/3-5A             | FXHQ100            | E017999            | IT Server Rm                                 |
|  |           |             | VFU/3-5B | FXHQ100              | E017996            |                    |  |
| Daikin                                 | VCU/3-6   | RXQ20TAYM   | E001720  | VFU/3-6A             | FXFQ32L            | E010849            | New Consulting Rm                            |
|  |           |             |          | VFU/3-6B             | FXFQ32L            | E010852            | New Counselling Rm 2                         |
|  |           |             |          | VFU/3-6C             | FXFQ32L            | E010846            | New Counselling Rm 1                         |
|  |           |             |          | VFU/3-6D             | FXAQ25P            | E033902            | New Pantry                                   |
|  |           |             |          | VFU/3-6E             | FXFQ32L            | E010848            | Corridor Outside New H.T                     |
|  |           |             |          | VFU/3-6F             | FXFQ63L            | E028044            | New Training Facilities Rm                   |
|  |           |             |          | VFU/3-6G             | FXFQ63L            | E028241            | Trew Training Facilities 1411                |
|  |           |             |          | VFU/3-6H             | FXFQ32L            | E010850            | Corridor outside New Counselling Rm 1        |
|  |           |             |          | VFU/3-6L             |                    | E010847            | Corridor Outside New F.T.                    |
|  |           |             |          |                      | FXFQ32L            |                    |  |
|  |           |             |          | VFU/3-6I             | FXFQ50S            | C001369            | New Lift Lobby & Waiting Area                |
|  |           |             |          | VFU/3-6J             | FXFQ50S            | C001374            |  |
|  |           |             |          | VFU/3-6K             | FXFQ50S            | C001371            |  |
| Daikin                                 | VCU/3-7   | RXQ12TAYM   | E003109  | VFU/3-7A             | FXFQ32L            | E010853            | Corridor ouside New Pantry                   |
|  |           |             |          | VFU/3-7B             | FXFQ63L            | E028257            | New Training Facilities Rm                   |
|  |           |             |          | VFU/3-7C             | FXFQ50S            | C001473            | New Lift Lobby & Waiting Area                |
|  |           |             |          | VFU/3-7D             | FXFQ50S            | C001372            |  |
|  |           |             |          | VFU/3-7E             | FXFQ50S            | C001370            |  |
|  |           |             |          | VFU/3-7F             | FXAQ25P            | E033900            | New Pandemic Store                           |
|  |           |             |          | VFU/3-7G             | FXFQ32L            | E010806            | Corridor Outside New M.T.                    |
| Daikin                                 | VCU/3-9   | RXQ6TAYM    | E000792  | VFU/3-9D             | FXFQ50L            | E018410            | New Facilities Management                    |
|  |           |             |          | VFU/3-9I             | FXFQ40L            | E009081            |  |
|  |           |             |          | VFU/3-9J             | FXFQ40L            | E009620            |  |
| Daikin                                 | VCU/3-10  | RXQ10TAYM   | E001741  | VFU/3-10A            | FXFQ40L<br>FXFQ63L | E028258            | New Peritoneal Dialysis - Simulation Rm      |
| Jainii I                               | VCO/3-10  | RACIOTATIVI | E001741  |                      |                    |                    | INEW FEITUNEAL DIAIYSIS - SIITIUIAIIOTI KITI |
|  |           |             |          | VFU/3-10B            | FXFQ63L            | E028274<br>E027600 |  |
|  |           |             |          | VFU/3-10C            | FXFQ63L            |                    |  |
|  | 1         |             | 1        | VFU/3-10D            | FXFQ63L            | E028279            | İ  |



**18. Jurong East** (17 nos.)

| Dialysis Centre | Condenser | Model    | Serial  | FCU No.                       | Fan Coil                              | Serial                        | Location                                 |
|-----------------|-----------|----------|---------|-------------------------------|---------------------------------------|-------------------------------|--|
| Daikin          | CU-1      | RXMQ6AVE | E004204 | FCU 1-1<br>FCU 1-2<br>FCU 1-3 | FXFQ40AVM<br>FXFQ50AVM<br>FXFQ40AVM   | E004323<br>E008295<br>E004319 | Doctor Room<br>Waiting Area 1<br>RO Room |
| Daikin          | CU-2      | RXMQ6AVM | E004217 | FCU 2-1<br>FCU 2-2<br>FCU 2-3 | FXFQ40AVM<br>FXFQ32AVM<br>FXFQ80AVM   | E004319<br>E005057<br>E012451 | RO Room<br>BME<br>Staff Pantry           |
| Daikin          | CU-3      | RXMQ6AVE | E004219 | FCU 3-1<br>FCU 3-2            | FXFQ50AVM<br>FXFSQ100AVM              | E008296<br>E001125            | Store<br>Treatment Area                  |
| Daikin          | CU-4      | RXMQ8AY1 | E001750 | FCU 4-1<br>FCU 4-2            | FXFSQ80AVM<br>FXFSQ100AVM             | E001131<br>E000914            | Waiting Area 2<br>Treatment Area         |
| Daikin          | CU-5      | RXMQ8AY1 | E001751 | FCU 5-1<br>FCU 5-2<br>FCU 5-3 | FXFQ40AVM<br>FXFSQ100AVM<br>FXAQ40PVE | E004359<br>E000917<br>E028542 | Store 2<br>Treatment Area<br>Switch Room |
| Daikin          | CU-6      | RXMQ8AY1 | E001840 | FCU 6-1<br>FCU 6-2            | FXFSQ80AVM<br>FXFSQ100AVM             | E001134<br>E000913            | Nursing Area<br>Treatment Area           |
| Daikin          | CU-7      | RXMQ8AY1 | E001749 | FCU 7-1<br>FCU 7-2            | FXFSQ100AVM<br>FXFSQ100AVM            | E000918<br>E001132            | Treatment Area Treatment Area            |

Mechanical Ventilation Fan List (09 nos.)

| WCCHamcar Ventuat | - (00     | 1103.)               |           |                |          |
|-------------------|-----------|----------------------|-----------|----------------|----------|
| Fan No            | Brand     | Model                | Air Floow | Location       | Pressure |
| EAF-1             | Wall-Prop | VF-AB8R              | 360       | Toilet         | -        |
| EAF-2             | Cil       | R\$125L              | 250       | HC             | 100      |
| EAF-3             | Wall-Prop | VF-AB6R              | 240       | Janitor        | =        |
| EAF-4             | Wall-Prop | VF-AB6R              | 300       | Biohazard      | =        |
| EAF-5             | Cil       | R\$125L              | 180       | Staff WC       | 160      |
| EAF-6             | Cil       | RS100L.2CA           | 80        | Staff CR       | 160      |
| EAF-7A            | Axial     | AND 710/12-12/4AL-30 | 6640      | Treatment Area | 480      |
| EAF-7B            | Axial     | AND 710/12-12/4AL-30 | 6640      | Treatment Area | 480      |
| EAF-8             | Cil       | RS160                | 300       | Wash Area      | 120      |

**19. Jurong West I** (15 nos.)

| Dialysis Centre | Condenser | Model      | Serial  | FCU No.            | Fan Coil                | Serial             | Location                                |
|-----------------|-----------|------------|---------|--------------------|-------------------------|--------------------|---|
| Daikin          | CU 1-1    | RZR125LUY1 | E003070 | FCU1-1             | FCQ125LUV1              | E012133            | Patient Area (Stn 1, 2, 13 & 14)        |
|                 |           |            |         |                    |                         |                    | , |
| Daikin          | CU 1-2    | RZR100MVMG | E000683 | FCU1-2             | FCQ100KAVEA             | E006873            | Front Nurse Counter & Stn 5 & 6         |
| Daikin          | CU 1-3A   | RZR60LVVM  | E003480 | FCU1-3A            | FCQ60LUV1               | E004705            | Patient Area (Stn 7 & 8)                |
| Daikin          | CU 1-3B   | RZR60LVVM  | E000159 | FCU1-3B            | FCQ60LUV1               | E001606            | Patient Area (Stn 10,11, 19 & 20)       |
| Daikin          | CU 1-4    | RZR71LUV1  | E004033 | FCU1-4A<br>FCU1-4B | FTKS35DVM<br>STKS35DVM  | E178168<br>E178083 | Patient Area Stn 12<br>Freeze Room      |
| Daikin          | CU 1-5    | RZR50LVVM  | E001310 | FCU1-5             | FCQ50LUV1               | E002901            | Store                                   |
| Daikin          | CU 1-6    | RZR100MVMG | E004999 | FCU1-6             | FCQ100KAVEA             | E013437            | Waiting Area                            |
| Daikin          | CU 1-7    | RZR71LUV1  | E004033 | FCU1-7             | FCQ71LUV1               | E007004            | Bi-Carb / Re-Processing Room            |
| Daikin          | CU 1-8    | 3MKS71ESG  | E020266 | FCU1-8A<br>FCU1-8B | FTKS35DVM<br>FFQ50BV1B9 | E047787<br>E008391 | Nusre Manager Room<br>Pantry            |
| Daikin          | CU 1-9    | R25DV 1    | E020045 | FCU1-9A            | FT25DVM                 | E086339            | BME Room                                |
| Daikin          | CU 1-9A   | RKS50GVMG  | E045807 | FCU1-9B            | FTKS50GVMG              | E043775            | RO Room                                 |
| Daikin          | CU 1-9B   | R50GV19    | E006102 | FCU1-9C            | FHC50KVE5               | E008136            | Corridor                                |
| Daikin          | CU 1-10   | RKS50GVMG  | E049058 | FCU 1-10           | FTKS50GVMG              | E047871            | RO Room                                 |
|                 |           |            |         |                    |                         |                    |   |



| 20. Jurong West II (19 nos.) |                 |        |         |                      |                       |                    |   |  |  |
|------------------------------|-----------------|--------|---------|----------------------|-----------------------|--------------------|---|--|--|
| Dialysis Centre              | Condenser       | Model  | Serial  | FCU No.              | Fan Coil              | Serial             | Location                                |  |  |
| Daikin                       | Area 1<br>CU 1A | RKS25A | E000799 | FCU 1A               | FFQ25B                | E005380            | Waiting Area                            |  |  |
| Daikin                       | CU 1B           | RKS35A | E027378 | FCU 1B               | FFQ35B                | E008753            | Waiting Area                            |  |  |
| Daikin                       | CU 2            | RXMQ5P | E004090 | FCU 2-1<br>FCU 2-2   | FXFQ63L<br>FXFQ50L    | E014596<br>E008704 | Nurse Station<br>Nurse Station          |  |  |
| Daikin                       | CU 3            | RXMQ5P | E004059 | FCU 3-1<br>FCU 3-2   | FXFQ63L<br>FXFQ50LUV1 | E014593<br>E015636 | Nurse Station<br>Nurse Station          |  |  |
| Daikin                       | CU 4            | RXMQ5P | E004062 | FCU 4-1<br>FCU 4-2   | FXFQ63L<br>FXFQ50L    | E014595<br>E008694 | Nurse Station<br>Nurse Station          |  |  |
| Daikin                       | CU 5            | 3MKS71 | E037629 | FCU 5-1<br>FCU 2-5   | FTKS25<br>FFQ50       | E078319<br>E013742 | Utilities<br>Reprocessing Room          |  |  |
| Daikin                       | CU 6            | 3MKS71 | E037625 | FCU 6-1<br>FCU 2-6   | FTKS25<br>FFQ35B      | E078303<br>E008747 | Nurse Manager<br>Trolley & Machine Area |  |  |
| Daikin                       | Area 2<br>CU 9  | 3MKS71 | E037627 | FCU 9-1<br>FCU 9-2   | FTKS25<br>FTKS35      | E078424<br>E095387 | BME Room<br>Consultation Room           |  |  |
| Daikin                       | CU 10           | 4MKS80 | E022963 | FCU 10-1<br>FCU 10-2 | FFQ35<br>FFQ50        | E008658<br>E013812 | Training Cum Staff Room                 |  |  |
| Daikin                       | CU 11           | RKS35  | E027345 | FCU 11-1             | FTKS35                | E095332            | Locker                                  |  |  |
| Daikin                       | CU 12           | RKS35  | E027376 | FCU 12-1             | FTKS35                | E095381            | Water Treatment Room                    |  |  |
| Daikin                       | CU 13           | RKS35  | E001716 | 1-31 UCF             | FTKS35                | E095367            | Water Treatment Room                    |  |  |



**21. Kolam Ayer** (25 nos.)

| Dialysis Centre | Condenser      | Model     | Serial  | FCU No.              | Fan Coil                   | Serial                        | Location                              |
|-----------------|----------------|-----------|---------|----------------------|----------------------------|-------------------------------|---------------------------------------|
| Daikin          | Area 1<br>CU 1 | 4MKS80    | E022607 | 1-1<br>1-2           | FFQ25B<br>FFQ60B           | E004889<br>E007054            | Waiting Area<br>Waiting Area          |
| Daikin          | CU 2           | 5MKS100   | E005608 | 2-1<br>2-2           | FFQ60B<br>FFQ60B           | E007045<br>E006373            | Nurse Station<br>Nurse Station        |
| Daikin          | CU 3           | 5MKS100   | E005609 | 3-1<br>3-2           | FFQ60B<br>FFQ60B           | E006366<br>E006378            | Nurse Station<br>Nurse Station        |
| Daikin          | CU 4           | 5MKS100   | E005456 | 4-1<br>4-2           | FFQ60B<br>FFQ60B           | E006405<br>E007749            | Nurse Station<br>Nurse Station        |
| Daikin          | CU 5           | 5MKS100   | E005601 | 5-1<br>5-2           | FXFQ63AVM<br>FXFQ63AVM     | E021539<br>E021540            | Nurse Station<br>Nurse Station        |
| Daikin          | CU 6           | 5MKS100   | E005458 | 6-1<br>6-2           | FFQ60B<br>FFQ35B           | E006363<br>E009584            | Nurse Station<br>Nurse Station        |
| Daikin          | CU 7           | 3MKS71    | E037758 | 7-1<br>7-2           | FFQ50B<br>FTKS25           | E012800<br>E101715            | Reprocessing Room<br>BI Carb Room     |
| Daikin          | CU 8           | 3MKS71    | E037843 | 8-1<br>8-2           | FFQ25B<br>FTKS35           | E004842<br>E099206            | Clean Utility Room<br>A Solution Room |
| Daikin          | Area 2<br>CU 9 | 4MKS80    | E022653 | 9-1<br>9-2           | FTKS25<br>FFQ60B           | E100354<br>E007058            | Lockers<br>Pantry                     |
| Daikin          | CU 10          | 4MKS80    | E022680 | 10-1<br>10-2<br>10-3 | FFQ35B<br>FFQ25B<br>FFQ25B | E008329<br>E004888<br>E004906 | Doctor Room<br>NM<br>Waiting Area     |
| Daikin          | CU 11          | 3MKS71    | E038041 | 11-1<br>11-2         | FFQ35B<br>FFQ35B           | E008245<br>E008342            | BME<br>Clean Utility Room             |
| Daikin          | CU 12          | RKS50GVMG | E023441 | 12                   | FTKS50GVMG                 | E017751                       | Plant Room                            |
| Daikin          | CU 13          | RKS50GVMG | E023438 | 13                   | FTKS50GVMG                 | E017749                       | Plant Room                            |

**22. Marsiling** (28 nos.)

| Dialysis Centre                           | Condenser | Model           | Serial  | FCU No.              | Fan Coil               | Serial             | Location                       |
|---|-----------|-----------------|---------|----------------------|------------------------|--------------------|--------------------------------|
|   |           |                 |         |                      |                        |                    |                                |
| Daikin                                    | CU-1      | RXMQ6AVE (1PH)  | E002257 | FCU 1-1/1            | FXFQ50LUV1             | E017348            | Ro Room                        |
|   |           |                 |         | FCU 1-3              | FXFQ32LUV1             | E010196            | Waiting Area                   |
|   |           |                 |         | FCU 1-4              | FXFQ32LUV1             | E010206            | Waiting Area                   |
|   |           |                 |         | FCU 1-2              | FXFQ25LUV1             | E007662            | BME Room                       |
|   |           |                 |         | FCU 1-5              | FXFQ25LUV1             | E007660            | Nurse Manager Room             |
| Daileia                                   | CU 2      | RXMQ6AVE (1PH)  | E002104 | FCU 1-1/2            | FXFQ50LUV1             | E017347            | Ro Room                        |
| Daikin                                    | CU 2      | KANIQOAVE (TPH) | E002104 | FCU 1-1/2<br>FCU 1-6 | FXFQ25LUV1             | E017347<br>E007658 | Staff Pantry Room              |
|   |           |                 |         | FCU 1-6<br>FCU 1-7   |                        | E007656            |                                |
|   |           |                 |         | FCU 1-7<br>FCU 1-9   | FXFQ25LUV1             |                    | Staff Pantry Room              |
|   |           |                 |         |                      | FXFQ25LUV1             | E007667            | Store Room                     |
|   |           |                 |         | FCU 1-8              | FXFQ32LUV1             | E010201            | Doctor / NM Room               |
| Daikin                                    | CU 3      | RXMQ4AVE (1PH)  | E004486 | FCU 1-10             | FXFQ50LUV1             | E017823            | Holding Area                   |
| D Can |           |                 |         | FCU 1-11             | FXFQ50LUV1             | E017872            | Holding Area                   |
|   |           |                 |         |                      | . 7.11 00020 7 1       |                    |                                |
| Dalkin                                    | CU 4      | RXMQ4AVE (1PH)  | E004485 | FCU 1-12             | FXFQ50SVM              | C001376            | Dialysis Area                  |
|   |           | ` ,             |         | FCU 1-13             | FXFQ50SVM              | C000574            | Dialysis Area                  |
|   |           |                 |         |                      |                        |                    |                                |
| Daikin                                    | CU 5      | RXMQ4AVE (1PH)  | E000443 | FCU 1-14             | FXFQ50SVM              | C001377            | Dialysis Area                  |
|   |           |                 |         | FCU 1-15             | FXFQ50SVM              | C001368            | Dialysis Area                  |
| Daikin                                    | CU 6      | RXMQ6AVE (1PH)  | E002752 | FCU 1-16             | FXFQ50SVM              | C001367            | Dialysis Area                  |
| Daikiii                                   | 000       | KANGOAVE (IFTI) | L002132 | FCU 1-17             | FXFQ50SVM<br>FXFQ50SVM | C001307            | Dialysis Area                  |
|   |           |                 |         | FCU 1-17<br>FCU 1-18 | FXFQ50SVM<br>FXFQ25SVM | C000299<br>C001378 | Dialysis Area<br>Dialysis Area |
|   |           |                 |         |                      |                        |                    |                                |
|   |           |                 |         | FCU 1-19             | FXFQ25SVM              | C000303            | Dialysis Area                  |
| Daikin                                    | CU 7      | RXMQ6AVE (1PH)  | E002178 | FCU 1-20             | FXFQ50SVM              | C001373            | Dialysis Area                  |
|   |           | ,               |         | FCU 1-21             | FXFQ50SVM              | C001366            | Dialysis Area                  |
|   |           |                 |         | FCU 1-22             | FXFQ50SVM              | C001375            | Dialysis Area                  |
|   |           |                 |         |                      |                        |                    |                                |
| Daikin                                    | CU 8      | RXMQ5AVE (1PH)  | E002659 | FCU 1-23             | FXAQ20PVE              | E030138            | Isolation Room                 |
|   |           |                 |         | FCU 1-24             | FXAQ20PVE              | E030139            | Ante Room                      |
|   |           |                 |         | FCU 1-27             | FXAQ20PVE              | E030143            | Clean Utility                  |
|   |           |                 |         | FCU 1-26             | FXFQ32LUV1             | E010260            | Trolley Bay                    |
|   |           |                 |         | FCU 1-25             | FXFQ25LUV1             | E008448            | Trolley Bay                    |
|   |           |                 |         |                      |                        |                    |                                |

| 23. Mun Hean Medic              | al Store  | (2 nos.) |        |         |          |        |          |
|---------------------------------|-----------|----------|--------|---------|----------|--------|----------|
| Dialysis Centre                 | Condenser | Model    | Serial | FCU No. | Fan Coil | Serial | Location |
|                                 |           |          |        |         |          |        |          |
| 2 Sets Of Single Split (Daikin) |           |          |        |         |          |        |          |
| Wall Mounted (12,000btu)        |           |          |        |         |          |        |          |
| R35 + FT35 (Wireless Remote)    |           |          |        |         |          |        |          |