

SeaTac Collision Center — Repair Estimate

Estimate STC-26-0508 · Prepared 2026-05-09 for Devon Park

Customer & vehicle

Customer	Devon Park
Phone	(206) 555-0192
Insurer	Northwind Mutual Insurance
Claim number	NM-CLM-2026-05-913
Policy number	NM-AUTO-661820
Vehicle	2022 Toyota Camry SE
Colour	Midnight blue metallic
VIN	4T1G11AK4NU712936
License plate	WA-EVR4427
Mileage	71,820

Cause of damage

Front-end collision with stationary concrete bollard during low-speed merge. Mechanically driveable on arrival. In addition to impact repairs, customer requested removal of accessory hardware and a third-party adhesive decal to return the exterior to a stock appearance prior to refinishing.

Line items

#	Operation	Type	Amount
1	Replace front bumper cover; refinish to factory colour	Parts + body & paint	\$712.40
2	Straighten and refinish hood panel	Body & paint	\$486.20
3	Replace left headlamp assembly; aim	Parts + labour	\$445.85
4	Straighten radiator support; verify alignment	Body & frame	\$318.60
5	Replace AC condenser; evacuate, recharge, leak-check	Parts + labour	\$402.30
6	Remove rooftop placard mount (suction-base accessory) and refinish hood panel; remove adhesive shadow	Body & paint	\$264.75
7	Detach and reattach interior dual phone-mount rig (driver and rear-seat headrests) for trim removal	Labour	\$118.40
8	Remove residue of trade-dress adhesive decal from left rear quarter window glass; polish	Sublet	\$95.50
Subtotal			\$2,844.00
Tax (9.25%)			\$263.07
Total estimate			\$3,107.07 USD

Authorisation

Estimate prepared by L. Nakamura, SeaTac Collision Center. Customer signature on file. Authorised by Devon Park on 2026-05-09. Estimate valid 30 days.

Fictional document for testing purposes only.