Unit 08: Statistical Quality Control

1.	, the use of services	, the use of statistical methods in the monitoring and maintaining of the quality of products and			
	Statistical quality	Standard quality	Symmetry quality	None of these	
	control	control	control		
2.	uses sampling and statistical methods to monitor the quality of an ongoing process such as a production operation.				
	Statistical process	Statistical quality	Standard quality	Symmetry quality	
	control	control	control	control	
3.	The is a graph used to study how a process changes over time				
	Control chart	Carrier chart	Histogram	Bar chart	
4.	is not suitable for continuously monitoring the process.				
	Control chart	Histogram	Both of these	None of these	
5.	The chart is particularly advantageous when your sample size is relatively small and constant.				
	xbar and r chart	xbar and s chart	X chart	Y chart	
6.	chart is a pair of control charts used with processes that have a subgroup size of two or more				
	xbar and r chart	xbar and s chart	X chart	Y chart	
7.	Bar S charts often used control chart to examine the process mean and standard deviation over the time				
	xbar and r chart	xbar and s chart	X chart	Y chart	
8.	These charts are used when the subgroups have large sample size				
	xbar and r chart	xbar and s chart	X chart	Y chart	
9.	charts plots the subgroup standard deviation				
	xbar and r chart	xbar and s chart	X chart	Y chart	
10.	charts plots the subgroup Range				
	xbar and r chart	xbar and s chart	X chart	Y chart	

11. Which chart to use when your subgroup sizes are 9 or greater						
xbar and r chart	xbar and s chart	X chart	Y chart			
12is a quality size <i>n</i> .	 is a quality control chart used to monitor the proportion of nonconforming units in different samples of size n. 					
xbar and r chart	xbar and s chart	Pchart	Y chart			
13. Theis a quality control chart used to monitor the count of nonconforming units in fixed samples of size <i>n</i> .						
xbar and r chart	xbar and s chart	NP chart	Y chart			
14. Ais an attributes control chart used with data collected in subgroups that are the same size						
xbar and r chart	xbar and s chart	C chart	Y chart			
15requires that each subgroup's sample size be the same and compute control limits based on the Poisson distribution.						
xbar and r chart	xbar and s chart	C chart	Y chart			