

2012-05-14

MR. GUANGMING OUYANG
SHENZHEN HEMEIXIN ELECTRONICS CO LTD
ABV PCB&PCBA TECHNOLOGY CO LTD

SOUTH OF 5TH FL, BLDG 7, WANXIA INDUSTRIAL PARK, TONGFUYU INDUSTRIAL AREA, SHAJING TOWN, GONGHE VILLAGE SHENZHEN, GUANGDONG, 518100 CHINA

Our Reference: File E351431 Project No: 11CA59760

Subject: Notice of Completion of the Engineering Investigation and Requirement for an Initial

Production Inspection (IPI)-

USR- UL File establishment with a Single Layer PWB Type HMX-1 and Multilayer

PWB Type HMX-2

Dear MR. GUANGMING OUYANG,

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL.

The engineering investigation under the above project number has been completed. This letter does not authorize use of the UL Mark on the products under the above project number.

## UL 。

Before you may begin shipping product with the UL Mark at each of the manufacturing locations listed below, an Initial Production Inspection (IPI) must be successfully performed by a UL representative at the manufacturing location(s):

SHENZHEN HEMEIXIN ELECTRONICS CO LTD ABV PCB&PCBA TECHNOLOGY CO LTD

SOUTH OF 5TH FL, BLDG 7, WANXIA INDUSTRIAL PARK, TONGFUYU INDUSTRIAL AREA, SHAJING TOWN, GONGHE VILLAGE SHENZHEN, GUANGDONG, 518100 CHINA The IPI is intended to confirm that the manufacturer is capable of producing a product in accordance with UL's requirements. THE MANUFACTURER MAY NOT SHIP PRODUCTS WITH THE UL MARK UNTIL THE IPI HAS BEEN COMPLETED AND UL HAS FOUND THE PRODUCTS AT THE FACTORY TO COMPLY WITH OUR REQUIREMENTS. Once this has been successfully completed the manufacturer(s) will be granted authorization to ship products bearing the UL Recognition Mark.

It is the responsibility of SHENZHEN HEMEIXIN ELECTRONICS CO LTD to inform its manufacturers of that the IPI must be successfully completed before product may be shipped with the UL Mark. Instructions for the IPI will be sent to our inspection center nearest to each of your manufacturing locations. The contact information of the inspection center is provided at the end of this letter. Please contact the inspection center to schedule the IPI and ask any questions you may have regarding the IPI.

In any correspondence concerning this investigation, please refer to the above file and project number.

Sincerely, Reviewed by:

Lily Huang

Lumina Wang

Associate Pro

Engineer Associate Project Engineer
Department: 3014KGUB E-mail: lumina.wang@ul.com
Tel: 86 20 3213 1221

Yvonne Lu Deanna Dean

E-mail: Lily.Huang@ul.com

Project Engineer Senior Engineering Association E-mail: Yvonne.Lu@ul.com E-mail: Deanna.A.Dean@ul.com

CC:

Shenzhen Inspection Center750(For Manufacturer No. 100575-037)
Address: 10F, No.4018 Jintian Road, Anlian Building, Futian District, Shenzhen City, Guangdong Province, P.R.China
Mr. Bill Zhang
86-755-88286188, 15323830218
szic@ccicshenzhen.com.cn

CC: SHENZHEN TIAN HAI TEST TECHNOLOGY CO LTD

MR. PRINCE HUANG prince@tianhaitest.com