



RESTORATION OF MARKERS

COLLECTION




DISASSEMBLE



WORST OF THE WORST



REMOVE PAINT...



...NOT POWDER COAT



RUST-OLEUM PRIMER




1" STEEL TUBING



GRIND RUST SPOTS



PAINT SHOP



SPECIFIED BY MDT




BACK TO PAINT SHOP



DRY PRIOR TO SECOND COAT



ASSEMBLE AND STORE









INSTALLATION