



Normal

Description: E-1000 Hitachi

Description: E-1000 Hitachi

Sample Information	Equipment Information
--------------------	-----------------------

Account Information

ID: 402009

Name: **Greer Lime**

Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000
US

Parent Account: **MATTHEWS LUBRICANTS, INC.**

Sample ID: 25296334026

Service Level: **Essential**

Bottle ID: **a037323728**

Tested Lubricant: **MOBIL DELVAC 1300 SUPER 15W-40 (CK-4)**

Asset Class: **Engine**





Manufacturer: **HITACHI**

Model: **DIESEL.**

Lubricant: MOBIL DELVAC 1300 SUPER 15W-40
(CK-4)

Sample Data & Trends

Sample Info	Report Status	Normal	Normal	Normal	Normal	Normal
	Sample ID	24122429064	24240272032	25111141073	25240419041	25296334026
	Service Level	Essential	Essential	Essential	Essential	Essential
	Bottle ID	a016233378	a003623545	A033673481	a037065320	a037323728
	Tested Lubricant	MOBIL DELVAC 1300 SUPER 15W-40 (CK-4)	MOBIL DELVAC 1300 SUPER 15W-40 (CK-4)	MOBIL DELVAC 1300 SUPER 15W-40 (CK-4)	MOBIL DELVAC 1300 SUPER 15W-40 (CK-4)	MOBIL DELVAC 1300 SUPER 15W-40 (CK-4)
	Sampled	03 Apr 2024	09 Jul 2024	17 Mar 2025	13 Aug 2025	17 Oct 2025
	Reported	08 May 2024	30 Aug 2024	23 Apr 2025	29 Aug 2025	24 Oct 2025
	Equipment Age	28386	28717	29656	30210	30506
	Equipment UOM	Hours	Hours	Hours	Hours	Hours
	Oil Age					
	Make-up Volume					
	Oil Changed	Yes	Yes	Yes	Yes	Yes
	Filter Changed	Yes	Yes	Yes	Yes	Yes
	Lubricant	Contamination Rating	Normal	Normal	Normal	Normal
Equipment Rating		Normal	Normal	Normal	Normal	Normal
Lubricant Rating		Normal	Normal	Normal	Normal	Normal
Visc@100C (cSt)		13.5	12.9	12.8	12.5	12.1
Oxidation (Ab/cm)		5	5	6	4	4
Soot (Wt%)		0.41	0.66	0.70	0.68	0.63
Water (Vol.%)		NotDetected	NotDetected	NotDetected	NotDetected	NotDetected
Coolant Indicator		NotDetected	NotDetected	NotDetected	NotDetected	NotDetected
Wear (ppm)	Ag (Silver)	0	0	0	0	0
	Al (Aluminum)	1	1	1	2	2
	Cr (Chromium)	0	0	0	0	0
	Cu (Copper)	0	2	1	1	1
	Fe (Iron)	3	6	5	5	5
	Mo (Molybdenum)	37	38	43	39	42
	Ni (Nickel)	0	0	0	0	0
	Pb (Lead)	0	0	1	1	1
	Sn (Tin)	1	1	0	0	1
	Ti (Titanium)	0	0	0	0	0
Contaminant (ppm)	K (Potassium)	0	0	0	2	2
	Na (Sodium)	3	3	3	4	3
	Si (Silicon)	6	3	5	5	6
	V (Vanadium)	0	0	0	0	0
Additive (ppm)	B (Boron)	60	54	64	65	60
	Ba (Barium)	1	0	0	0	0
	Ca (Calcium)	1772	1772	1773	1665	1668
	Mg (Magnesium)	554	548	562	538	543
	P (Phosphorus)	865	859	854	799	824
	Zn (Zinc)	972	928	957	931	913



	Normal	
	Unit ID: 976	Asset ID: 50072648
	Description: E-1000 Hitachi	
Account Information	Sample Information	Equipment Information
ID: 402009 Name: Greer Lime Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US Parent Account: MATTHEWS LUBRICANTS, INC.	Sample ID: 25296334026 Service Level: Essential Bottle ID: a037323728 Tested Lubricant: MOBIL DELVAC 1300 SUPER 15W-40 (CK-4)	Asset Class: Engine Manufacturer: HITACHI Model: DIESEL Lubricant: MOBIL DELVAC 1300 SUPER 15W-40 (CK-4)

Continued

Recommendation/Comments

NO ACTION REQUIRED ON OIL OR ENGINE. Results indicate that all levels are within acceptable ranges. Examine progressive changes and monitor results for changing trends. Sample at next scheduled interval. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 17 Oct 2025 5:18 PM UTC - Josh Simmons - In Service Oil Sample Comments: Photo: