

MobilTM

Caution

Unit ID: 4-RK-2

Asset ID: 50074749

Description: Kiln 1 Drive Trunion Bearing 5

Account Information

Sample Information

Equipment Information

ID: 402009

Name: Greer Lime

Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US

Parent Account: MATTHEWS LUBRICANTS, INC.

Sample ID: 25147288001

Service Level: Essential

Bottle ID: a003623164

Tested Lubricant: MOBIL SHC 636

Asset Class: Circulating System

Manufacturer:

Model:

Lubricant: MOBIL SHC 636

Sample Data & Trends

Sample Info	Report Status	Alert	Alert	Alert	Normal	Caution
	Sample ID	24047458004	24162579013	24205294020	24330183018	25147288001
	Service Level	Essential	Essential	Essential	Essential	Essential
	Bottle ID	a022169321	a003616144	a029200168	a033578899	a003623164
	Tested Lubricant	MOBIL SHC 636	MOBIL SHC 636	MOBIL SHC 636	MOBIL SHC 636	MOBIL SHC 636
	Sampled	07 Feb 2024	03 Jun 2024	16 Jul 2024	13 Nov 2024	18 May 2025
	Reported	21 Feb 2024	18 Jun 2024	29 Jul 2024	27 Nov 2024	29 May 2025
	Equipment Age					
	Oil Age					
	Make-up Volume					
	Oil Changed			Yes		
	Filter Changed					
Lubricant	Contamination Rating	Normal	Normal	Normal	Normal	Normal
	Equipment Rating	Alert	Alert	Alert	Normal	Caution
	Lubricant Rating	Caution	Caution	Caution	Normal	Normal
	Visc@40C (cSt)	750.0	751.0	758.9	731.5	745.5
	TAN (mg KOH/g)	0.41	0.41	0.41	0.41	0.41
	Water (Hot Plate)	NotDetected	NotDetected	NotDetected	NotDetected	NotDetected
Wear (ppm)	Ag (Silver)	0	0	0	0	0
	Al (Aluminum)	0	0	0	0	0
	Cr (Chromium)	0	0	0	0	0
	Cu (Copper)	119	145	256	23	47
	Fe (Iron)	8	9	17	3	5
	Mo (Molybdenum)	0	0	0	0	0
	Ni (Nickel)	0	1	1	0	0
	Pb (Lead)	41	40	68	9	15
	Sn (Tin)	9	8	14	2	4
Contaminant (ppm)	K (Potassium)	0	0	0	0	0
	Na (Sodium)	1	0	0	0	0
	Si (Silicon)	4	5	7	5	5
	B (Boron)	0	0	0	0	2
Additive (ppm)	Ba (Barium)	0	0	0	0	0
	Ca (Calcium)	14	15	28	6	13
	Mg (Magnesium)	0	1	0	0	0
	P (Phosphorus)	457	456	459	397	465
	Zn (Zinc)	3	3	5	1	2

Viscosity

Date	Visc@40C (cSt)
07 Feb 2024	750.0
03 Jun 2024	751.0
16 Jul 2024	758.9
13 Nov 2024	731.5
18 May 2025	745.5

Wear

Date	Ag	Al	Cr	Cu	Fe	Ni	Pb	Sn
07 Feb 2024	0	0	0	119	8	0	41	9
03 Jun 2024	0	0	0	145	9	1	40	8
16 Jul 2024	0	0	0	256	17	1	68	14
13 Nov 2024	0	0	0	23	3	0	9	2
18 May 2025	0	0	0	47	5	0	15	4

Contaminants

Date	Na	K	Si
07 Feb 2024	1	0	4
03 Jun 2024	0	0	5
16 Jul 2024	0	0	7
13 Nov 2024	0	0	5
18 May 2025	0	0	5

Physical Properties

Date	TAN (mg KOH/g)	Water (Hot Plate)
07 Feb 2024	0.41	0
03 Jun 2024	0.41	0
16 Jul 2024	0.41	0
13 Nov 2024	0.41	0
18 May 2025	0.41	0

Results and comments of this analysis are advisory only. The validity of the data may be impaired by a non-representative sample or incorrect data. © 2016-2024 ExxonMobil. ExxonMobil and Mobil are trademarks or registered trademarks of ExxonMobil Corporation or one of its subsidiaries. Other trademarks shown are property of their respective owners.

1 of 2

	Caution	
	Unit ID: 4-RK-2	Asset ID: 50074749
	Description: Kiln 1 Drive Trunion Bearing 5	
Account Information	Sample Information	Equipment Information
ID: 402009 Name: Greer Lime Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US Parent Account: MATTHEWS LUBRICANTS, INC.	Sample ID: 25147288001 Service Level: Essential Bottle ID: a003623164 Tested Lubricant: MOBIL SHC 636	Asset Class: Circulating System Manufacturer: Model: Lubricant: MOBIL SHC 636
Continued		
Recommendation/Comments		

ACTION REQUIRED - ELEVATED WEAR METALS LEVELS. Determine cause of elevated wear metals levels and take corrective action. If the wear metals levels are elevated for the first time with no history of an increasing trend, then resample immediately to confirm condition. Because silicon levels are not also elevated, abrasive dirt is not the cause of this condition. Possible causes of elevated wear metals include: a. Worn of oil-wetted parts; b. Contamination from previous fill; c. Over-extended oil service life; d. Normal break-in of new equipment. Continue to closely monitor the equipment and oil for signs of further condition regressions. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 18 May 2025 5:39 PM UTC - Brad Roy - In Service Oil Sample Comments: Photo: