

	Vapor Chamber	Heat Pipe
Theory	Two-phase heat transfer	Two-phase heat transfer
Application	Two-dimensional heat distribution. Spreading heat by a single vapor chamber. Suitable for large heat flux and high power	One-dimensional heat distribution. Using one or more heat pipes to spread heat. Suitable for long distance between heat source and heat exchanger.
Shape	Complex shape in x and y direction with pedestal, flattened rectangle, surface embossing and z-direction bendable	Round, flattened or bent in any direction
Sealing method	Swaged and welded on each end	Pinched and welded on each end, four sided diffusion bonding or welding
Fixtures	Mounted with through-holes in vapor chamber	Additional fixture plates needed to mount heat pipes
Mounting to heat source contact	Direct contact	Indirect contact through base plate unless flattened and machined