
HSE FLASH – Learning From Incident

DESERT STAR ENERGY

Reversing truck struck a parked light vehicle			
Ifadah#	45821	**Date**	18-Aug-2026
Time	07:45	**Risk Category**	Driving / Vehicle Safety
Injury/Asset Damaged	Asset damage – rear door of light vehicle	**Activity**	Material delivery to laydown yard
Actual Severity	Minor (Level 1)	**Potential Severity**	Major (Level 4)
Location	Laydown yard, Desert Star Energy Field Camp 3		





No banksman, no reversing.

What happened?

During a material delivery by Falcon Logistics LLC, a 10-tonne flatbed truck reversed into the laydown yard without a banksman. The driver, Rami Haddad, could not see a light vehicle parked behind the truck and struck its rear door at low speed. Nobody was inside the light vehicle and no one was injured.

Why it happened / Findings

- No banksman was assigned for the reversing manoeuvre.
- The truck's reversing camera was not working and had not been reported.
- The light vehicle was parked inside the truck manoeuvring area, which was not marked as a no-parking zone.
- The delivery was not covered in the morning toolbox talk (Permit WP-2209 listed offloading only).

Reflective questions to discuss with your Team

- When do we need a banksman on our site?
- Do we check reversing aids before every trip, and how do we report defects?
- Where are the no-parking zones in our laydown areas?

How can this learning be sustained at site?

- Assign a trained banksman for every reversing manoeuvre.
- Add reversing camera and alarm checks to the daily vehicle pre-use inspection.
- Mark and enforce no-parking zones in truck manoeuvring areas.
- Brief all delivery drivers at the gate on site traffic rules.