
LINKMISR
ADVANCED STORAGE SOLUTIONS

Quality Department

Visual Test Method , Instructions and Tolerances
According to ISO 17637 , ISO 5817 Level B And CSA W 59

Method	طريقة الفحص
VT shall be performed Before , During and after welding. **Before welding :** **1-The material specs shall be verfied based on applicable Drawings.** **2-The preparation and fit up shall be verified with repect to drawings and WPS.** **3-Welders qualifications & IDs.** **4-Welding consumables specs according to WPS.** **During welding :** **1-Welding parameters Current , Volt and travel speed according to WPS.** **After Welding :** **1-Check welding profile & Welding Dimensions.** **2-Repairs monitored in accordance with repairs instruction.**	، الفحص البصري للحام لابد وان يكون : قبل اللحام .مواصفات الخامات تكون مطابقة للرسومات .التجهيز والتجميع يكون طبقا للرسومات ومواصفة اللحام .مؤهلات اللحامين والكرنيهات .مواصفات سلك اللحام طبقا ل مواصفة اللحام : اثناء اللحام .فحص التيار والفولت والسرعة طبقا لمواصفة اللحام : بعد اللحام .فحص خط اللحام وابعاد اللحام .اصلاح اللحام يكون طبقا ل تعليمات اصلاح اللحام

Instructions	تعليمات
1-VT interpretation done by level 1 or level 2 , Evaluation done by level 2. **2-Test Extension 100 %.** **3-The minimum light intensity at the examination surfaces shall be 1000 Lux.** **4-Calibrated tools shall be used for measurement.** **5-Weld inspection shall include 10 mm left and right welding as aminimum.** **6-Direct inspection should enable the eye to be :** ***Within 600 mm of the surfaces being inspected.** ***In aposition to give aviewing angle of not less than 30.** 	توضيح عيوب اللحام تتم ب مستوى 1 او 2 ، تقييم العيوب ب 2. 100 : نسبة الاختبار %. Lux .1000 اقل شدة اضاءة مسموح بها علي السطح . .يتم معايرة ادوات القياس المستخدمة .فحص اللحام 10 مم يمين وشمال اللحام : الفحص المباشر لابد وان يمكن العين من ان تكون *علي يعد 600 مم من الاسطح التي يتم فحصها. *في وضع يسمح بزاوية رؤية لاتقل عن 30.

Welding imprefections Limits according to ISO 5817 Level B

Imprefection	Limit		Imprefection	Limit
Incorrect Gap	Less than 0.4 mm		Overlap , Cracks	Not permitted
Excessive throat	Less than 1.3 mm		Clustered spatter	Not permitted
Insufficient throat	Not permitted		Surface porosity	Not permitted
Max.Convexity	Less than 1.4 mm		Lack of fusion	Not permitted
Under cut	Less than 0.5 mm		Irregular , sharp edge	Not permitted