
Man
• Worn gasket
Method
Measurement
Seal leakage
Machine
Material
Mother Nature