Hylan Datacom & Electrical				Daily Work Report - Pole Work			
N	obilitie Exten	et Crown Cast		Date:		17-17	
Node #	CRAN_RN	45-00001-	21				
		Manpower Info	mation		Job# -	120 - 0051	
Name:	Al Vitalone	/					
Name:	Julian Tamburi	Reg:	OT:		318		
Name:	Julian Tallipun	Reg:	OT:	+	167 _		
Name:		Reg:	OT:		291 _		
realine.		Reg:	OT:		109 -		
		cription of Work	4		Qty	Total	
REMOVE AND DISPOSE EXISTING POLE (ALL POLE TYPES).							
FURNISH AND INSTALL TYPE 'M' POLE							
REMOVE AND RE-INSTALL TYPE M POLE							
REMOVE AND REINSTALL TYPE OCTOGONAL POLE							
	FS TYPE FOUNDATION						
	SPIDER FOUNDATION						
TEMP OUT TRAFFIC SVCS. UP TO 10LF - \$650.00 *OVER 10LF WILL BE \$97.50 EA. LF*							
TEMP PYLON							
	REINSTALL SIGNS ON POL	E EA. (Up to 3)					
	D DISPOSE DUSKY LIGHT	EA					
	ISTALL OCTOGONAL POLE						
REPLACE BASE (FS)							
REPLACE BASE (M2)							
FURNISH AND INSTALL 8' ARM AND LUMINAIRE							
F & I (2) RUNS PER NYC DOT 13C/314 TRAFFIC CABLE / PER FOOT							
F & I 2(2) #10 & (1) #8 GROUND TRAFFIC FEED CABLE / PER FOOT							
	PIPE STUBS IN POLE BASE	EA.					
SPLICE FEED	EA						
TAP & FUSE							
FURNISH AND INSTALL POWER CABLE (2) #14 IMSA / PER LF							
REMOVE & REPLACE FLOODLIGHT							
TRANSFER EXISTING ARM & LUMINAIRE REPLACE CONTROLLER							
FIX EXISTING						•	
	STALL FIRE ALARM PHOTO	EL COTRIO OCU					
	ARM, AND BASE EA	ELECTRIC CELL					
	2A MAST ARM EXTENSION A	PEEMBLY WITH FITTINGS		-			
	R DAY *\$25.00 PER HOUR	ASSEMBLY WITH FITTINGS		-+	-+		
	CLE INSTALL				-+		
POWER A	T LOCATION		- 1				
Job Location: Nassayst a Pine st							
Description of Work: COULD NOT take sold bear March							
Description of Work: Could Not take pole Down. Need to put No parking signs up and get there early morning.							