Hylan Datacom & Electrical — Daily Work Report - Pole Work

Mobilitie [ ]   Extenet [ ]   Crown Castle [✓]   Date: 8-27-17

Node # CRAN_RNYJ_0000B_5   Job# 120-017B

Manpower Information

Name:		Reg:	OT:		
Al Vitalone		Reg:	OT: 7	318	
Chris Dropp		Reg:	OT: 6	167	
		Reg:	OT:	291	
		Reg:	OT:	109	

Description of Work	Qty	Total
REMOVE AND DISPOSE EXISTING POLE (ALL POLE TYPES).		
FURNISH AND INSTALL TYPE 'M' POLE		
REMOVE AND RE-INSTALL TYPE M POLE		
REMOVE AND REINSTALL TYPE OCTOGONAL POLE		
CONSTRUCT FS TYPE FOUNDATION		
CONSTRUCT SPIDER FOUNDATION		
TEMP OUT TRAFFIC SVCS. UP TO 10LF - $650.00 *OVER 10LF WILL BE $97.50 EA. LF*		
TEMP PYLON		
REMOVE AND REINSTALL SIGNS ON POLE EA. (Up to 3)		
REMOVE AND DISPOSE DUSKY LIGHT EA		
FURNISH & INSTALL OCTOGONAL POLE		
REPLACE BASE (FS)		
REPLACE BASE (M2)		
FURNISH AND INSTALL 8' ARM AND LUMINAIRE		
F & I (2) RUNS PER NYC DOT 13C/314 TRAFFIC CABLE / PER FOOT		
F & I 2(2) #10 & (1) #8 GROUND TRAFFIC FEED CABLE / PER FOOT		
GROUND 2" PIPE STUBS IN POLE BASE EA.		
SPLICE FEED EA.		
TAP & FUSE		
FURNISH AND INSTALL POWER CABLE (2) #14 IMSA / PER LF	135 Ft	
REMOVE & REPLACE FLOODLIGHT		
TRANSFER EXISTING ARM & LUMINAIRE		
REPLACE CONTROLLER		
FIX EXISTING DOOR		
FURNISH & INSTALL FIRE ALARM PHOTO ELECTRIC CELL		
PAINT POLE, ARM, AND BASE EA		
INSTALL 5' M-2A MAST ARM EXTENSION ASSEMBLY WITH FITTINGS		
FLAGMEN PER DAY *$25.00 PER HOUR		
GFI RECEPTACLE INSTALL		
POWER AT LOCATION NO		

Job Location: 3 & st   Tunnel exit SEC

Description of Work: ~~Test~~ Tried to Rod from the NEC to NWC and no Luck. Had the guys Do A test pit at the NEC to NWC and the Greenfield was damaged. repaired greenfield and pull in 65' of IMSA and tag. from the NEC to the SEC. repaired greenfirls and made other test pit 15' from SEC and repaired conduit pulled IN IMSA Cable about 90' and tage. Look in Back for map.

(diagram: NWC ←65ft→ NEC, with arrows from SWC to NWC, and 70 / SEC)