Hylan Datacom & Electrical	Daily Work	Report	- Pole Work
Mobilitie Extenet Crown Castle		nte: 8 - 2	
Node # 14377		Job#	44 - 20
Manpower Inform	ation	JOD#	710
		240	
	OT:	109 _	
Description of Work		Qty	Total
REMOVE AND DISPOSE EXISTING POLE (ALL POLE TYPES).			
FURNISH AND INSTALL TYPE 'M' POLE			
REMOVE AND RE-INSTALL TYPE M POLE			
REMOVE AND REINSTALL TYPE OCTOGONAL POLE			
CONSTRUCT FS TYPE FOUNDATION			
CONSTRUCT SPIDER FOUNDATION			
TEMP OUT TRAFFIC SVCS. UP TO 10LF - \$650.00 *OVER 10LF WILL BE \$9	7.50 EA. LF*		
TEMP PYLON			
REMOVE AND REINSTALL SIGNS ON POLE EA. (Up to 3)			
REMOVE AND DISPOSE DUSKY LIGHT EA			
FURNISH & INSTALL OCTOGONAL POLE			
REPLACE BASE (FS)			
REPLACE BASE (M2)			
FURNISH AND INSTALL 8' ARM AND LUMINAIRE			
F & I (2) RUNS PER NYC DOT 13C/314 TRAFFIC CABLE / PER FOOT			
F & I 2(2) #10 & (1) #8 GROUND TRAFFIC FEED CABLE / PER FOOT			
GROUND 2" PIPE STUBS IN POLE BASE EA.			
SPLICE FEED EA.			
TAP & FUSE			
FURNISH AND INSTALL POWER CABLE (2) #14 IMSA / PER LF			
REMOVE & REPLACE FLOODLIGHT			
TRANSFER EXISTING ARM & LUMINAIRE			
REPLACE CONTROLLER	·		
FIX EXISTING DOOR			
FURNISH & INSTALL FIRE ALARM PHOTO ELECTRIC CELL			
PAINT POLE, ARM, AND BASE EA			
INSTALL 5' M-2A MAST ARM EXTENSION ASSEMBLY WITH FITTINGS			
FLAGMEN PER DAY *\$25.00 PER HOUR			
POWER AT LOCATION			
Job Location: De Kalb AVE and	Kent AVE	NEC	to SEL
Description of Work: Rod Dot conduit from the NEC to SEC and wo			
Luck. We Blow air into conduit and Rod conduit over andover			
we got gir through the conduit and we kept on trying to			
Pushingrod through the conduit to we got the rod to the			
SEC. Pulled in rop need to go Back to splice.			
I .			