Hylan Datacom & Electrical					Daily Work Report - Pole Work			
N	lobilitie 🔽	Extenet	Crown Castle		Date:		25-17-	
Node #	1220) \				Job#	497	
			Manpower Inform	ation		JUDII		
Name:	Al Vitalone		Reg: 7	OT:	4	318		
Name:			Reg:		/	. 167		
Name:			Reg:			291		
Name:			Reg:	- OT:		. 291		
		Donosintina						
DEMOVE AN	D DISBOSE EVICE	Description				Qty	Total	
REMOVE AND DISPOSE EXISTING POLE (ALL POLE TYPES). FURNISH AND INSTALL TYPE 'M' POLE								
REMOVE AND RE-INSTALL TYPE M POLE								
REMOVE AND REINSTALL TYPE OCTOGONAL POLE								
	FS TYPE FOUND							
	SPIDER FOUND							
			OVER 10LF WILL BE \$97					
TEMP PYLOI		10 TOLF - \$650.00 "	OVER TOLF WILL BE \$9	7.50 EA. LF*				
	D REINSTALL SIG	NS ON BOLE	EA (11= 4= 0)					
	D DISPOSE DUSK		EA. (Up to 3)					
	NSTALL OCTOGO		1					
REPLACE BA		NAL FOLE						
FURNISH AND INSTALL 8' ARM AND LUMINAIRE								
		13C/314 TRAFFIC CAL	PLE / BED FOOT					
		TRAFFIC FEED CAB						
	PIPE STUBS IN PO							
SPLICE FEEL		ALL BAGE EA.				2		
TAP & FUSE								
	D INSTALL POWE	R CABLE (2) #14 IMS	A / DED I E			ROTT		
	EPLACE FLOODL		A/1 LA LI			<u>KUTT</u>		
	XISTING ARM & L						<u> </u>	
REPLACE CO		OWNANTE						
FIX EXISTING								
		RM PHOTO ELECTRIC	C CELL					
	ARM, AND BASE	EA	0222					
		CTENSION ASSEMBLY	/ WITH FITTINGS					
	R DAY *\$25.00 PE							
GFI RECEPT	ACLE INSTALL							
POWER A	AT LOCATION	1		NEC		V		
Job Locati	on:	Rodge	ers AVE a	ind L	incol	N 19	NEL to SEC	
Description of Work: Made a test pit At the NEC The Green field is								
damaged repaired Greenfield with New Greenfield Pull in								
80' OF TMSA cable. Splice in old treffic Cable, Splice in								
her twee A A-Pla to Acusto the								
.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	CQI)	10 (01	LED: Took	DOWI	n ten	100		
	<u> </u>							