Hylan Datacom & Electrical Daily Work Report - Pole Work			
Mobilitie Extenet Crown Castle	D	ate: 861	1
Node # \3718		Job#	112=0061
Manpower Inform	ation		
Name: Howard Olshewitz Reg:	OT:	318	<b>∮</b> (†)
Name: Chris Dropp Reg:		167	i i
Name: Reg:		291	-15 J. C. D.
Name: Reg:	-	109	
Description of Work	-	Qty	Total
REMOVE AND DISPOSE EXISTING POLE (ALL POLE TYPES).		Qty	Total
FURNISH AND INSTALL TYPE 'M' POLE			
REMOVE AND RE-INSTALL TYPE M POLE			· · · · · · · · · · · · · · · · · · ·
REMOVE AND REINSTALL TYPE OCTOGONAL POLE			
CONSTRUCT FS TYPE FOUNDATION			
CONSTRUCT SPIDER FOUNDATION	-		
TEMP OUT TRAFFIC SVCS. UP TO 10LF - \$650.00 *OVER 10LF WILL BE \$9	7.50 EA. LF*		
TEMP PYLON			
REMOVE AND REINSTALL SIGNS ON POLE EA. (Up to 3)			,
REMOVE AND DISPOSE DUSKY LIGHT EA			
FURNISH & INSTALL OCTOGONAL POLE			
REPLACE BASE (FS)			
REPLACE BASE (M2)			
FURNISH AND INSTALL 8' ARM AND LUMINAIRE			
F & I (2) RUNS PER NYC DOT 13C/314 TRAFFIC CABLE / PER FOOT			
F & I 2(2) #10 & (1) #8 GROUND TRAFFIC FEED CABLE / PER FOOT			
GROUND 2" PIPE STUBS IN POLE BASE EA.			
SPLICE FEED EA.			
TAP & FUSE			
FURNISH AND INSTALL POWER CABLE (2) #14 IMSA / PER LF			
REMOVE & REPLACE FLOODLIGHT	_		
TRANSFER EXISTING ARM & LUMINAIRE			
REPLACE CONTROLLER	-		E)
FIX EXISTING DOOR			
FURNISH & INSTALL FIRE ALARM PHOTO ELECTRIC CELL			
PAINT POLE, ARM, AND BASE EA			
INSTALL 5' M-2A MAST ARM EXTENSION ASSEMBLY WITH FITTINGS			
FLAGMEN PER DAY *\$25.00 PER HOUR	· · · · ·		
GFI RECEPTACLE INSTALL			
POWER AT LOCATION			
Job Location:			
Description of Work:			
Boom not working properly. We wint in			
Location but couldn't do Tim			