

The NX Automated Work Instruction tool is a bespoke developed tool that allows the user to create a standardised work instructions document by entering several key information about the CAM program created. The tool will produce the documentation required to provide the machine shop with the required information to successfully set up and run the job.

At a glance, the tool has the below user interface:

The screenshot displays the user interface of the NX Automated Work Instruction tool. It features a form with several input fields and a checkbox, with callout boxes providing additional context for specific elements.

|              |                      |                                                                                   |
|--------------|----------------------|-----------------------------------------------------------------------------------|
| Prog. Folder | <input type="text"/> |  |
| Project      | <input type="text"/> |                                                                                   |
| Revision     | <input type="text"/> | ▼                                                                                 |
| Costumer     | <input type="text"/> | ▼                                                                                 |
| Machine      | <input type="text"/> | ▼                                                                                 |
| Instructions | <input type="text"/> | ▼                                                                                 |
| Datum        | <input type="text"/> | ▼                                                                                 |
| Work Holding | <input type="text"/> | ▼                                                                                 |
| AS/OPP Req?  | <input type="text"/> | ▼                                                                                 |
| Notes        | <input type="text"/> | ▼                                                                                 |


☐ Create Tool Path Display Sheets

Please ensure that the Prog. Folder parameter entered matches the program folder name on NX.  
Click CREATE to begin work instruction builder.  
Click CANCEL to exit the program.

**Callout Boxes:**

- Top Right:** This button allows the user to reload data that was used previously. (Points to the reload icon next to the Prog. Folder field)
- Middle Right:** Information required by the user. (Points to the Instructions field)
- Bottom Right (Top):** Option to create tool path display sheets for each tool path (does increase the generation time) (Points to the checkbox)
- Bottom Right (Bottom):** Buttons to start generation or cancel and close the program. (Points to the Cancel and Create buttons)

# Working Principle



EXAMPLES

## 3 - Job Information Sheet

### Job Information Sheet

Part Number

Costumer

Machine

Programmer

Revision

Project

Date

muhsin.caglar

Program Folder

**Instructions:**

**Datum:**


X0 Y0 CENTRE OF BLOCK  
Z0 BOTTOM OF BLOCK

**Work Holding:**

CLAMPS

**AS & OPP Required:**

**NOTES:**



| Tool List |  |
|-----------|--|
|-----------|--|

|             |  |      |                          |
|-------------|--|------|--------------------------|
| Part Number |  | Date | Wed Jan 22 11:16:40 2025 |
|-------------|--|------|--------------------------|

| Tool Number | Tool Name | Stick Out | Tool Diam | Tool Rad | Flute Length | Tool Code | Holder |
|-------------|-----------|-----------|-----------|----------|--------------|-----------|--------|
|-------------|-----------|-----------|-----------|----------|--------------|-----------|--------|



3043- Job Views


Job Views

|             |  |  |      |                          |
|-------------|--|--|------|--------------------------|
| Part Number |  |  | Date | Wed Jan 22 11:16:41 2025 |
|-------------|--|--|------|--------------------------|


VIEW 1



VIEW 2



VIEW 3



FIXTURE





3043 - Tool Path Summary - 3043\_101

Tool Path Summary

|             |  |  |      |                          |
|-------------|--|--|------|--------------------------|
| Part Number |  |  | Date | Wed Jan 22 11:16:44 2025 |
|-------------|--|--|------|--------------------------|

| Operation Name | Program | Tool | NX Tool Name | Tool Code | Speed | Feed | Time (Mins) |
|----------------|---------|------|--------------|-----------|-------|------|-------------|
|----------------|---------|------|--------------|-----------|-------|------|-------------|

|  |  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|--|
|  |  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|--|



**3043 - Tool Path Summary - 3043\_201**

|                          |
|--------------------------|
| <b>Tool Path Summary</b> |
|--------------------------|

|             |                 |      |                          |
|-------------|-----------------|------|--------------------------|
| Part Number | 1006172_007_MFG | Date | Wed Jan 22 11:16:45 2025 |
|-------------|-----------------|------|--------------------------|

| Operation Name | Program | Tool | NX Tool Name | Tool Code | Speed | Feed | Time (Mins) |
|----------------|---------|------|--------------|-----------|-------|------|-------------|
|----------------|---------|------|--------------|-----------|-------|------|-------------|

|  |  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|--|
|  |  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|--|