



Kernel Version	GPU (Mali)	VPU (MPP / H.264/265)	NPU (RKNN)	HDMI / PCIe	USB 3 / Type- C	Camera	Notes
5.10 (Legacy)	✓ Stable	✓ Fully supported	✓ RKNN 1.x	V	V	V	Best supported by Rockchip BSP
6.1 (BSP)	✓ Mali	✓ VPU (MPP, GStreamer OK)	✓ RKNN 2.x	V	V	V	Officially supported by Rockchip from 2023
6.11 (Mainline)	▲ Early / experimental	X No VPU by default	<u></u> ₩IP	V	V	A	Cutting-edge, but missing key media drivers (no mpph264enc)

* PERFORMANCE

Kernel	Performance	Notes C
5.10		Optimized for RK3588, lowest latency, best power handling
6.1		Better I/O throughput, still with full driver support
6.11	🚧 Experimental	Might feel smoother with desktop GUI but lacks codec support

Based on research we will be using these 2 images as base image linux version 6.1

It is found 5.1 is legacy and have older user space abd 6.11 is lacking drivers and not stable .
For overlay App 6.1 is finalized to use .

https://drive.google.com/file/d/1hz_0ap6kDR5hGNAYQQ-xgS-8UcdBeYvf/view?usp=sharing https://drive.google.com/file/d/175jhoSSkkiVIHZgq51LwpqvHPtwUBT2q/view?usp=sharing