

## Converting Transfer Functions to State Space



# Contents

- Phase variables
- Converting transfer function with no zeros
- Converting transfer function with zeros
  - Lower order than denominator

## Phase Variables

The  $n^{\text{th}}$ -order transfer function has a single input and output.

- Choose state variables,  $x_i$ , to be the output and its  $(n - 1)$  derivatives — known as *phase variables*
- Example: phase variables for a system with output,  $y$

$$x_1 = y$$

$$x_2 = \frac{dy}{dt}$$

$$x_3 = \frac{d^2y}{dt^2}$$

$$\vdots$$

$$x_n = \frac{d^{n-1}y}{dt^{n-1}}$$

## Phase Variables in State Equation

If the relationship between the output,  $y$ , and input,  $u$ , is described by the following differential equation

$$\frac{d^n y}{dt^n} + a_{n-1} \frac{d^{n-1} y}{dt^{n-1}} + \dots + a_1 \frac{dy}{dt} + a_0 y = b_0 u$$

then taking the first derivative of the phase variables yields

$$\dot{x}_1 = x_2$$

$$\dot{x}_2 = x_3$$

⋮

$$\dot{x}_n = -a_0 x_1 - a_1 x_2 - \dots - a_{n-1} x_n + b_0 u$$

# State-Space Representation in Phase Variable Form

Putting this in matrix form yields

$$\begin{bmatrix} \dot{x}_1 \\ \dot{x}_2 \\ \dot{x}_3 \\ \vdots \\ \dot{x}_{n-1} \\ \dot{x}_n \end{bmatrix} = \begin{bmatrix} 0 & 1 & 0 & 0 & 0 & 0 & \dots & 0 \\ 0 & 0 & 1 & 0 & 0 & 0 & \dots & 0 \\ 0 & 0 & 0 & 1 & 0 & 0 & \dots & 0 \\ \vdots & \vdots & & & & & & \\ 0 & 0 & 0 & 0 & 0 & 0 & \dots & 1 \\ -a_0 & -a_1 & -a_2 & -a_3 & -a_4 & -a_5 & \dots & -a_{n-1} \end{bmatrix} \begin{bmatrix} x_1 \\ x_2 \\ x_3 \\ \vdots \\ x_{n-1} \\ x_n \end{bmatrix} + \begin{bmatrix} 0 \\ 0 \\ 0 \\ \vdots \\ 0 \\ b_0 \end{bmatrix} u$$

which is the phase-variable form of the state equation.

Based on our definition of the state variables, the output equation is

$$y = [1 \ 0 \ 0 \ \dots \ 0] \begin{bmatrix} x_1 \\ x_2 \\ x_3 \\ \vdots \\ x_{n-1} \\ x_n \end{bmatrix}$$

## Example 1

Start with transfer function

$$G(s) = \frac{C(s)}{R(s)} = \frac{43}{s^2 + 9s + 24}$$

Cross multiply to get

$$(s^2 + 9s + 24)C(s) = 43R(s)$$

Take inverse Laplace transform (assuming zero initial conditions)

$$\ddot{c} + 9\dot{c} + 24c = 43r$$

Use phase variables as state variables

$$x_1 = c$$

$$x_2 = \dot{c}$$

Write state equations (first-order derivatives of state variables)

$$\dot{x}_1 = x_2$$

$$\dot{x}_2 = -24x_1 - 9x_2 + 43r$$

## Example 1 (Continued)

In summary, the transfer function

$$G(s) = \frac{C(s)}{R(s)} = \frac{43}{s^2 + 9s + 24}$$

has state-space representation in phase-variable form of


$$\begin{aligned}\dot{\bar{x}} &= \begin{bmatrix} 0 & 1 \\ -24 & -9 \end{bmatrix} \bar{x} + \begin{bmatrix} 0 \\ 43 \end{bmatrix} r \\ y &= [1 \ 0] \bar{x}\end{aligned}$$

where the state variables are


$$\bar{x} = \begin{bmatrix} x_1 \\ x_2 \end{bmatrix} = \begin{bmatrix} c \\ \dot{c} \end{bmatrix}$$

# Transfer Functions With Non-Zeroth-Order Numerator

Consider the transfer function shown in (a) as two blocks cascaded as shown in (b)



(a)



Internal variables:

$$X_2(s), X_3(s)$$

(b)

Choose  $x_1$  and its derivatives (phase variables) as state variables

$$\bar{x} = [x_1 \quad \dot{x}_1 \quad \ddot{x}_1]^T = [x_1 \quad x_2 \quad x_3]^T$$

The second block gives the output ( $c$ ) in terms of phase variables

$$y = b_0x_1 + b_1\dot{x}_1 + b_2\ddot{x}_1 = b_0x_1 + b_1x_2 + b_2x_3 = [b_0 \quad b_1 \quad b_2] \bar{x}$$

## Example 2

Start with transfer function

$$G(s) = \frac{C(s)}{R(s)} = \frac{43s + 2}{s^2 + 9s + 24}$$

Treat this as two cascaded transfer functions,  $G_1(s)$  and  $G_2(s)$

$$G_1(s) = \frac{1}{s^2 + 9s + 24}, \quad G_2(s) = 43s + 2$$

Cross multiply  $\frac{X_1(s)}{R(s)} = \frac{1}{s^2+9s+24}$  and take inverse Laplace:

$$\ddot{x}_1 + 9\dot{x}_1 + 24x_1 = r$$

Write state equation using phase variables of  $X_1(s)$

$$\dot{\bar{x}} = A\bar{x} + Bu = \begin{bmatrix} \dot{x}_1 \\ \dot{x}_2 \end{bmatrix} = \begin{bmatrix} 0 & 1 \\ -24 & -9 \end{bmatrix} \begin{bmatrix} x_1 \\ x_2 \end{bmatrix} + \begin{bmatrix} 0 \\ 1 \end{bmatrix} r$$

Use  $Y(s) = C(s) = X_1(s)G_2(s)$  to form output equation

$$y = 2x_1 + 43\dot{x}_1 = C\bar{x} = 2x_1 + 43x_2 = \boxed{\begin{bmatrix} 2 & 43 \end{bmatrix} \bar{x}}$$


## Example 3 — Alternative Representations

The so-called *phase-variable form* is far from the only state-space representation possible.

- Cascade form, parallel form, controller canonical form, observer canonical form, ...

For example, represent  $G(s) = \frac{24}{(s+2)(s+3)(s+4)}$  in cascade form

Imagine  $G(s)$  as the cascade form of four transfer functions



Taking the output of each block from denominator as a state variable yields

$$\begin{aligned}\dot{x}_1 &= -4x_1 & +x_2 \\ \dot{x}_2 &= & -3x_2 + x_3 \\ \dot{x}_3 &= & -2x_3 + 24r \\ y &= c(t) = x_1\end{aligned}$$

$$\begin{aligned}\dot{\bar{x}} &= \begin{bmatrix} -4 & 1 & 0 \\ 0 & -3 & 1 \\ 0 & 0 & -2 \end{bmatrix} \bar{x} + \begin{bmatrix} 0 \\ 0 \\ 24 \end{bmatrix} r \\ y &= [1 \ 0 \ 0] \bar{x}\end{aligned}$$