Scania Diagnos & Programmer 3




YS2R6X400E9183544 / COO, Coordinator / E 30, COO control unit / COO7 / D, Diodes, resistors and potentiometers / D60, Clutch pedal sensor

D 60, Clutch pedal sensor

The clutch pedal sensor is a Hall effect sensor.

Pin	Task	Signal type
1	Grounding of the clutch pedal sensor	Ground
2	Not used	
3	Not used	
4	Signal from the clutch pedal sensor	Analogue
5	Voltage supply	+5 V
6	Not used	



D 60, Clutch pedal sensor

D 60, Clutch pedal sensor



