


YS2R6X400E9183544 / GMS, Gearbox management system / E 5, GMS control unit / OPC / T, Sensors and monitors / T108, Position sensor for lateral stroke

## C 101, Connector





From front, round sockets. Cable side, round sockets. From front, round pins. Cable side, round pins.











C 101, Connector

## E 5, GMS control unit


En för OPC och en för TMS

## T 108, Position sensor for lateral stroke


Analogue inductive position sensor.



Pin:	Task:	Signal type:	Source/Destination:
1	Position information for lateral stroke	Output signal voltage, 50% PWM signal	Control unit (E5) Pin C2
2	Voltage supply	Input signal voltage, 12V	Control unit (E5) Pin C6



T 108, Position sensor for lateral stroke



T 108, Position sensor for lateral stroke