


YS2R6X400E9183544 / GMS, Gearbox management system / E 5, GMS control unit / OPC / T, Sensors and monitors / T106, Position sensor for splitter gear

C 101, Connector





From front, round sockets. Cable side, round sockets. From front, round pins. Cable side, round pins.













C 101, Connector

C 108, Connector









C 108, Connector


E 5, GMS control unit

En för OPC och en för TMS

T 106, Position sensor for splitter gear

Analogue inductive position sensor.

Pin:	Task:	Signal type:	Source/Destination:
1	Voltage supply	Input signal voltage, 12V	Control unit (E5) Pin C5
2	Position information for split- ter gear	Output signal voltage, 50% PWM signal	Control unit (E5) Pin C1



T 106, Position sensor for splitter gear

T 106, Position sensor for splitter gear



