

Summary report

Wellbore: 15/9-19 BT2

Period: 1998-01-30 00:00 - 1998-01-31 00:00

Status:	normal
Report creation time:	2018-05-03 13:53
Report number:	57
Days Ahead/Behind (+/-):	
Operator:	Statoil
Rig Name:	BYFORD DOLPHIN
Drilling contractor:	
Spud Date:	1997-12-05 00:00
Wellbore type:	
Elevation RKB-MSL (m):	25
Water depth MSL (m):	85
Tight well:	Y
HPHT:	Y
Temperature ():	
Pressure ():	
Date Well Complete:	

Dist Drilled (m):	-999.99
Penetration rate (m/h):	-999.99
Hole Dia ():	
Pressure Test Type:	
Formation strength ():	
Dia Last Casing ():	

Depth at Kick Off mMD:	2911
Depth at Kick Off mTVD:	
Depth mMD:	-999.99
Depth mTVD:	
Plug Back Depth mMD:	
Depth at formation strength mMD:	
Depth At Formation Strength mTVD:	
Depth At Last Casing mMD:	4643
Depth At Last Casing mTVD:	

Summary of activities (24 Hours)

COMPLETED TRIP TO RETRIEVE LMRP. CHANGED OUT WORN FLEX JT AND PREPARED TO RUN LMNR.

Summary of planned activities (24 Hours)

COMPLETE R/ UP ON LMNR AND RUN IN AND RETRIEVE BOP TO SURFACE.

Operations

Start time	End time	End Depth mMD	Main - Sub Activity	State	Remark
00:00	00:30	0	interruption -- repair	fail	CONTINUED RIGGING DOWN FROM SLIP JT. STORED RISER SUPPORT RING.
00:30	03:00	0	interruption -- repair	fail	MOVED RIG 30M OFF LOCATION IN 020 DEGR DIRECTION.
03:00	06:00	0	interruption -- repair	fail	PULLED LMNR TO SPLASH SONE.
06:00	06:30	0	interruption -- repair	fail	CONTINUED PULLING LMNR TO MOONPOOL.
06:30	10:30	0	interruption -- repair	fail	SECURED LMNR AND DISMANTLED POD FEMALE RECEPCIALS IN ORDER TO LAND LMNR ONTO SKID BEAMS. SET DOWN LMNR OK.
10:30	12:00	0	interruption -- repair	fail	REMOVED BULLSEYE AND POSITION BEACON AND DISCONNECTED RISER JOINT. INSPECTED FLEX JOINT AND FOUND 3 KEY SEATS.
12:00	00:00	0	interruption -- repair	fail	MOVED LMNR TO FWD SIDE IN MOONPOOL. DISCONECTED KILL AND CHOKE LINE COFLEX HOSES AND FLEX JOINT.