

Summary report

Wellbore: 15/9-19 ST2

Period: 1993-04-11 00:00 - 1993-04-12 00:00

Status:	normal
Report creation time:	2018-05-03 13:53
Report number:	147
Days Ahead/Behind (+/-):	
Operator:	Statoil
Rig Name:	TREASURE PROSPECT
Drilling contractor:	UNKNOWN
Spud Date:	1992-09-15 01:00
Wellbore type:	
Elevation RKB-MSL (m):	22
Water depth MSL (m):	84
Tight well:	Y
HPHT:	Y
Temperature ():	
Pressure ():	
Date Well Complete:	1993-01-28

Dist Drilled (m):	-999.99
Penetration rate (m/h):	-999.99
Hole Dia ():	
Pressure Test Type:	
Formation strength ():	
Dia Last Casing ():	

Depth at Kick Off mMD:	
Depth at Kick Off mTVD:	
Depth mMD:	-999.99
Depth mTVD:	
Plug Back Depth mMD:	
Depth at formation strength mMD:	
Depth At Formation Strength mTVD:	
Depth At Last Casing mMD:	4640
Depth At Last Casing mTVD:	

Summary of activities (24 Hours)

- *PLACED BOP ON CARRIER
- *CHANGED OUT 2 DAMAGED SEALS ON SHEAR RAM.
- *SHEAR RAM STILL LEAKING. STARTED CHANGING OUT 3.RD SEAL.

Summary of planned activities (24 Hours)

- *CONT. REPAIRING BOP. PRESSURE TEST AND FUNCTION TEST.
- *RUN BOP.
- *CHANGE OUT SEAL ASSEMBLY TO METAL-TO-METAL SEAL.

Operations

Start time	End time	End Depth mMD	Main - Sub Activity	State	Remark
00:00	02:30	33	interruption -- waiting on w eather	ok	CONT. W.O.W.
02:30	03:00	29	interruption -- repair	ok	PULLED BOP TO 29M, L/D RISER PUP JOINT.
03:00	05:00	29	interruption -- waiting on w eather	ok	CONT. W.O.W.
05:00	05:30	29	interruption -- waiting on w eather	ok	CONT. W.O.W.
05:30	06:00	0	interruption -- repair	ok	PULLED BOP THROUGH SPLASH ZONE. PREPARED TO LAND BOP ON CARRIER.
06:00	07:30	0	interruption -- repair	ok	LANDED AND SECURED BOP ON CARRIER.
07:30	19:30	0	interruption -- repair	ok	OPENED SHEAR RAM DOORS ON BOP AND INSPECTED SEALS. FOUND DAMAGES ON T-SEAL AND ON 1 RAM-TOP SEAL, CHANGED OUT SAME AND CLOSED DOORS.
19:30	21:30	0	interruption -- repair	fail	PRESSURE TESTED MPR, INNER KILL VALVE AND UPR TO 20/345 BAR, 5/10 MINS ATTEMPTED PRESSURE TESTING SHEAR RAM, NEGATIVE. MAJOR LEAK ACROSS THE RAMS.
21:30	00:00	0	interruption -- repair	ok	DRAINED BOP. INVESTIGATED LEAK.

Drilling Fluid

Sample Time	23:00
Sample Point	
Sample Depth mMD	-999.99
Fluid Type	BRINE
Fluid Density (g/cm3)	1.15
Funnel Visc (s)	-999.99
Mf ()	
Pm ()	
Pm filtrate ()	
Chloride ()	
Calcium ()	
Magnesium ()	
Ph	
Excess Lime ()	
Solids	
Sand ()	
Water ()	
Oil ()	
Solids ()	
Corrected solids ()	
High gravity solids ()	
Low gravity solids ()	
Viscometer tests	
Plastic visc. (mPa.s)	-999.99
Yield point (Pa)	-999.99
Filtration tests	
Pm filtrate ()	
Filtrate Lthp ()	
Filtrate Hthp ()	

Cake thickn API ()	
Cake thickn HPHT ()	
Test Temp HPHT ()	
Comment	