

Summary report

Wellbore: 15/9-F-14

Period: 2010-09-16 00:00 - 2010-09-17 00:00

Status:	normal
Report creation time:	2018-05-03 13:52
Report number:	7
Days Ahead/Behind (+/-):	3.2
Operator:	Statoil
Rig Name:	MÆRSK INSPIRER
Drilling contractor:	Aker Well Service
Spud Date:	2007-11-04 00:00
Wellbore type:	
Elevation RKB-MSL (m):	54.9
Water depth MSL (m):	91
Tight well:	Y
HPHT:	Y
Temperature ():	
Pressure ():	
Date Well Complete:	2008-06-15

Dist Drilled (m):	-999.99
Penetration rate (m/h):	-999.99
Hole Dia ():	
Pressure Test Type:	formation integrity test
Formation strength (g/cm3):	1.56
Dia Last Casing ():	

Depth at Kick Off mMD:	
Depth at Kick Off mTVD:	
Depth mMD:	-999.99
Depth mTVD:	
Plug Back Depth mMD:	
Depth at formation strength mMD:	2788
Depth At Formation Strength mTVD:	2728.4
Depth At Last Casing mMD:	3695
Depth At Last Casing mTVD:	3123.4

Summary of activities (24 Hours)

Logged RST from 3150 to 3101 m. RST far detector stopped working. Ran PLT logging pass from 3390 m up to 2970 m at speed 10, 20, 30 and 40 m/min. Took stationary readings at 3200, 3040 and 2970 m. Evaluated data. POOH. LD BHA. Waited on plug equipment from shore. Meanwhile produced well and prepared 5/16" cable equipment.

Summary of planned activities (24 Hours)

Produce well.

Expected status 06:00 tomorrow: RIH with EVO plug.

Operations

Start time	End time	End Depth mMD	Main - Sub Activity	State	Remark
00:00	02:15	3098	workover -- wire line	ok	Logged RST in IC mode at 0.5 m/min from 3150 to 3101 m. RST far detector stopped working.
02:15	02:45	3116	workover -- wire line	ok	Tractored back into well 15 m and stopped at 3116 m. Troubleshoot and made several attempts to get the detector to work. Neg.
02:45	03:00	3390	workover -- wire line	ok	RIH with tractor activated to 3390 m.
03:00	03:45	2970	workover -- wire line	ok	Ran PLT logging pass from 3390 m up to 2970 m at speed 10 m/min.
03:45	04:45	3390	workover -- wire line	ok	RIH with tractor activated to 3390 m.
04:45	05:15	2970	workover -- wire line	ok	Ran PLT logging pass from 3390 m up to 2970 m at speed 20 m/min.
05:15	05:45	3390	workover -- wire line	ok	RIH with tractor activated to 3390 m.
05:45	06:00	2970	workover -- wire line	ok	Ran PLT logging pass from 3390 m up to 2970 m at speed 30 m/min.
06:00	06:30	3390	workover -- wire line	ok	RIH with tractor activated to 3390 m.
06:30	06:45	2970	workover -- wire line	ok	Ran PLT logging pass from 3390 m up to 2970 m at speed 40 m/min.
06:45	07:00	3200	workover -- wire line	ok	RIH with tractor activated to 3200 m.
07:00	08:15	2970	workover -- wire line	ok	Took stationary readings at 3200, 3040 and 2970 m. Evaluated data.
08:15	10:15	0	workover -- wire line	ok	POOH with BHA#1. Lost communication with PLT/RST on the way OOH.
10:15	13:15	0	workover -- rig up/down	ok	OOH. SIWHP 103 bar. Closed well and bled off pressure. Flushed riser/lubricator with N2. Inflow tested HMV. LD BHA#1.
13:15	00:00	0	interruption -- waiting on weather	ok	Waited on plug equipment from shore. Boat departure cancelled due to poor weather forecast. Meanwhile produced well and prepared 5/16" cable equipment due to loose strand on 7/16" cable.