

Summary report

Wellbore: 15/9-F-11 T2

Period: 2013-04-02 00:00 - 2013-04-03 00:00

Status:	normal
Report creation time:	2018-05-03 13:51
Report number:	28
Days Ahead/Behind (+/-):	
Operator:	Statoil
Rig Name:	MÆRSK INSPIRER
Drilling contractor:	Maersk Drilling
Spud Date:	2013-03-07 17:30
Wellbore type:	
Elevation RKB-MSL (m):	54.9
Water depth MSL (m):	91
Tight well:	Y
HPHT:	Y
Temperature ():	
Pressure ():	
Date Well Complete:	2013-05-09

Dist Drilled (m):	0
Penetration rate (m/h):	-999.99
Hole Dia (in):	26
Pressure Test Type:	
Formation strength (g/cm3):	0
Dia Last Casing ():	

Depth at Kick Off mMD:	
Depth at Kick Off mTVD:	
Depth mMD:	1365
Depth mTVD:	1345.5
Plug Back Depth mMD:	
Depth at formation strength mMD:	0
Depth At Formation Strength mTVD:	0
Depth At Last Casing mMD:	202.3
Depth At Last Casing mTVD:	202

Summary of activities (24 Hours)

Racked back and laid down 26" bottom hole assembly.
 Rigged up to run 20" casing.
 Picked up and made up shoe joint, float collar joint and one intermediate joint with thread lock.
 Troubleshooting and repairing of pipe deck machine (PDM)

Summary of planned activities (24 Hours)

Run 20" casing.

Operations

Start time	End time	End Depth mMD	Main - Sub Activity	State	Remark
00:00	03:00	0	drilling -- trip	ok	Broke out and racked back 5 1/2" heavy weight drill pipe and 9 1/2" drill collars in derrick from 144m MD to 60m MD.
03:00	03:30	0	drilling -- trip	ok	Downloaded MWD.
03:30	06:45	0	drilling -- trip	ok	Broke out and laid down OnTrak, GyroTrak and motor to deck.
06:45	07:30	0	drilling -- casin g	ok	Performed prejob meeting prior to rig up casing running equipment.
07:30	14:30	0	drilling -- casin g	ok	Made up cement stand and racked back in derrick. Rigged up to run 20" casing. Removed drilling bails and elevators, installed casing bails and elevators. Observed that 20" cas ing tong door had problems opening and closing.
14:30	17:00	0	drilling -- casin g	ok	Retrieved CTS and hoses from seabed.
					Meanwhile: Performed prejob meeting prior to run 20" casing.
17:00	18:00	0	drilling -- casin g	ok	Installed 20" casing bushings and slips.
18:00	20:30	36	drilling -- casin g	ok	Picked up shoe joint on deck. Verified float by hosing water through it. Made up shoe joint and float collar joint. Thread locked to connection. Experienced problems with Pipedec k Machine (PDM). Claw did not open. Not able to pick up casing joints from pipedeck to catwalk.
20:30	00:00	36	interruption -- repair	ok	Troubleshoot and repaired Pipedek Machine (PDM). Found tilt function and boom extension not working.
					Meanwhile: Performed general maintenance.

Bit Record

Run No.	Bit Size	Bit Type	IADC Code	Manufacturer	Hrs Drilled	Start mMD	End mMD	Hole Made (last 24H)	Hours Drilled (last 24H)	Form ROP	Total ROP	Total Hole Made	Total Hrs Drilled
8	26 in	VG-1	115	Hughes Christensen	45.2	454	454			20.2	20.2	911	45.2

Drilling Fluid

Sample Time	08:00
Sample Point	Active pit
Sample Depth mMD	455
Fluid Type	KCl/Polymer/GEM
Fluid Density (g/cm3)	1.35
Funnel Visc (s)	-999.99
Mf ()	
Pm ()	
Pm filtrate ()	
Chloride ()	
Calcium ()	
Magnesium ()	
Ph	
Excess Lime ()	
Solids	
Sand ()	
Water ()	
Oil ()	
Solids ()	
Corrected solids ()	

High gravity solids ()	
Low gravity solids ()	
Viscometer tests	
Plastic visc. (mPa.s)	32
Yield point (Pa)	14
Filtration tests	
Pm filtrate ()	
Filtrate Lthp ()	
Filtrate Hthp ()	
Cake thickn API ()	
Cake thickn HPHT ()	
Test Temp HPHT ()	
Comment	