Form B03

Scheduled Maintenance Work Order



Quantum Medical Solutions son blid transferding boundaries, transforming life Format Ref. - QMS/TSD-003 Rev. 00

	The second secon								
Work Order No	Qu=372189	Sch	eduled Month	FEBUARY	Po [8				
Work Order Date	1/2/10	Corr	pleted Date	12/2/2018					
Clinic Name	KLINIK I MALAYSIAM (TIM MUTIAR	A)Çlini	c Code	wilds					
BE No	WPL 000551	Distr	ict	WP. Labor	en				
BE Category	OFHTHALM OS COPE	wo	Assigned to	No fo ASTA	40/				
Ownership	Existing Equipment		New & Purchased Eq	ulpment	1				
BE Condition	☐ Under Warranty		BER Proposed						
Work Order Tune	☐ Preventive Maintenance (PM)	Third Party Calibration (TPC)							
Work Order Type	Routine Inspection (RI)		Statutory Certification	(SC)					
BE Third Party C	alibration / Statutory Certification Details								
Company Name	- 4/6	Cal /	Cert Date	NA					
Contact Number	I NOT THE REAL PROPERTY OF THE	Cal /	Cert Expiry Date						
Schedule Mainten	ance Execution Details QMS Engineer / Technician Name	13. 15. 15. 15. 15. 15. 15. 15. 15. 15. 15	Date	Start Time	End Time				
	cartian a shakkiyat di Mohto Nichali		2/2/2018	16-45an	11 Toan				
	BIOLEDICAL YEGHERIAN, GRIS 010-203-034				and an analysis of the second				
					, and a second s				
Customer Remarks									
oustomer Nemark	·								
Engineer / Technic	ian Signature	Customer Signature							
Name	MOND, ASSINDER & MOSED REALAND	Name							
Date	RECEIVED AND TECHNOLISMS	Designation							
	019-2634231	Date		HAIZA MAIDIN					
	12 fro18	Stamp Penolong Pegawai Perubatan U29							
	Y IV I FULL			· · · · · · · · · · · · · · · · · · ·					

For Internal Use only

First Verification

QMS Circle Incharge

Junds-Hansun Biomedical Ingineer, amb 019-3640179

Final Verification

QMS State Implance

QUARTUM MEDICAL SOLUTIONS SON BHD

Quantum Medical Solutions sin bhd transconding branduries, transforming life

Quantum Medical Solutions Sdn Bhd

BEMS Planned Preventive Maintenance Checklist **Ophthalmoscopes**

BE CODE: 12-815

CHECKLIST NO: CL-104 REV.000

PA	RT1 ASSET DE	TAILS			n e	4 4	di ilia							-50		
wo	RK ORDER NO	· pu	680	218	> 9					ASS	SET NO DEL 1	· W	LC	005	<i>51</i>	
MAN	NUFACTURER	>			,					MOI	DEL 1	N	(m	•		
FRE	QUENCY	► 3 MONT	HLY ()	6 MC	нти	LY ()		12 MONTHLY	(/) PPN	HOURS !	- SH O	.2	5		
PA	RT 2 SPECIAL P	RECAUTION														
If the	ere is evidence of	body fluid contar	mination,	submit th	ne dev	ice fo	r cleanin	g and	decontamination	on before inspecting	į it.					
	ar appropriate Per			•	•	-										
	ar grounded electron or to the safety pro			=				•		nee						
	e sure the test eq	•			and go	ilaana	e as per	THE TE	nacture: galaciii							
PA	RT 3 TEST APP	ARATUS		ik es es												
Tick	(√) where approp	riale			******	2 X Pro. Sto. 100 100 100 100 100 100 100 100 100 10						ARRAMENT SAIN 15 ARRAMANANANAN				***********
NO ASSET NO		DESCRIPTION						SERIAL	CAI	CALIBRATION DUE ON						
	NK		ELECTRICAL SAFETY ANALYZER						RFA		A1A-					
								-					•	-	• • • • • • • • • • • • • • • • • • • •	
DAI	DT 4															144.03°1
	RT 4 QUALITATI $()$ where approp				dijerije.	duit			ud Bedering						- 00 (8	
IMA	(У у шнеге църгор.	riaie		PASS	F.	AIL	NA					PAS	3	FAIL	N/	4
					_											
1	Chassis - verify p cleanliness and c			(/) ()	()	7		r/ Fuse - verify integ t breaker and/or rat		(ial) ()		()
2	Mount/ Fasteners	s - verify physical	integrity	() ()	(/)	8	Fittings/ Connectittings/connec	ectors - check all tors		(/	5 ()	()
3	Cables - verify in	tegrity		() ()	(/)	9	Controls/Switc	hes - verify proper	operation of) ()	()
4	AC Plug - verify in	ntegrity		() ()	(/)	10	Indicators - ve operation	rify proper illuminat	ion and	() ()	/	-)
5	Power Cord - ver integrity	ify proper insulat	ion and	() ()	(/)	11	Check Charge	r - verify proper ope	eration	() ()	/)
6	Strain Relief - ve		grity at	() ()	(/)	12	Check lamp he	older		(/	T ()	()
DAE	RT 5 PREVENTIN	/E MAINTENAN	CE TACL	/C					Company of the species		T.					
	($$) where appropi		UE IASI	10				3,99								
	() where opposite					от								NOT		
				DONE		NE **	NA					DON	Ξ [OONE **	N.	A
	Clean exterior an equipment	d interior of the) ()	(4	Check/replace	battery		/) ()	(
2	Clean lens dial) ()	(5	Check / replac	:e-lamp		(<u>/</u>	() (()
3	Clean filters			(/	Y ()	() No	** If you	I Parts, NA is defin have ticked 'NOT se Whichever Appl	DONE', then			8		

Quantum Medical Solutions Sdn Bhd

BEMS Planned Preventive Maintenance Checklist Ophthalmoscopes

CHECKLIST NO; CL-104 REV.000

	or			DE: 12-815						
RK ORDER NO -	pau 032	72189								
RT6 QUANTITATIV					A CALL AND					
(√) where appropriate	e									
No .	Descript	ion	Units / UOM	Set Values	Measured Values	Limit/Tolerance	PASS	FAIL	(R)	
								:		
						-				
	_						<u> </u>			
								<u></u>		
				!						
IRT7 ELECTRICAL	SAFETY TEST			Part Part I		Angle control of the beauty of the control of the c				
ECTRICAL SAFETY T		CANCEL CONCRETE AND AND AND A TANK TO WARRY COMM	man quire 4.74 mt s. 2 4.4 mbha a an 14.5 a a a a a a a a a a a a a a a a a a a	beer and I would		war war a mark and a state of the state of t				
(in accordance to the										
	PASS	FAIL	Z	IΑ				•		
RT 8 NOTES		ning delik Julia		t Eur						
	man a transition of the second	<u> </u>								
			i.							
								,	`	
									M	
								IZZA	NDIKN	V
							Penalona ^p		10/1-1-1-	
	CORRECTIVE N	MAINTENANCE REQ	UIRED		FUNCTION	ING	NOT FUNCTIO		^	_
WORK ORDER NO	· •	NA					NEXT PPM DA	re ► ' <u>2</u>	11/5/	≥4
PM has been performe	d in accordance to th	e checklist and the e	quipment is functio	ning to th	e intended pu	rpose.				
OMPLETED BY:	ANDREAS PROSE	- 自治見為語								
OMPLETED BY: 참안해 최연화	KOKAT LAGE (TA	all, Gets								