Form B03

Scheduled Maintenance Work Order



Format Ref:- QMS/TSD-022 Rev.01

| Mark Committee of the C | | | | Torride | Net QIVIS/ 13D-022 Rev. | | | |
|--|---|------|------------------------------|--|-------------------------|--|--|--|
| Work Order No | ~/0 pw040573 | Sch | neduled Month | January 2019 | | | | |
| Work Order Da | te ~/0 01/01/2019 | Cor | npleted Date | 30/1/2 | 0/9 | | | |
| Clinic Name | k.k KAMPAR | Clin | ic Code | price33 | | | | |
| BE No | PRK 031177 | Dist | trict | KAMPAR | ? | | | |
| BE Category | GLYCATED HEMOGLOBIA | U WO | Assigned to | rear a | | | | |
| Ownership | Existing Equipment | | MEET Equipment | | | | | |
| BE Condition | ☐ Under Warranty | | BER Proposed | to a commercial or | | | | |
| Work Order Ty | Preventive Maintenance (PM) | | Third Party Calibration | on (TPC) | | | | |
| THOM OTHER TY | Routine Inspection (RI) | | Statutory Certificatio | n (SC) | | | | |
| Reschedule Dat | е | | | | | | | |
| BE Third Party | Calibration / Statutory Certification Deta | ails | | | | | | |
| Company Name | W/D | Cal | / Cert Date | n | n = 1 | | | |
| Contact Number | n 10 | Cal | / Cert Expiry Date | 10 | | | | |
| | | | Purchase Kewpa No | Date: 1/1/ b. KKM/JKN 0f - 01-1 | leil PKB/KK/ | | | |
| Schedule Maint | enance Execution Details | | | | | | | |
| SI No | QMS Engineer / Technician Name | | Date | Start Time | End Time | | | |
| | SORU(| | 30/1/20/9 | 11:30 | 13:30 | | | |
| | | | | | | | | |
| STTHE M | URRENTLY NOT IN USE O CALIBRATION DATA ACHING. | | | PIRLO CO RIDGE A | PASOMAR (| | | |
| G Tel | NOOR AZARUL B AHAMAD PIRAK LAB SPECIALIST Quantum Medical Solution Sdn. Bhd No 10 B, Persiaan Greentown 4c reentown Avenue, 30450 Ipoh, Perak /fax: 05-2461991 Hp: 012-39644013 | Name | gnation MIMI MA JUNUTEKNO | ZURA EN GAZ W LOGIMAKMAZ ERUBAD CKESIHATAN KAMPA | AHAP AHU32 B | | | |
| or Internal Use of | niv | | | | | | | |

First Verification QMS Circle Incharge

Final Verification QMS State Incharge



KEMENTERIAN KESIHATAN MALAYSIA

MEET Planned Preventive Maintenance Checklist Analyzers, Laboratory, Glycated Hemoglobin
BE CODE: ME-004

CHECKLIST NO:CL-013-002 REV.000

| F | PART 1 ASSET DET | TAILS | | | | | | | | | | | | | | |
|------|---|---------------------|------------|----------|-----------------|--------|-----------|---------|--------------------|-----------------------------------|---------------|---------|-----------|-------|-----|----|
| W | ORK ORDER NO | r/o p | w 40 | 546 | 373 | 3 | | | | E | BE NO | - PRI | 603 | 11. | 77 | |
| M. | ANUFACTURER | ► Bio Rad | | | | | | | | Λ | MODEL | ► D10 | | | | |
| FF | REQUENCY | ► 6 MONTH | LY (|) | 12 M | ONTI | HLY (v |) | | F | PPM HOURS | ▶ 2.00 | | | | |
| E | ART 2 SPECIAL PI | RECAUTION | | | | | | | | | | i in in | | | | |
| lf t | there is evidence of t | oody fluid contami | nation, s | ubmit th | ne dev | ice fo | r cleanir | ng an | d decontaminati | on before inspec | ting it. | | | | | |
| W | ear appropriate Pers | onnel Protection I | Equipme | nt (PPE |) durir | ng wo | rk. | 100 100 | | | | | | | | |
| W | ear grounded electro | static wristband w | vhen han | dling P | CB or | electr | onic cor | npon | ents. | | | | | | | |
| Re | efer to the safety proc | cedure for addition | nal preca | utions a | and gu | idanc | e as pei | mar | nufacturer guideli | ines. | | | | | | |
| | ake sure the test equ | | duly calib | rated. | | | | | | | | | | | | |
| | ART 3 TEST APPA | | | | | | | | | | | | | | | |
| | ck (√) where appropri | | | | | | | | | | | | | | | |
| | NO ASS | ET NO | | | DI | ESCR | IPTION | | | SERI | AL NO | CAL | IBRAT | ION D | DUE | NC |
| | +~ 10 |) — E | LECTRI | CAL SA | FETY | ANA | LYZER | | | | - 0 | 10 - | _ | | | |
| | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | |
| P | ART 4 QUALITATIV | F TASKS | | | | | | | | | | | | | | |
| _ | $k(\sqrt{)}$ where appropris | | | | | | | T | | | | | | | | |
| | Tr. I | | | PASS | FA | AIL | NA | | | | | PASS | F/ | AIL | N/ | ١. |
| | | | | | | | | | | | | | | | | |
| 1 | Chassis - verify phocleanliness and co | | | (/) |) (|) | () | 9 | HPLC Pump - | Verify Proper Op | eration | (/ |) (|) | (|) |
| 2 | Mount/ Fasteners - | verify physical in | tegrity | (/) | (|) | () | 10 | Probes - Verify | Integrity | | (/ |) (|) | (|) |
| 3 | AC Plug / Power C Integrity and Prope | | cal | (/) | (|) | () | 11 | Temperature S | System- Verify | | (/ |) (|) (| (|) |
| 4 | Strain Relief - verif both ends of line co | | y at | (/) | (|) | () | 12 | Fan/Motor/Pun | np - Verify Condi | ion & Operati | on (/ |) (|) (| (|) |
| 5 | Fittings/ Connector fittings/connectors | | rity | (/) | (|) | () | 13 | Computer Syst | ems -Verify Phys | sical | (/) | (|) (| (|) |
| 6 | Controls/Switches - of controls | - verify proper ope | eration (| (/) | (|) | () | 14 | Printer - Verify | Operation | | () | (|) (| (|) |
| 7 | Indicators/Displays Operation | Verify Proper | (| /) | (|) (| () | | | | | | | | | |
| 8 | Bar Code Reader - | Verify Integrity | (| /) | (|) (|) | | | | | | | | | |
| PA | RT 5 PREVENTIVE | MAINTENANCE | TASKS | | | | | | | | | | | | | |
| ick | ($\sqrt{\ }$) where appropria | te | | | | | | | | | | | | | | |
| | | | ı | DONE | NO DON ** | | NA | | | | | DONE | NO DON | | NA | |
| 1 | Cleanliness-Clean I the Equipment | nterier and Exterie | er of (| /) | (|) (|) | 5 | Clean Measurin | ng Area | | (/) | (|) (| |) |
| 2 | Clean Hydraulics ar | nd pneumatic syst | em (| /) | (|) (|) | 6 | Perform Post R | outine | | (/) | (|) (| |) |
| 3 | Clean the tubing (re | place if necessary | y) (| 1) | (|) (|) | | | | | | | | | |
| 4 | Clean Sampling Ma | chanism | | 1 | | | | Note | es: ** If you h | Parts, NA is definate ticked 'NOT | DONE', then | | | | | |

(dir.)

KEMENTERIAN KESIHATAN MALAYSIA

MEET Planned Preventive Maintenance Checklist Analyzers, Laboratory, Glycated Hemoglobin

CHECKLIST NO:CL-013-002 REV.000

| VORK | ORDER NO > ~/ @ DW0405673 | | | | | | | |
|---|---|--------------------------------------|---|--------------------|--|-------------|-------------|--------|
| | ORDER NO > ~/ & pw0405673 | 3 , | | | | | | |
| ART 6 | QUANTITATIVE TASKS | | lugaries i | | | L. Laker | | |
| ck(V) | where appropriate | | | | | | | |
| No | Description | Units / | Set Values | Measured Values | Limit/Tolerance | PASS | FAIL | NA |
| | QC Result (Attach Result) | | | | | () | () | (/) |
| | | | | | | | 3 36 | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| RT 7 | ELECTRICAL SAFETY TEST | | | | 14 = 50 × 10 × 10 × 10 × 10 × 10 × 10 × 10 × | | | |
| | | | | | | | | |
| | CAL SAFETY TEST, (attach report) | | | | | | | |
| :k (\) | where appropriate Standard use : | | Result : | | | | | |
| | IEC 60601 IEC 61010 II | EC 62353 | | PASS | FAIL | NA | | |
| RT 8 | NOTES | | 544 E. E. | | | Д | | |
| | | | | 100 | | | | |
| * 7 | et applicable for | R ECG | CT DEM | RICA Sof | oc sal | eern ; | res org. | 7 DUF |
| * 7 | LET APPLICABLE FOR | R ECG | ECT. | RICA | oc sal | EETY ; | 7E S. | 7 DUF |
| * ~ 7 | e unit runant | R FCG | ECT. | RICA | oc sal | EETY ; | 7F S. | 7 DUF |
| * | LET APPLICABLE FOR | R ECG | PET (| RICA | oc sal | eery ; | 76 G | 7 DUF |
| * ~ 7 | CORRECTIVE MAINTENANCE REQUI | UM | Pen | RICA | TUPP | OT FUNCTION | 956. | 7 DUF |
| 7 | C UNIT PUNAINE CORRECTIVE MAINTENANCE REQUIR | UM | Pen | Sef | G N | OT FUNCTION | NG T | |
| 7 | C UNIT PUNMINE | UM | Pen | Sef | G N | E BA | NG T | ncy Jo |
| 7 | C UNIT PUNAINE CORRECTIVE MAINTENANCE REQUIR | UM | Pen | Sef | G N | OT FUNCTION | NG T | |
| WOR | C UNIT PUNAINE CORRECTIVE MAINTENANCE REQUIR | RED | Z F | UNCTIONING | G N | OT FUNCTION | NG T | |
| WOR Whas t | CORRECTIVE MAINTENANCE REQUIRED BY: CORRECTIVE MAINTENANCE REQUIRED BY: NOOR AZARUL B | RED | Fang to the in | UNCTIONING | G N | OT FUNCTION | NG T | |
| WOR WOR | CORRECTIVE MAINTENANCE REQUIRED BY: CORRECTIVE MAINTENANCE REQUIRED BY: NOOR AZARUL B | RED | Fang to the in | UNCTIONING | G N | OT FUNCTION | NG T | |
| WOR A has b | CORRECTIVE MAINTENANCE REQUIR K ORDER NO Deen performed in accordance to the checklist and the equir | PRED AHAMAD CIALIT Utility SAP RI | P F F F F F F F F F F F F F F F F F F F | UNCTIONING | G N | OT FUNCTION | NG T | |