Form B03





Format Ref: - QMS/TSD-022 Rev.01

Work Order No.	PWO365343	Schedule Month	June 2018					
Work Order Date	01/06/2018	Completed Date	# 12-06-2018					
Clinic Name	Klinik Kesihatan Pesta / Kampung Ken	Clinic Code	JHR015					
BE No.	JHR002018	Distict	BATU PAHAT					
BE Category	Fetal Heart Detectors, Ultrasonic	WO Assigned to	MUHD SHAZRUL.					
Ownership	✓ Existing Equipment	Purchase	New					
BE Condition	✓ Active	BER Proposed						
Work Order Type	✓ Preventive Maintenance (PM)	Third Party Calibration (TPC)						
Work Order Type	Routine Inspection (RI)	Statutory Certification (SC)						
Reschedule Date								
BE Third Party Calibrat	ion / Statutory Certification Details							
Company Name	NA	Cal / Cert Date	NO					
Contact Number		Cal / Cert Expiry Date	NI					
Action Taken								
PM / RI job d	one as per checklist. Unit tested functioning go	od & ready to use.	Manufacturer :					
Corrective M	aintenance / Breakdown		Modal :					
BE Sticker A	vailability : Yes / NA		Serial No :					
Remarks:								
Schedule Maintenance	Execution Details							
SI No	QMS Engineer / Technician Name	Date	Start Time End Time					
W	JHD SHAZRUL	17-06-7018	11:40 12:00					
	•							
	9							
Customer Remarks								
	NA.							
	12/06/2018	Date (No. Pend	cirah Necey Afduliain daftaran Penuh: 54451) Jururawat U29 Kenangan Dato Onn					
For Internal Use	RÁŽICA MISKAN		12/6/18					

First Verification QMS Circle Incharge Biomedical Engineer (Circle In-Charge) Quantum Medical Solutions Sdn. Bhd.

Final Verification QMS State Incharge



PART 1 ASSET DETAILS

KEMENTERIAN KESIHATAN MALAYSIA

MEET Planned Preventive Maintenance Checklist Fetal Heart Detectors, Ultrasonic

BE CODE : 11-696

CHECKLIST NO:CL-070-000 REV.000

WOF	RK ORDER NO	•	bno 3	6534	-3					BE NO	•	JHR	310601	B
MAN	UFACTURER	•	Huntl	ergu						MODEL	•	# Sol	nicaic	· /c
FRE	QUENCY	•	12 MONT	THLY (√)					PPM HOUR	s Þ	0.50		
PAF	RT 2 SPECIAL PR	RECA	UTION							interviewe ex		haraday		
If the	re is evidence of bo	ody fl	uid contam	ination, s	ubmit the	device f	or cle	aning a	and decontamination	before inspecting it.				
Wea	r appropriate Perso	nnel	Protection	Equipme	nt (PPE) d	uring w	ork.							
Wea	r grounded electros	static	wristband v	when han	dling PCB	or elec	tronic	compo	nents.					
Refe	r to the safety proce	edure	for additio	nal preca	utions and	guidan	ice as	per ma	anufacturer guideline	es.				
Make	sure the test equip	pmer	nt used are	duly calib	orated.									
PAF	RT 3 TEST APPAR	RATI	JS											
Tick (($\sqrt{\ }$) where appropri	ate												
N	O ASSI	ET N	0			DES	CRIP	TION		SERIAL NO		CALIE	BRATION	DUE ON
								~ '						
							N	P '						
PAF	RT 4 QUALITATIV	ETA	SKS	Bern .	in to					Back Frank Cole				
Tick (√) where appropria	ate											-	
					PASS	FAIL		NA				PASS	FAIL	NA
1	Chassis - Verify ph cleanliness and co					() ()	7 Indicators/Disp and operation.	olays - Verify proper illumina	tion	(/)	()	()
2	Mount/Fasteners -	Verif	y physical i	ntegrity.	(/)	() ()	8 Alarm/Audible	e Signal - Verify operation.		(/)	()	()
	Power Cord - Verify integrity.	y pro	per insulati	on and	()	() (/)		to the state of th				
4	Strain Relief - Veri both ends of line co		ysical integ	grity at	(/)	() ()						
	Transducers/Cable condition.	es - V	erify integri	ity and	V)	() ()						
	Controls/Switches/ operation of contro		ad - Verify	proper	(/)	() ()						
PAF	RT 5 PREVENTIVE	E MA	INTENAN	CE TASK	S									
Tick ((\checkmark) where appropria	ate												
					DONE	NOT		NA						
					DOME	DONE	**	14/3						
1	Cleaning the exteri	or/int	erior.			() ()						
2	Clean Transducers	s/Cab	les.		(/)	() ()	If you have	Il Parts, NA is defined as NC ve ticked 'NOT DONE', then			**	
3	Check/Replace ba	attery	***		(/)	() ()	Choose V	Whichever Applicable				



KEMENTERIAN KESIHATAN MALAYSIA

MEET Planned Preventive Maintenance Checklist Fetal Heart Detectors, Ultrasonic

BE CODE : 11-696

CHECKLIST NO:CL-070-000 REV.000

VORK ORDER N) >					
PART 6 QUANTI	FATIVE TASKS					
ick ($\sqrt{\ }$) where appr	opriate			i -		2
No	Description	Units / UOM	Set Values	Measured Values	Limit/Tolerance	PASS FAIL NA
Not Appl	cable					
			/			
_						
ART 7 ELECTR	ICAL SAFETY TEST					
ECTRICAL SAF	ETY TEST, (attach report)					
ck (\) where ap	propriate					
Standard	use:		Result :			ea.
	IEC 60601 IEC 61010 IEC 6	32353		PASS	FAIL	NA
		NA				
	CORRECTIVE MAINTENANCE REQUIRED)	Z	FUNCTIONIN	NG N	NOT FUNCTIONING
WORK ORDE	RNO ►				NEXT PPM	NDATE - JUNE 19
	ormed in accordance to the checklist and the equipment MUHD SHAZRUL.	nt is functioni	ng to the ii	ntended purpo	Se.	