Form B03 **Scheduled Maintenance Work Order**



Format Ref: - QMS/TSD-022 Rev.01

Work Order No.	PWO365202			Schedule Month			June 2018			
Work Order Date	01/06/2018			Coi	mple	ted Date	27.6.18			
Clinic Name	Klinik Kesihatan Batu Anam				nic C	ode	JHR080			
BE No.	JHNANE014				tict		SEGAMAT			
BE Category	1	ANALYZERS, LABORATORY, HEM) Ass	igned to	Hastrong			
Ownership		Existing Equipment				Purchase	√ New			
BE Condition		V	Active			BER Proposed				
Work Order Type		✓ Preventive Maintenance (PM)			Third Party Calibration (TPC)					
		Routine Inspection (RI)			k E	Statutory Certificati	ion (SC)			
Reschedule Date										
3E Third Party Calibration / Statutory Certification Details										
Company Name	npany Name ~				/ Ce	ert Date	J			
Contact Number	ontact Number			Cal / Cert Expiry Date			_			
Action Taken										
PM / RI job done as per checklist. Unit tested functioning good					d & ready to use.		Manufacturer: Mindray			
Corrective Maintenance / Breakdown							Modal: Bc-305			
BE Sticker Availability : Yes / NA					Serial No : TH = 7300					
Remarks: PPM done by under										
Schedule Maintena	nce Exec	cution	Details							
SI No	SI No QMS Engineer / Technician Name					Date	Start Time End Time			
	Hanr	Hanrs				27/0/18	10.00 a.m	12.00 p.M		
						. , . ,				
			·							
Customer Remarks										
Engineer / Technician Signature					Customer Signature					
Name MOHD HANIS BIN JAMHURI					Name AFD HAKIM					
Date SENIOR BICHEROLEAL TECHNICIAN Desig					signation AHMAD LUCMAR U29					
TECHNICAL SERVICE DEPARTMENT					Date KK Batu Anam					
012-3967845 Seal										
For Internal Use										

First Verification

QMS Circle Incharge MOHD SHAIFUDIN BIN SIMIN Biomedical Engineering Quantum Medical Solutions H/P: 012-3967638

Final Verification QMS State Incharge



PART 1 ASSET DETAILS

KEMENTERIAN KESIHATAN MALAYSIA

MEET Planned Preventive Maintenance Checklist Analyzers, Laboratory, Hematology, Cell Counting, Automed (Medium)

BE CODE: ME-009

CHECKLIST NO:CL-015-000 REV.000

wo	RK ORDER NO .	0W0 36521	25					BE NO	- Jh	MA	NEC	914	F
work order no > pwo 365202 MANUFACTURER > Mindry								BENO JHHANE OIY MODEL BC-30 S					
FRE	EQUENCY ►	6 MONTHLY (12 MONT	HLY ()		PPM HOURS	▶ 2.0	0			
PA	RT 2 SPECIAL PRECA	UTION											
If the	ere is evidence of body fl	uid contamination, s	submit the	device f	or cleaning	g and	decontamination	on before inspecting it.	***************************************	***************************************			
Wea	ar appropriate Personnel	Protection Equipme	ent (PPE)	during w	ork.								
Wea	ar grounded electrostatic	wristband when har	ndling PC	B or elect	tronic com	pone	ents.						
Refe	er to the safety procedure	e for additional preca	autions an	d guidan	ce as per	manı	ufacturer guideli	nes.					
	e sure the test equipmen		brated.										
	RT 3 TEST APPARATU	JS -		4.0									
	(√) where appropriate			DE00	DIDTION			OFFINI NO		041.101			
NO ASSET NO ELE		3	DESCRIPTION ELECTRICAL SAFETY ANALYZER					SERIAL NO		CALIBRATION DUE ON			
		ELECTR						3226902	1				
DA	DT 4 OUND TO THE	Olco											
	RT 4 QUALITATIVE TA $(\sqrt{\ }) \text{ where appropriate}$	iono											
lick	(v) where appropriate		PASS	FAIL	NA				P	ASS	FAIL	j	NA
1 Chassis - verify physical integrity, () (()	()	11	Probes- Verify	physical interigity	(_)	()	()
cleanliness and condition Mount/ Fasteners - verify physical integrity			(/)	()	()	12	Temperature s	system- verify proper operatio	n (()	()
3 Power Cord - verify proper insulation and			(/)	()	()	13	Fan/motor/con	npressor/pump- verify physica				()
integrity 4 Strain Relief - verify physical integrity at			(/)		()		integrity and property initialization Property		/)		()	
both ends of line cord									4.9	2 ·			
	Fittings/ Connectors - ch fittings/connectors		(/)		()		104 (001 1000 P	physical operation.)		()
6 Controls/Switches - verify proper operation of controls			(/)	()	()	16	User Setting -	Verify Operation		/)		()
7 Indicators/Displays- verify proper operation			(/)	()	()	17	User calibratio	n - Verify Operation	(1	()	()
8				()	()	18	Self Diagnostic	c - Verify Operation	(-	1	()	()
integrity 9 Hydraulics and Pneumatics System-verify			(/)	()	()	19	Plate moveme	nt calibration - Verify Operation	on (-)	()	()
10	physical integrity 10 Sensors- verify phisical integrity			()	()								
ΡΔΙ	RT 5 PREVENTIVE MA	INTENANCE TASK	(6										
	() where appropriate	INTERACT PACE											
ren	(v) mere appropriate			NOT							NOT		
			DONE	DONE **	NA				D	BNC	DONE	1	NA
1	Clear exterior and interi	or of the	()	()	()	6	Clean measuri	ng area	(,	_)()	()
2	equipment Inspect/clean interior of	unit	()	()	()	7	Calibrate syste	em parameter	(-	()()	(,	/)
3	Clean hydraulics and pn	eumatic system	()		()	8	Perform Post r	outine	í	· //) (,	()
							i Giloini i Goti	oduno	سر `	/ / \	,	`	,
4	Tubings - cleah/ replace	()		()	Note	es:							
5	Clean sampling mechan	(/)	()	()		** If you	I Parts, NA is defined as NOT have ticked 'NOT DONE', the se Whichever Applicable			8			



KEMENTERIAN KESIHATAN MALAYSIA

MEET Planned Preventive Maintenance Checklist

Analyzers,Laboratory,Hematology, Cell Counting, Automated,Medium

BE CODE: ME-009

CHECKLIST NO:CL-015-000 REV.000

pw0 365200 WORK ORDER NO > PART 6 QUANTITATIVE TASKS Tick ($\sqrt{\ }$) where appropriate Units / Set Measured Limit/Tolerance PASS FAIL No Description NA UOM Values PART 7 ELECTRICAL SAFETY TEST ELECTRICAL SAFETY TEST, (attach report) Tick (\(\) where appropriate Result: Standard use: IEC 61010 IEC 62353 IEC 60601 PASS FAIL NA PART 8 NOTES FUNCTIONING NOT FUNCTIONING CORRECTIVE MAINTENANCE REQUIRED NEXT PPM DATE ► WORK ORDER NO ▶ PPM has been performed in accordance to the checklist and the equipment is functioning to the intended purpose. COMPLETED BY: Hanis 27/0/10 DATE: