## Form B03

## Scheduled Maintenance Work Order



Quantum Medical Solutions son blid grass rading boundaries, coassinening The Format Ref. -QMS/TSD-003 Rev. 00

Work Ord	er No	140339935	Scheduled Month	し ば	JAN-19.						
Work Order Date		01/01/2018	Completed Date	19.	01.2018						
Clinic Name		KK JALAN OYA.	Clinic Code	\$1	wk169,						
BE No		SWK004819	District	2	1BH						
Be Catego	ry	BP SET, Aneroid.	WO Assigned to	اک	UBME1.						
Ownership Existing Equipment			MEET Equip	MEET Equipment							
BE Condition		Under Warranty	BER Propose	ed							
Work Or	der Type	Preventive Maintenance (P	M)	Third Party Calibration (TPC)							
Work Order Type		Routine Inspection (Ri)		Statutory Certification (SC)							
1,5		ration / Statutory Certification D			a, o februaria di bul						
mpany íگر		N/A -	Cal / Cert Date		-N/A						
Company I Action Tak			Cal / Cert Expiry Da	ate							
		e. fun Oti oning go ce Execution Details	е <b>д</b> ,								
SI No		ineer / Technician Name	Date	Start Time	End Time						
10028B	Cha	ides Than	19:01.2018	08:30	a9 = 80.						
<del> </del>											
Customer F	Remarks										
Engineer / <sup>2</sup>	Technician	Signature	Customer Signature								
/			Name	Name							
Date	CHARLES THAM  Biomedical Engineer Quantum Medical Solutions Sibu Division  Designation  Date  Seal 2 3 204										
		Biomedical Engineer Quantum Medical Solutions	Date	sork	47						

For Internal Use Only

First Verification QMS Circle Incharge

James Bo Sr. Biomedical Engineer
Quantum Medical Solutions

Final Verification QMS State Incharge



## Quantum Medical Solutions Sdn Bhd

BEMS Planned Preventive Maintenance Checklist Sphygmomanometers, Aneroid

CHECKLIST NO: CL-140 REV.000

		BE CODE : 16-156	; 	
PART 1 ASSET DETAILS	tan di di mari d			
WORK ORDER NO -	PW0339935		ASSET N	· SWK00489
MANUFACTURER -	N/A.		MODEL	· SPIRIT.
FREQUENCY > 3	MONTHLY ( )	6 MONTHLY ( ) 12	MONTHLY (V) PPM HOU	RS + Ox5H
PART 2 SPECIAL PRECAU	TION			
Wear appropriate Personnel Pi Wear grounded electrostatic wi	rotection Equipment (PF ristband when handling or additional precautions	PCB or electronic components. and guldance as per manufactu		
PART 3 TEST APPARATUS				
*(V) where appropriate			estate to the place of the place of the second seco	
NO ASSET NO		DESCRIPTION	SERIAL NO	CALIBRATION DUE C
I EEGA COUST	NON-INVASIVE	BLOOD PRESSURE ANALYZER	3228010	- I algho
				_
ART 4 QUALITATIVE TASKS	3			
Chassis - verify physical intercleanliness and condition  Mount/ Fasteners - verify phyintegrity  Check cuff & hose verify phyintegrity and cleanliness  Check Bulb verify physical intercleanliness  Check air release valve  Check dial	vsical (V)			
Calibration	( ) (	) ( :/)		
77.5 PREVENTIVE MAINTENA	ANCE TASKS			
(v) where appropriate				
	DONE (	NOT DONE NA Notes:		
Clean exterior and interior of the equipment	/	** ) ( ) * Fo	or all Parts. NA is defined as NOT you have ticked 'NOT DONE', the hoose Whichever Applicable	APPLICABLE in justify in Part 8



## Quantum Medical Solutions Sdn Bhd

BEMS Planned Preventive Maintenance Checklist Sphygmomanometers, Aneroid

CHECKLIST NO: CL-140 REV.000

		8E C	ODE . 16-15	3							
WORK	ORDER NO - PW0339935		•								
PART 6	QUANTITATIVE TASKS				van Spans vir 1900 Geografie George		01,243° 31,743°			Are play	
	where appropriate	Tally Appending and the second	** *** *** *** ***			1				<u> </u>	
No	Description	Units /	Set	Measured	Limit/Tolerance	e P	ASS	FAI	 !L	ΝA	
	,	UOM	Values	Values							
	·				-						
1	Blood pressure accuracy	mmHg	40	460	38-42	(1	<b>-</b> /)	(	)	{	)
		mmHg	70	70	68-72	( (	<b>V</b> )	(	)	(	)
		mmHg	100	ಣ್ನ	98-102	(4.	1)	(	)	(	)
		mmHg	130	131	128-132		<u> </u>		)		)
			i								
		mmHg	160	160	156-162		<u>/)</u>		)		)
		mmHg	190	190	188-192	()	<b>/</b> )	(	)	(	)
				•							
RT7	ELECTRICAL SAFETY TEST	5 X 30 64 50	4.14, 3.15	jang sargi		eric Jack				155 AAC	a jagaray
ECTRIC	CAL SAFETY TEST, (attach report)										
	(In accordance to IEC 60501)										
,		$\overline{}$									
	PASS FAIL	N.	A								
ारा 8	NOTES										
	long.										
C-	ppm done										
	•										
	ppm done.										
		Ν,									
-	Unit is function	4°h-4	P2	A ste	actions	†					
		ر ا		,	' '	,					
	CORRECTIVE MAINTENANCE REQUIRE	D	F	JNCTIONING	; <u> </u>	NOT FUNCTI	ONIN	IG			
									*T	14.4	) 201
WORK	ORDER NO ►					NEXT PPM D	ATE	٠.	0	4.	
has -	on novicement in aggregations to the objective	ont in fracti	a to the !	Innded so	~~		·····				
	en performed in accordance to the checklist and the equipme	ent is runctionin	g to the in	tenaed purpo	se.						
PLETE	0										
	CHARLES THAM										
	Blomedical Engineer Quantum Medical Solutions										
<b>5</b> :	Sibu Division										

19/01/2018