Form B03

Scheduled Maintenance Work Order



Format Ref. -QMS/TSD-003 Rev. 00

Work Order No	PW0339442	Scheduled Month	ta.,	JAN 20LB.	
Work Order Date	01/01/2018	Completed Date		19.01.2018	
Clinic Name	KIL THLAN OYA.	Clinic Code		SWK169:	
BE No	SWK004681	District		SIBULI	
Be Category	BP, SET WERCHRY	WO Assigned to		SIUBMEL,	
Ownership	Existing Equipment	MEET Equipmen	t		
BE Condition	Under Warranty	BER Proposed			
Work Order Type	Preventive Maintenance (PM)	Third Party Calib	ration (TPC)		
Work Order Type	Routine Inspection (RI)	Statutory Certific	cation (SC)		
Third Party Calibr	ation / Statutory Certification Details	· 1000 1000 1000 1000 1000 1000 1000 10			
ယကpany Name	- N/A -	Cal / Cert Date		-N/A	
Company Number		Cal / Cert Expiry Date		70 111	
	e. S functioning go ce Execution Details				
	neer / Technician Name	Date	Start Time	End Time	
desoly Ch	ales Than:	19:07.2018	12-60	(2.39	
B. I.	ARLES THAM iomedical Engineer itum Medical Solutions	Customer Signature Name Designation Date	Service of the servic		
	Sibu Division 9.01.2010	Seal P(8/2	~ ~g		

First Verification

QMS Circle Incharge
James Bo
Sr. Biomedical Engineer
Quantum Medical Solutions

Final Verification QMS State Incharge



Quantum Medical Solutions Sdn Bhd

BEMS Planned Preventive Maintenance Checklist Sphygmomanometers Mercury

CHECKLIST NO: CL-143 REV.000

				E. 16-158		ĺ
PART	ASSET DETAILS					
WORK	ORDER NO - P	WO 339442	-		ASSET NO	· Swkoo 464
MANUFA	CTURER >	CLUSON			MODEL	· Mu3
FREQUE	NCY ► 31	MONTHLY ()	6 MONTHLY ()	12 MONTHLY (PPM HOURS	
PART 2	SPECIAL PRECAUTI	ON			77111110070	
If there is	evidence of body fluid	contamination, submit	the device for cleaning and	decontamination before in	aspecting it	F 17
Wear app	ropriate Personnel Pro	ection Equipment (PF	E) during work.		rapooning it.	
			PCB or electronic compone	ents.		
Refer to th	e safety procedure for :	additional precautions	and guidance as per manu	rfacturer guidellnes.		
Make sure	the test equipment use	d are duly calibrated.			,	
	EST APPARATUS					
	iere appropriate					·
NO	ASSET NO		DESCRIPTION		SERIAL NO	CALIBRATION DUE O
1	EASHUOSS	NON-INVASIVE	BLOOD PRESSURE ANA	LYZER 322	DON	12/0/10
						1 9 10
251-2 Q	JALITATIVE TASKS					
	re appropriate	<u>ar ing pangganan na manggana</u>				
and clear Check Bu cleanlines Check air Check mer	Ib verify physical integs release valve rcury valve as tube leak	rity and (V)				
	ENTIVE MAINTENAN	CE TASKS				
f V) where a	ppropriate		NOT ONE NA Notes:			· · ·
Clean exterio equipment	or and interior of the) ()	* For all Parts, NA is de If you have ticked 'NOT D	ONE' then justify in	CABLE ** Part 8 ***
Clean mercu	гу	()() ()	Choose Whichever Applic	CADIE	
Clean mercui		()() ()			
lean glass ti	ube	(\mathcal{V})) ()			

))	
प्रवादिशाव	. Æोटम	erfittienta	ahı bini

Quantum Medical Solutions Sdn Bhd

प्रमुखंशात - 	BEMS Planned Preventive Maintenance Checklist Sphygmomanometers, Mercury BE CODE . 18-198						CHECKLIST NO:CL-143 REV.000	
WORK (ORDER NO >	DW0339442						
PART 6	QUANTITATIVE	TASKS		5.42.154				
lick (v)	where appropriate		1	T = .		· · · · · · · · · · · · · · · · · · ·		
No		Description	Units /	Set Values	Measured Values	Limit/Tolerance	PASS	FAIL NA
į								
1	Blood pressure a	accuracy	mmHg	40	40	38 - 42	()	() ()
			mmHg	70	172	68 - 72	(1)	() ()
			mmHg	100	100	98 - 102		() ()
			mmHg	130	132	128 - 132		() ()
			mmHg	160	160	158 - 162	(1)	() ()
		**************************************	mmHg	190	192	188 ~ 192		() ()
					172			., .
	ELECTRICAL SA	FETY TEST	1. 1989 - 1					
~ \	UNIT	done. is functioni	I	8-	UGL 1			
	ORDER NO .	CORRECTIVE MAINTENANCE REQUIRED	Bungkarin		UNCTIONING	•	NOT FUNCTIONING NEXT PPM DATE	They so
rnas oee 1PLETEC	CHA Ble Quant	28	ranction(f)	, to the lift	eriueu purpo.	uo.		٠.