Form BO

Form B03 Scheduled Maintenance Work Order



Quantum Medical Solutions sdn bhd

Format Ref: - QMS/TSD-022 Rev.01

The second second					
Work Order No.	PWO366177	Schedule Month	July 2018		
Work Order Date	01/07/2018	Completed Date	1017/2018		
Clinic Name	Klinik Kesihatan Sungai Ren	ngit Clinic Code	JHR047		
BE No.	JHR008642	Distict	KOTA TINGGI		
BE Category	Mixers	WO Assigned to	ktgbme3		
Ownership	✓ Existing Equipment	Purchase	New		
BE Condition	Active	BER Propose	d		
	✓ Preventive Mainten	ance (PM) Third Party Co	alibration (TPC)		
Work Order Type	Routine Inspection	(RI) Statutory Cert	cation (SC)		
Reschedule Date	ир				
BE Third Party Calibra	ation / Statutory Certification De	tails			
Company Name	MIA	Cal / Cert Date	N/A		
Contact Number	N/A	Cal / Cert Expiry Date	N/A		
BE Sticker / Remarks:	Availability: Yes / N	A	Serial No: 061116		
Remarks:					
Schedule Maintenand			Start Time End Time		
SINo	QMS Engineer / Technicia				
ag	SAFWAN	10/7/201	8 10 00 11 10		
Customer Remarks	Mp				
Date	SAFWAN BIN ROSLAN omedical Technician Medical Solution Sdn. Bhd	Customer Signature Name Designation Date Seal	MASIK Juruteknologi Makmel Perubatan U29 Klinik Kesihatan Sungal Rengit Pengerang		
First Verification QMS Circle Incharge	MUHD RAMADHAN B. TAMAR JAYA Biomedical Sequineer Tachnical Service Department Quantum Medical Solutions Sdn. Bhd. Tel: +60 12-396 1697	Final Verification QMS State Incharge			



KEMENTERIAN KESIHATAN MALAYSIA

MEET Planned Preventive Maintenance Checklist Mixers

BE CODE 15-590

CHECKLIST NO:CL-100-000 REV.000

PART 1 ASSET DETAILS		The Control of the Control	MANAGER STATE	- JHR 00 86 42
WORK ORDER NO - PW 0 3	366177		BE NO	
MANUFACTURER - PRIM	IER		MODEL	. 2000
REQUENCY • 6 MONTH	ILY () 12 MONTHLY (√)	PPM HOURS	▶ 1.00
PART 2 SPECIAL PRECAUTION		THE STATE AND		
there is evidence of body fluid contamin	nation, submit the device for cleaning a	and decontamination be	efore inspecting it.	100
Near appropriate Personnel Protection E				
Near grounded electrostatic wristband w	when handling PCB or electronic compo	onents.		1373-15
Refer to the safety procedure for addition	hal precautions and guidance as per ma	anufacturer guidelines.		
Make sure the test equipment used are d	duly calibrated.	THE RESERVE OF THE PARTY OF THE		SANCE OF THE SANCE
PART 3 TEST APPARATUS		LT RESUSTAN	Manager Commencer State	
Eick (√) where appropriate	DESCRIPTION		SERIAL NO	CALIBRATION DUE ON
NO ASSET NO			3218071	24/8/2018
1 TEESA OOLO	ELECTRICAL SAFETY ANALYZER		321 0091	
				- The second sections
PART 4 QUALITATIVE TASKS		THE PERSON	i dine santal	
Tick (√) where appropriate				PASS FAIL NA
	PASS FAIL NA			PASS FAIL NA
		8 Controls/Switches	s - verify proper	(/)()()
Chassis - verify physical integrity, cleanliness and condition	(/)()()	operation of contr		
2 Casters/Brakes - if mounted, verify physical integrity	(/)()()	9 Indicators/ Displa illumination and o		() () (/)
3 AC Plug - verify integrity	(/)()()	10 Alarms/ Interlocks available	s - check all alarms	() () (/)
4 Power Cord - verify proper insulation integrity	n and (/) () ()	11 Motor - verify prop	per operation	(/)()()
5 Strain Relief - verify physical integrit both ends of line cord	ty at (/) () ()	12 Label - verify phys	sical integrity	(/)()()
6 Circuit Breaker/ Fuse - verify integrity of external circuit breaker and/or rating of external fuse	(/)()()			
7 Fittings/Connectors - check all fittings/connectors	(/)()()			
PART 5 PREVENTIVE MAINTENANCE	TASKS		THE WAY SAID	THE REAL PROPERTY.
ick (v) where appropriate	THE CONTRACT OF		A STATE OF	
	DONE NOT NA			Mark Control
Clean/Inspect the Extenor & Interior	(/)()()			
2 Lubricate	()()(/)			
		"If you have	is, NA is defined as NOT AP ticked 'NOT DONE', then ju Whichever Applicable	PLICABLE istify in Part 8

V.	3	KEMENTERIAN KESIHATAN MALAYSIA MEET Planned Preventive Maintenance Checklist Mixers BE CODE: 15-590					CHECKLIST NO.CL-105-000 REV.006
ORK ORDER		W0366177					
5000000	TITATIVE TAS	KS				AND DESCRIPTION OF THE PARTY OF	
No No	propriate		Units /	Set	Measured		PASS FAIL NA
		Description	UOM	Values	Values	Limit/Tolerance	PASS FAIL NO
NOT A	PPLICABLE						
111111							
				/			
	7	NA -					
				1			
ART 7 ELEC			TI-IN'L	4,195			Andread
	FETY TEST,	attach report)					
ck (V) where	appropriate						
Stand				Result			and the state
ART 8 NOTE		EC 60601	353		PASS	FAIL [NA NA
		N A					
WORK OR		ORRECTIVE MAINTENANCE REQUIRED			FUNCTION	NEXT PP	NOT FUNCTIONING M DATE JULY 2019
COMPLETED B	Y	D SACVAN BIN ROSLAN pmedical Technician Pedical Solution Sdn. Bhd	is function	ng to the	intended purp	ose.	

Test Setup

DUT Information

Operator ID:

Calibration Tech : MOHANA
Calibration Date : 08/24/2018

Firmware Version: 2.08.01

Serial Number : 3218071 Date & Time : 07/10/2018&10.20AM

JOB Name :

Equipment Number: JHR008642

Serial Number : Manufacturer :

Model: Location:

KK SUNGAI RENGIT

Other:

Template Information

Template Name : MIXERS
Pause after Power ON NO

Power ON delay: 2
Test Speed: NORMAL
Halt on Test Failure: YES
Include Time: YES
Insulation Resistance \ 500V
Multi Enclosure Test: NO

Standard : IEC60601-1-3rd Ed

Pause before Power O NO
Power OFF delay: 0
Test Mode: AUTO
Multi PE Test: NO
Multi Resstore: WORST/LAST

Reverse Polarity: YES
Classification:

PLC Configuration-Applied part setup

AP Name AP Type AP Num

ESA615 Test Results

Test Name	Value	High Limits Low Limits	Status
Protective Earth Resistance	0.065 Ohn	0.2 -	Р
Insulation Resistance			P
	999 MOhr		P
Mains to Non-Earth Accessible Conductive Pa	999 MOhr		P
Mains Voltage			P
Live to Neutral	228.4 V		P
	6.4 V		P
Live to Earth	233.6 V		P
	0.0 A		P
Earth Leakage Current			P
Normal Condition	16.2 uA-O	5000 -	Р
	24.4 uA-O	10000 -	P
	33.9 uA-O	10000 -	P
	27.5 uA-O	5000 -	P
Istimal condition increases			P
Enclosure Leakage Current	0.7 uA-OP	100 -	P
Hollina Condition	0.8 uA-OP	500 -	P
Open carti	0.8 uA-OP	500 -	P
Open read a	0.7 uA-OP	500 -	P
Open weddar neverses mans		100 -	D
Tabillar Condition Transfer Manager	0.6 uA-OP		-
Open Earth- Reversed Mains	0.8 uA-OP	500 -	P

