Form B03 Scheduled Maintenance Work Order





Format Ref: - QMS/TSD-022 Rev.01

| Work Order No. | PWO365250 | Schedule Month June 2018 | | | | | | | |
|--|--|---|---|--|--|--|--|--|--|
| Work Order Date | 01/06/2018 | Completed Date | 2016 118 | | | | | | |
| Clinic Name | Klinik Pergigian Di Klinik Kesihatan Sur | Clinic Code | JHR549 | | | | | | |
| BE No. | JHR023414 | Distict | LEDANG | | | | | | |
| BE Category | STERILIZING UNITS, PORTABLE | VO Assigned to Rabeah | | | | | | | |
| Ownership | Existing Equipment | Purchase | New | | | | | | |
| BE Condition | ✓ Active | BER Proposed | | | | | | | |
| Work Order Type | Preventive Maintenance (PM) | Third Party Calibration (TPC) | | | | | | | |
| work Order Type | Routine Inspection (RI) | Statutory Certificat | ion (SC) | | | | | | |
| Reschedule Date | | | | | | | | | |
| E Third Party Calibration | n / Statutory Certification Details | | | | | | | | |
| Company Name | 46 | Cal / Cert Date | rla | | | | | | |
| Contact Number | NA | Cal / Cert Expiry Date | NIA | | | | | | |
| Action Taken PM / RI job done as per checklist. Unit tested functioning good & ready to use. Manufacturer: SCRCAN. Corrective Maintenance / Breakdown BE Sticker Availability: Yes / NA Remarks: ppm sore as perchecklist | | | | | | | | | |
| Schedule Maintenance Ex | recution Details | | | | | | | | |
| SI No | QMS Engineer / Technician Name | Date | Start Time End Time | | | | | | |
| 1) | Roberh | 20/6/18 | 10 02 11. 42 | | | | | | |
| | | | | | | | | | |
| Customer Remarks | | | | | | | | | |
| Engineer / Technician Signa Name RABEAH Date | 24 | Customer Signature Name Designation Date Seal | E 1481. S KNOLOGI ZERGIGIAN U29 PERGIGIAN : SEMIATI | | | | | | |

For Internal Use

First Verification

QMS Circle Incharge

Biomedical Engineering
Quantum Medical Solutions
HyP: 012-3967638

Final Verification QMS State Incharge



KEMENTERIAN KESIHATAN MALAYSIA

MEET Planned Preventive Maintenance Checklist Sterlizing units, Portable BE CODE: DE-031

CHECKLIST NO:CL-147-000 REV.001

| PART 1 | ASSET DETAILS | | | | | | | | | | | | |
|----------------------|--|--------------|-------------|-------------|---|-------|-------------------|----------------|--|-------|----------|--------|-------|
| WORK C | ORDER NO pw 0 30 | 75 26 | 0 | | | | | | ASSET NO | > 31 | 1202 | 341 | 4 |
| MANUFA | CTURER > Scies | n | | | | | | | MODEL | ► SP | ati m | 200 | 00 |
| FREQUE | NCY ► 3 MONTI | HLY (|) 6 N | IONTHL | Y (/) | | 12 MONTHLY | () | PPM HOURS | ► 1 H | IOUR | | |
| PART 2 | SPECIAL PRECAUTION | | | | | | | | | | | | |
| If there is | evidence of body fluid contan | nination, s | submit the | device fo | or cleanin | g and | I decontaminatio | n before ins | pecting it. | | | | |
| Wear app | ropriate Personnel Protection | n Equipme | ent (PPE) d | luring wo | ork. | | | | | | | | |
| Wear gro | unded electrostatic wristband | when har | ndling PCB | or elect | ronic con | npone | ents. | | | | | | |
| | he safety procedure for addition | | | | | | | nes. | | | | | |
| | e the test equipment used are | | | 3 | , | | · · | | | | | | |
| | TEST APPARATUS | - duly outli | oratea. | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | where appropriate | | | | | | | | | 1 | 0411004 | TION D | |
| NO | ASSET NO | | | DESC | RIPTION | 74 | | | ERIAL NO | | CALIBRA | ION D | UE ON |
| 1 | 1EES A 0025 | DIGITAL | TEMPERA | ATURE I | PROBE | | | 29520 | 020165 | | 00. | | 2018 |
| 2 | TEESA 0.338 | DIGITAL | PRESSU | RE METI | ER | | 2 | | H-315540 | 5 | 8/1 | 1/2 | C18 |
| | | | 1 St | _ | | 4 | MA PARTIES | | | | | | |
| | | 1 | 70 | | | | | | | | | | |
| PART 4 | QUALITATIVE TASKS | | | | | | | | | | | | |
| entrological control | | | | | | Т | | | | | | | |
| lick (V) | where appropriate | | PASS | FAIL | NA | | | | | Р | ASS F | AIL | NA |
| 1 Cha | ssis - verify physical integrity, | | (/) | | (|) 9 | Over pressure | cut of valve | - Verify physical | (| 1) (|) | () |
| | nliness and condition | | | 7 3 | X | | integrity | | | 2 | / . | | |
| 2 Bow | er Cord - verify proper insulat | tion | (.) | () | (|) 10 | Door lock - Ve | | integrity | (| 1)(|) | () |
| | integrity | lion | (/) | () | | / 10 | Door look vo | | | 1 | , (| , | ` ' |
| | | | 7 | , , | | \ | Page gook at V | Code physics | l intogrity | 1 | 111 |) | () |
| | in Relief - verify physical integ oth ends of line cord | grity | (/) | () | (| ' ' | Boor gasket V | erily priysica | ir integrity | / | /) (| , | , |
| 4 Fittir | ngs/ Connectors - check all | | (/) | () | (|) 12 | Check water to | ank leak | | (| /)(|) | () |
| 33525535 | gs/connectors | | (2) | , , | | | E 10000 0000 0 | | | | | i. | |
| 5 Con | trols/Switches - verify proper | | (/) | () | (|) 13 | Check drain v | alve -Physica | al integrity | (| /) (|) | () |
| | ation of controls | | 1 | | | | | | | 1 | | | |
| 6 India | cators/ Displays - verify prope | r | (/) | () | (|) 14 | Check label | | | (| /) (|) | () |
| | nination and operation | | 7 | | | | | | | / | | | |
| 7 Che | ck fuse, circuit breaker | | (/) | () | (|) 15 | | Resevoir/Bo | ttle - clean & veri | fy (| 1) (|) | () |
| 8 Hea | ter - verify physical Integrity | | (/) | () | (| , | integrity | | | | | | |
| * | | | 1 | ` ' | • | | | | | | | | |
| | mber/Cassette - verify physic grity (scalling, rusting, pitting o | | (1) | | ST SAN ASSAULT DE STATE DE S | | | | | | | | |
| PART 5 | PREVENTIVE MAINTENAN | ICE TASH | (S | | | | 15611 | | | | | | |
| Tick (√) | where appropriate | | | | | | | | | | | | |
| | | | DONE | NOT DONE | NA | | | | | D | | ONE | NA |
| | | | | ** | | | e geograpia er er | is some | | 200 | 700 1740 | ** | , |
| | an exterior and interior of the pment | | (/) | (|) (|) 4 | Lubricate all n | noving parts | | (|) (|) | () |
| 2 Che | ek / replace gasket *** | | (/) | (|) (|) | | | | | | | |
| | on, replace gashet | | , , | | , \ | No | tes: | | | | | | |
| 3 Che | ck/ clean solenoids | | () | (|) (/ | 7) | ** If you | have ticked | is defined as NOT I 'NOT DONE', the | | | | |



KEMENTERIAN KESIHATAN MALAYSIA

MEET Planned Preventive Maintenance Checklist Sterlizing units, Portable BE CODE : DE-031

pw0 365250 WORK Order No

CHECKLIST NO:CL-147-000 REV.001

| No | Description | Checked | Sen | /ice/ | Repl | laced | N Appli | ot cable | No | Description | Checked | Service/C ean | Replace | Not Applicable |
|----|--|---------|-----|-------|------|-------|------------|-------------|----|------------------------------------|---------|------------------|---------|-------------------|
| 1 | Fuses | (_) | (|) | (|) | (|) | 16 | Chamber Guard Seal (if applicable) | (/) | () | () | () |
| 2 | Main Control Board | (/) | (|) | (|) | (|) | 17 | Solid State Relay (if applicable) | () | () | () | (/) |
| 3 | Fan Running Rear & Side (if applicable) | (//) | (|) | (|) | (|) | 18 | Thermostat Assembly | () | () | () | (/) |
| 4 | Clean Water Resevoir | (-) | (|) | (|) | (|) | 19 | Thermal Printer (if applicable) | () | () | () | (/) |
| 5 | Electric Door Lock | (/) | (|) | (|) | (|) | 20 | Vacuum Pump (if applicable) | | () | () | () |
| 6 | Pressure Door Lock | (//) | (|) | (|) | (|) | 21 | Temperature Sensor | (/) | () | () | () |
| 7 | Discharge Door Lock | (/) | (|) | (|) | (|) | 22 | Filters | (/) | () | () | () |
| 8 | Pressure Transducer | (-) | (|) | (|) | (|) | | | | | | |
| 9 | Pressure Gauge | (/) | (|) | (|) | (|) | | | | | | |
| 10 | Safety Valve | 1 | (|) | (|) | (|) | | | | | | |
| 11 | Air Valve/Steam Solenoid Valve (if applicable) | (/) | (|) | (|) | (|) | | | | | | |
| 12 | Discharge Valve | 1 | (|) | (|) | (|) | | | | | | |
| 13 | Feed Water Valve (if applicable) | | (|) | (|) | (|) | | | | | | |
| 14 | Heating Element | (/) | (|) | (|) | (|) | | | | | | |
| 15 | Door Gasket/Cessette Seal | (1) | (|) | (|) | (|) | | | | | | |
| | | | | | | | | | | | | | | |
| DA | T. T. Walder Brand | | | | | | | | | | | | | |
| PA | Technician Remarks | | | | | | | | | | | | - | |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |
| | | | | | | | | _ 1 | UA | <i>e</i> ~ | | | | |
| | | | | | | | / | | | | | | | |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |
| | | | / | / | | | | | | | | | | |
| | | / | _ | _ | | | | | | | | | | |



KEMENTERIAN KESIHATAN MALAYSIA

MEET Planned Preventive Maintenance Checklist Sterlizing units, Portable BE CODE : DE-031

CHECKLIST NO:CL-147-000 REV.001

WORK ORDER NO ▶

Pw0365250

| PART 8 | QUANTITATIVE TASKS | | | | | | | |
|----------|--|------------------|---------------|--------------------|------------------------|--------------------------------|--------|-------------|
| Tick (√) | where appropriate | | | | | | | |
| No | Description | Units / UOM | Set Values | Measured Values | Limit/Tolerance | PASS | FAIL | NA |
| 1 | Temperature reading | °C | 13 4°C | 135.4 | 134-137 121-124 | () | () | () |
| 2 | Pressure reading - non absolute pressure reading | bar | | | 2.03-2.32 1.04-1.24 | (1) | () | () |
| 3 | Electrical Supply Voltage | V | 2450 | refer to EST | Refer to Nameplate | 1 | () | () |
| 4 | Electrical Power/Consumption | kW | | refer to EST | Refer to Nameplate | 1 | () | () |
| | | | | | | 12 | | |
| | , | | | | | | | |
| PART 9 | ELECTRICAL SAFETY TEST | | | | | | | |
| PART 10 | NOTES | N | A | | | | | |
| VA/C | CORRECTIVE MAINTENANCE REQUIRE | Pwo 3 | - | FUNCTIONII | | NOT FUNCTION | | 2019, |
| VVC | DRK ORDER NO ► | | | | | HEALTHINDAI | - " := | |
| | s been performed in accordance to the checklist and the equipm | nent is function | ning to the | e intended pur | pose. WITNESSED BY: | AZLEE JURUTEKNO KLINIK PERG | | RGIGIAN U2S |
| DATE : | | | | | DATE: | NLININ PERC | 20/0 | [18 |

Date: 20/6/2018

Test Setup

DUT Information

Operator ID:

Calibration Tech:

NADIA

Calibration Date:

25/8/2018

Firmware Version: Serial Number:

2.08.01

Date & Time:

3246911

20/06/2018 & 10:45 A.M

Location:

Serial Number: Manufacturer:

SCICAN

Equipment Number: JHR 023414

STATIM 2000E **KP SUNGAI MATI**

110311F00004

Other:

Model:

JOB Name:

Template Information

Template Name:

62353-Alt.STERILIZING

Standard:

IEC62353-Direct

Pause after Power ON: NO

Power ON delay:

2

NORMAL

Halt on Test Failure:

YES

Include Time:

Test Speed:

YES

Insulation Resistance \ 500V

Multi Enclosure Test: NO

0

Pause before Power O NO Power OFF delay:

Test Mode:

AUTO

Multi PE Test:

NO

Multi Resstore:

WORST/LAST

Reverse Polarity: Classification:

YES

PLC Configuration-Applied part setup

AP Name AP Type

AP Num

ESA615 Test Results

| Test Name | Value | High l | Limits Low Lim | its Status |
|-----------------------------|----------|--------|-----------------|------------|
| Protective Earth Resistance | 0.24 Ohm | | 0.3 - | Р |
| Insulation Resistance | | | | Р |
| Mains to Protective Earth | 75.3 MOh | 1- | ca . | Р |
| Mains Voltage | | | | Р |
| Live to Neutral | 244.8 V | = | e= | Р |
| Neutral to Earth | 2.2 V | - | 0. | Р |
| Live to Earth | 241.8V | - | - | Р |
| Equipment Current | 0.2 A | - | () = | Р |
| Direct Equipment Leakage | | | | Р |
| Open Earth | 0.9 uA | | 500 - | Р |
| Open Earth- Reversed Mains | 0.7 uA | | 500 - | Р |