Fc'

Scheduled Maintenance Work Order





Format Ref: - QMS/TSD-022 Rev.01

Work Order No.	PWO365727	Schedu	le Month	June 2018				
Work Order Date	01/06/2018	Comple	ted Date	25/6/2018				
Clinic Name	Klinik Pergigian Selkolah Menengah Le	Clinic C	ode	JHR556				
BE No.	JHR002394	Distict		LEDANG				
BE Category	Sterilizing Units, Portable	WO Ass	igned to	Rabeah.				
Ownership	✓ Existing Equipment		Purchase	New				
BE Condition	✓ Active		BER Proposed					
Work Order Type	✓ Preventive Maintenance (PM)		Third Party Calibration (TPC)					
Work Order Type	Routine Inspection (RI)		Statutory Certificati	ion (SC)				
Reschedule Date								
BE Third Party Calibratio	n / Statutory Certification Details							
Company Name	210	Cal / Ce	CAT 1987 OF TOTAL AND A TOTAL	rb rla				
Contact Number Action Taken	A (3	Cal / Ce	ert Expiry Date	W 101				
PM / RI job dor Corrective Main BE Sticker Ava Remarks:	ilability: Yes / NA	od & read	y to use.	Manufacturer: S Modal: Storing Serial No:				
Schedule Maintenance E	xecution Details							
SI No	QMS Engineer / Technician Name		Date	Start Time	End Time			
1)	Robean		28/6/18	10-00	11:00			
Customer Remarks								
Customer Hemarks								
Engineer / Technician Signa	ature	Custome	er Signature					
Name RABEAH		Name	sha	effet				
Date		Designa Date	tion	I SARINA ALI				
>	1	Seal	PEGAW	AI PERGIGIAN				
For Internal Lice			M	DC 3928				

For Internal Use

First Verification

QMS Circle Incharge J SHAIPUDHE EIN SHAI Bion Edical Engineering Clean and Medical Solutions H/P: 012-3967638

Final Verification QMS State Incharge



KEMENTERIAN KESIHATAN MALAYSIA

MEET Planned Preventive Maintenance Checklist Sterlizing units, Portable BE CODE : DE-031

CHECKLIST NO:CL-147-000 REV.001

PART	1 ASSET DETAILS	44.65						45.00	
WORK	ORDER NO P	W0365	727				ASSET NO	> JAR	002394
MANUF	ACTURER > Sc	ican					MODEL	- Stat	m 2000 E
FREQU		MONTHLY	() 6 MO	NTHLY (/)	12 MONTHLY	() PPM HOURS	b 1 HOU	R
PART	2 SPECIAL PRECAUT	rion							
If there	is evidence of body fluid	contamination	on, submit the dev	ice for clea	aning a	and decontamination	n before inspecting it.		
Wear a	opropriate Personnel Pr	otection Equi	ipment (PPE) duri	ng work.					
Wear gr	ounded electrostatic wr	istband wher	handling PCB or	electronic	compo	onents.			
Refer to	the safety procedure for	or additional p	precautions and gu	uidance as	per ma	anufacturer guidelir	nes.		
	ure the test equipment u	ised are duly	calibrated.						
	TEST APPARATUS								
) where appropriate			ESCRIPTI	ION		SERIAL NO	CAL	IBRATION DUE ON
NO	ASSET NO)	1475				Marina Cor Service		
1).	TEESAO(05)		TAL TEMPERATI		3E		3246911		5/8/2018
ی)	TETTA 093	8 DIGI	TAL PRESSURE	METER			#315545	8	11/2018
				- 111					
PART	QUALITATIVE TASE	(S							
Tick (√) where appropriate				9,63				
1 Ch	assis - verify physical ir	ntearity .	PASS F	AIL N	IA)	9 Over pressure	cut of valve - Verify physica	PASS	FAIL NA
	anliness and condition	negrity,		, (integrity	out of valve - verily physica	. (/	, () ()
	wer Cord - verify proper d integrity	insulation	(/) () ()	10 Door lock - Ve	rify physical integrity	() () (/)
	ain Relief - verify physic both ends of line cord	cal integrity	(/) () ()	11 Door gasket V	erify physical integrity	()()()
	tings/ Connectors - chec ngs/connectors	ck all	(() () ()	12 Check water to	nk leak	(/	()()()
	ntrols/Switches - verify eration of controls	proper	(/) () ()	13 Check drain va	alve -Physical integrity	()()(/)
	licators/ Displays - verify mination and operation	y proper	(/) () ()	14 Check label		(/) () ()
7 Ch	eck fuse, circuit breake	r	(1)) ()	15 Waste Water I	Resevoir/Bottle - clean & ver	rify (/)()()
8 He	ater - verify physical Into	egrity	(/) () ()				
	amber/Cassette verify egrity (scalling, rusting,								
PART!	PREVENTIVE MAIN	TENANCE T	ASKS						
Tick (√,) where appropriate		5355						NOT
				TOI NE N	IA			DONE	NOT DONE NA
	ean exterior and interior	of the	(5)) ()	4 Lubricate all m	oving parts	()()(/)
2 Ch	eck / replace gasket ***		(/)() ()	lotes:			
3 Ch	eck/ clean solenoids		()() (** If you	Parts, NA is defined as NO have ticked 'NOT DONE', the Whichever Applicable		



KEMENTERIAN KESIHATAN MALAYSIA

MEET Planned Preventive Maintenance Checklist

Sterlizing units, Portable

BE CODE: DE-031

CHECKLIST NO:CL-147-000 REV.001

WORK Order No

No	Description	Checked	Serv		Repl	aced	Not Applicable	No	Description	Checked	Service/C	Replaced	Not Applicab
1	Fuses	(6	()	()	()	16	Chamber Guard Seal (if applicable)	(1	()	()	()
2	Main Control Board	(/)	()	()	()	17	Solid State Relay (if applicable)	()	()	()	(/)
3	Fan Running Rear & Side (if applicable)	()	()	()	1	18	Thermostat Assembly		()	()	()
4	Clean Water Resevoir	()	(2	1	()	()	19	Thermal Printer (if applicable)	()	()	()	(/)
5	Electric Door Lock	()	()	()	(/)	20	Vacuum Pump (if applicable)	()	()	()	(/)
6	Pressure Door Lock	()	()	()	(6)	21	Temperature Sensor	1	()	()	()
7	Discharge Door Lock	()	()	()	(1)	22	Filters	1	()	()	()
8	Pressure Transducer	()	()	()	(6)			L			
9	Pressure Gauge	()	()	()	(/)						
10	Safety Valve	()	()	()	(/)						
11	Air Valve/Steam Solenoid Valve (if applicable)	()	()	()	()						
2	Discharge Valve	(/)	()	()	()						
3	Feed Water Valve (if applicable)		()	()	()						
14	Heating Element	(/)	()	()	()						
15	Door Gasket/Cessette Seal	(/)	()	()	()						
PA	RT 7 Technician Remarks												
									i i				
							N	A					
							/						
					,								
			_6	/									



KEMENTERIAN KESIHATAN MALAYSIA

MEET Planned Preventive Maintenance Checklist
Sterlizing units, Portable
BE CODE: DE-031

Maintenance Checklist cHECKLIST NO:CL-147-000 rev.001

WORK ORDER NO ▶

PART 8	QUANTITATIVE TASKS								
Fick (√)	where appropriate								
No	Description	Units / UOM	Set Values	Measured Values	Limit/Tolerance	PASS	FAIL	N.	A
1	Temperature reading	°C	1340	13460	134-137 121-124	()	()	()
2	Pressure reading - non absolute pressure reading	bar	2.2	2.0	2.03-2.32 1.04-1.24	>	()	()
3	Electrical Supply Voltage	V		refer to EST	Refer to Nameplate	/	()	()
4	Electrical Power/Consumption	kW		refer to EST	Refer to Nameplate	(/)	()	()
	ICAL SAFETY TEST, (attach report) (In accordance to IEC 69601) PASS FAIL NOTES		NA A	A					
	CORRECTIVE MAINTENANCE REQUIRED			FUNCTIONII	NG	NOT FUNCTION	IING		
wo	RK ORDER NO ▶					NEXT PPM DAT	E ►	6/2	019
	been performed in accordance to the checklist and the equipment	is function	ning to the	e intended pur	pose. WITNESSED BY:	2	2		
DATE :	\overline{A}				DATE:				

Date: 25/6/2018

Test Setup

DUT Information

Operator ID:

Calibration Tech:

NADIA

Calibration Date:

25/8/2018

Firmware Version:

2.08.01

Serial Number: Date & Time:

3246911

25/06/2018 & 10:00 A.M

JOB Name:

Equipment Number: JHR 002394

Serial Number:

110309G00036

Manufacturer:

SCICAN

Model:

STATIM 2000E

Location:

Other:

KP SEKOLAH MENENGA

Template Information

Template Name:

62353-Alt.STERILIZING

Standard:

IEC62353-Direct

Pause after Power ON: NO

Power ON delay:

2

Power OFF delay:

Pause before Power O NO

0

Test Speed:

NORMAL

Test Mode:

AUTO

Halt on Test Failure:

YES

Multi PE Test:

NO

Include Time:

YES

Multi Resstore: Reverse Polarity: WORST/LAST

Insulation Resistance \ 500V

YES

Multi Enclosure Test: NO

Classification:

PLC Configuration-Applied part setup

AP Name AP Type

AP Num

ESA615 Test Results

Test Name	Value	High Limits Low Limits State	us
Protective Earth Resistance	0.26 Ohm	0.3 - P	
Insulation Resistance		Р	
Mains to Protective Earth	74.3 MOh	nr - P	
Mains Voltage		Р	
Live to Neutral	237.3 V	P	
Neutral to Earth	2.6 V	P	
Live to Earth	239.8 V	P	
Equipment Current	0.3 A	P	
Direct Equipment Leakage		Р	
Open Earth	39.2 uA	500 - P	
Open Earth- Reversed Mains	56.4 uA	500 - P	
•			