

KEMENTERIAN KESIHATAN MALAYSIA

MEET Planned Preventive Maintenance Checklist

Amaigamators

CHECKLIST NO:CL-002-000 REV.000

BE CODE: 10-082 WORK ORDER NO . PART 6 QUANTITATIVE TASKS Tick (√) where appropriate Units / Description Set Measured Limit/Tolerance PASS FAIL MOU Values NA Values PART F ELECTRICAL SAFETY TEST ELECTRICAL SAFETY TEST, (attach report) Tick (v) where appropriate Standard use : Result: [EC 60601 [IEC 61010 [IEC 62353 PASS FAIL KALWE NOTES - proposed to BER. CORRECTIVE MAINTENANCE REQUIRED FUNCTIONING NOT FUNCTIONING WORK ORDER NO ▶ NEXT PPM DATE ► ____ PPM has been performed in accordance to the checklist and the equipment is functioning to the intended purpose. COMPLETED BY: FOSTER ANAK ENGKASAN QUANTUM BIOMEDICAL ENGINEERING YUGHAN AK LARRY RENBEN JURUTERAPI PERGIGIAN U32 KUP KUCHING SARAWAK.