## Form B03

## Scheduled Maintenance Work Order



Format Ref. -QMS/TSD-003 Rev. 00

Work Order No	fw6339600	Scheduled Month		huary 2018
Work Order Date	01/01/2018	Completed Date	د د	11/2018
Clinic Name	Klinik Kesihatan Jalan Oya	Clinic Code	SWK16	
BE No	Smk004810	District	SIBU	-
Be Category	Op ht healm croopes	WO Assigned to	SIUBME	E1
Ownership	Existing Equipment	MEET Equipme	nt	
BE Condition	Under Warranty	BER Proposed		
	Preventive Maintenance (PM)	Third Party Cali	bration (TPC)	
Work Order Type	Routine Inspection (RI)	Statutory Certif		
BE Third Party Calib	ration / Statutory Certification Details			
mpany Name		Cal / Cert Date		ala
Company Number	16.	Cal / Cert Expiry Date		<u> </u>
Schedule Maintenar	ice Execution Details			
ICINIA IONACESA		Date	Start Time	End Time
	ineer, / Technician Name	Date	Start Time	End Time
SI NO QMS Eng		Date	Start Time 940	End Time
	ineer / Technician Name (µld•	<del> </del>		
670	ineer / Technician Name (µld•	<del> </del>		
	ineer / Technician Name (µld•	<del> </del>		
670	ineer/Technician Name (wed • (New let	<del> </del>		
Customer Remarks  Engineer / Technicia	ineer / Technician Name  (white the control of the	32/1/2018		
Customer Remarks	ineer / Technician Name  (wld •  (New let  Dignature  WEDNISLEY) JIMMY  PROMEDICAL TECH	Customer Signature Name Designation	SAK AK KUJAT	10.06
Customer Remarks  Engineer / Technicial Name Date	ineer / Technician Name  (publication)  Signature  WEDNISLEYJI JIMMY  BIOMEDICAL TECH OUANTUM MEDICAL SOLUTIONS	Customer Signature Name Designation	SAK AK KUJAT ai Perubatan U32	
Customer Remarks  Engineer / Technicial Name Date	ineer / Technician Name  (wld •  (New let  Dignature  WEDNISLEY) JIMMY  PROMEDICAL TECH	Customer Signature Name Designation Date Pen Pagaw	SAK AK KUJAT ai Perubatan U32	10.06

First Verification

QMS Circle Incharge

James Bo Sr. Blomedical Engineer
Quantum Medical Solutions

Final Verification

QMS State Incharge



## Quantum Medical Solutions Sdn Bhd

BEMS Planned Preventive Maintenance Checklist
Ophthalmoscones

CHECKLIST NO: CL-104 REV.000

eran e e					-	halmoso 2006 . 12	•			İ	•	REV.	000
PART 1 ASSET D	ETAILS							43-3		1.27			100 mm
WORK ORDER NO	, - for	033960	ÖÖ						ASSET NO	► 8	wki	004	810
MANUFACTURER	<b>&gt;</b>								MODEL	<b>&gt;</b>			
FREQUENCY			) 6	MONTHLY	( )	12	MONTHLY	(سس)	PPM HOURS	} ▶	<b>O</b> .	20	
PARTZ SPECIAL  If there is evidence of											71 (1 a) 2 (4)	1 7 A	<u> </u>
Wear appropriate Per Wear grounded electr Refer to the safety pro Wake sure the test equ	sonnel Protect ostatic wristbar ocedure for add	ion Equipment nd when handi itional precaut	: (PPE) d ing PCB ions and	uring work. or electroni	c comp	onents,							
PARTS TEST APPA						- 15				10. 10		7 11 12 Va. 1	
Tck ( v ) where appropr		T											
NO ASS	ET NO			DESCRIPT	ION			S	SERIAL NO		CALIBI	1OITAF	1 DUE O
		ELECTRICA	L SAFET	TY ANALYZ	ER			UD					
			<del></del> -										
			·	<del></del>		<del></del>							
ARTA QUALITATIV	E TASKS		1 5 t W		<del>- ;</del>			<u> </u>					<u> </u>
Chassis - verify phy cleanliness and con			.SS F	'AIL N <sub>e</sub>		' Circui exterr fuse	it Breaker/ f nal circuit br	Fuse - veriñ eaker and/	y integrity of or rating of extern	,	\ss ) (	FAIL	NA ( /
Mount/ Fasteners - v	verify physical i	ntegrity (	) (	) (	) 8	Fitting	s/Connectors	ors - check s	all	(/	(	)	( )
Cables - verify integr	fity	(	) (	) (	) 9	Contro contro	ils/Switches Is	s - verify pro	oper operation of	( /	<b>'</b> )(	)	( )
AC Plug - verify integ	ırity	(	) (	) ( /	) 10	Indicat operat	ors - verify <sub>l</sub> ion	oroper illun	nination and	(	) (	)	( / )
Power Cord - verify p integrity	roper insulation	nand (	) (	) ( /	) 11	Check	Charger - v	erify prope	r operation	(	) (	)	( سر )
Strain Relief - verify p both ends of line cord	ohysical integrit	yat (	) (.	) ( /	) 12	Check	lamp holder	-		( /	-) (	)	( )
75 PREVENTIVE M	AINTENANCE	TASKS		:			a Areas					<del>.,</del>	e to tuti
v ) where appropriate							<u> </u>			· · ·	<u>, i </u>	<u>- 236</u>	<u> </u>
		DONE	NOT NOD E							DON		OT ONE	NA
llean exterior and inte quipment	rior of the	(/	) (	) (	) 4	Check/r	eplace batte	ery		(/	) (	) (	)
lean lens dial		(/	) (	) (	5	Check /	replace lam	ıp		( -	) (	) (	)
lean filters			) (	) (	Not	**	For all Part If you have Choose Wh	ticked 'NO	fined as NOT AP IT DONE', then ju	PLICAE	3LE Part 8		

	D.
наитени	par no snormle

## Quantum Medical Solutions Sdn Bhd

1	velar facel			ilmoscop DE : 12-815				REV.000
WORK ORDER NO	· Pw033960			<i>IDC</i> .   2*01.				
PART 6 QUANTITA		and the second second			1, 4, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,			
Tick ( v ) where approp		<u> </u>					<u> </u>	· · · · · · · · · · · · · · · · · · ·
No	Description		Units / UOM	Set Values	Measured Values	Limit/Tolerance	PASS	FAIL NA
			DOW.	741463	Va.u			
			-				<u> </u>	
						1		
						<u> </u>		
						<u> </u>		
				1				
ART7 ELECTRICA	L SAFETY TEST		e de la companya de La companya de la co					
ECTRICAL SAFETY	/ TEST, (attach report)	* *						
(In accordance t	o IEC 80801)							
	PASS	FAIL	NA	A.				
-		_	1					
RT8 NOTES					1.82			
	und	finati oni	mg (	األاله	•			•
,								
,								
	CORRECTIVE MAINTEN			Z F	UNCTIONING	· .	NOT FUNCTIONIN	G
				☑ F				G Jan (C
WORK ORDER NO				<b>☑</b> F			NOT FUNCTIONIN NEXT PPM DATE	G Jan (C
	) ▶	IANCE REQUIRED			UNCTIONING			G Jan (
A has been performe		IANCE REQUIRED	is functioning		UNCTIONING			Jun (°
A has been performe	d in accordance to the checklis	NANCE REQUIRED			UNCTIONING			G Jan (C
	d in accordance to the checklis	IANCE REQUIRED	ИММҮ		UNCTIONING		NEXT PPM DATE	Jan 1º