

## KEMENTERIAN KESIHATAN MALAYSIA

MEET Planned Preventive Maintenance Checklist

Vibrators

BE CODE: 14-369

CHECKLIST NO:CL-166-000 REV.000

lck(V)	миеге артат											
No	1 .		scription		Units /	Set	Measured	Limit	t/Tolerance		PASS FAIL	NΛ
	NOT APPLI				NOM	Values	Values					
	NOT AFFER	DADLE:						ļ 		·		<del></del> .
		<u></u>	· · · · · · · · · · · · · · · · · · ·									
·												
						j						
· · · · · · · · · · · · · · · · · · ·											<del>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</del>	
						· · · · · · i					·	
····				-							·····	
in the second of												
14.8 2.30		SAFETY TEST										
		TEST, (attach rep	ort)									
	where approp				,	3						
	Standard use					Result :	<b>□</b>		_			
		IEC 60601	IEC 61010	IEC 6235	53		Z PASS		FAIL	NA		
· la se Ce de	CIPTURE		And the contract of the contra								AND THE RESERVE AND THE PARTY OF THE PARTY O	
R1 8	NOTES Pp-	n do	ne.				. <u>11</u>					
1.8		n do	ne.									
<b>₹1.8</b>		n do	re.					The second secon				
<b>1.8</b>		n do	ene.									
<b>4.8</b>		n do	ne.									
18		n do	ene.									
		n do	e.									
		n do	re.									
		n do	ere.					The state of the s				
		n do	re.									
		n do	ene.					The state of the s				
		n do	ene.									
		n do	ene.					The state of the s				
		n do	ene.									
				FOLIBED		51	INCTIONING.	The second secon	N	OT ELINO	TIONING	
	- pp-		MAINTENANCE RE	EQUIRED		FL	INCTIONING		N:	OT FUNC	1	
				EQUIRED		✓ FL	UNCTIONING		NEXT PPM		1	roq
VORK	ORDER NO	CORRECTIVE	MAINTENANCE RE		nctioning to						1	Log
VORK	ORDER NO	CORRECTIVE			nctioning to						1	roq