DEV NUMBER:	ORIGINATOR:		DATE:	TE: RAIN BIRD		BUSINESS UNIT (SBU and PLANT) W/ PRIMARY DESIGN CONTR SHEET:						
DEV24-0439 Alonso Sánchez Soltero		Soltero	27DE24	DEVIATION FORM (DRAWING)		025	·>> CTR	>CTR		OF 1		
DMR# (IF APPLICAE	# (IF APPLICABLE): DEVIATION NEW 🔽									1 ()F I	
3388863 TYPE: EXTENSION ☐ OF DEV#:				FORM#2338	AFFECTED MFG	FFECTED MFG PLANTS (WHERE USED):						
TOP-LEVEL SKU P/N(S) AND MODEL NUMBER(S):			EFFECTIVITY DATE:	EXPIRATION DATE:	005 LAM 🔲	013S STL	025 OTY	✓	041 NOG	. 🗆		
Mini Maxi/Maxi Paw & Maxi Bird Models				30DE24	31MR25	008 BUY 🗌	019 AZU	028 TUC		047 TUC	; 🔲	
PROJECT NAME OR NO. (OPTIONAL):						013E EEX 🔲	020MX NMD	026 ELG		CHINA	. 🔲	
REASON FOR DEVIATION:								APPROVAL	APPROVALS (ALL REQUIRED):			
Some units of the MiniMaxi production from line 1 are reported to have a start-up pressure for forward and reverse tripping above the 20 psi MAX. The highest recorded pressure is at 25 psi								osi QUALITY M	QUALITY MGR. OR QUALITY ENG.			
for star-up, which is the lowest operating presure for all MiniMaxi/Paw & Maxi Bird models. This deviation look to allow for the maximum start-up pressure to be raised to 25 psi while a root								t Lu	Luis Gerarde Escalante			
cause analysis is done and a revalidation of the ultrasonic welding station for the arm and cover is done.								MANUFACT	MANUFACTURING ENGINEER			
RISK ASSESSMENT/ CORRECTIVE ACTION PLAN (NAMES & DATES)/ COMMITMENT:								Cir	Cinthia Yarely Espinoza			
Low, risk is minimal as all units function withing specification at 25 psi which is the minimum operating pressure for all MiniMaxi/Paw & MaxiBird product family.								PROD. ENG	PROD. ENG. MGR. OR PLANT ENG. MGF			
Corrective action plan:									Abdul Castillo			
- Root cause analysis for increased startup pressure 20MR25 Resp A. Sanchez Soltero - Revalidation of ops 190 (ultrasonic welding of arm and cover) to eliminate excess flash 10MR25 Resp C. Y. Espinoza								BUYER OR	BUYER OR BUYER/PLANNER			
- itevalidation of ops		and cover) to eliminate	excess liasii Tolvii (zo Nesp O. 1. Espilloza					Sergio	Herrera		
DRAWING NUMBER: DRAWING REVISION: DEVIATION		DEVIATION REVISION	SION: DRAWING TITLE/ PART DESCRIPTION:				VENDOR:	PLANT MAN	PLANT MANAGER			
175322 C C1			PROD SPEC - MINI/MAXI PAW				N/A	Jorge Borquez				
								SBU PROD	JCT MGF	R. OR SBU E	ENG. MGF	
								Marc (Gruslin; S	ergio Bermu	dez	
								OTHER:				
DESCRIPTION OF DEVIATION (IS/WAS CONDITION AND DRAWING ZONE FOR EACH PART NO. OR ATTACH REDLINE PRINTS):								QUALITY DIRECTOR (REQUIRED FOR				
WAS: • Operating Pressure All models:				mend; 70 psi, maximum (20 psi	marianum forward and cover		Te in	BAC	K-TO-BA	CK DEVIAT	iONS)	
				e sprinkler to operate with some								
								UT TANK CAMPUNG				
Posición de resorte (instruccion XEH09P02):								UNIT TANK SAMPLING:				
								START-UP PSI	Rot fwd	Rot back	4	
							11	17.22 15.25	6.75 5.5	4		
							11	13.03	6.94			
								13	14.88	7.19	-	
			Todos los modelos.	11				12	14.68	7.01	1	
IS:		(Posición A)						11	15.15	6.78	-	
Operating	Description	Δ11.	nodels:					14	15	6.87	-	
Operating	riessure		25-60 psi, <u>recommen</u>	d; 70 psi, maximum (25 psi. 1				14	16.25	6.44	1	
			is acceptable for the s	prinkler to operate with some	e degradation of rotation spe	ed between 60 and 7	70 psi	15	16.85	5.5	1	
								11	14.41	6.91		
Posicion de resorte:			POSICION SPRING. TODOS LOS MODELOS					15	15.81	5.35	1	
			(POSICIO	ON B)				14	15.34	6.67]	
								15	14.78	5.35		
						11	14.95	5.64]			
							14	16.37	5.71]		
								14	14.84	6.62]	

Sanchez, Alonso OTY 4306

From: Sanchez, Alonso OTY 4306

Sent: Friday, December 27, 2024 5:19 PM

To: Gruslin, Marc SOPT 6521; Bermudez, Sergio SOPT; Borquez, Jorge OTY 4398; Escalante,

Luis Gerardo OTY 4307; Espinoza, Cinthia Yarely OTY 4340; Herrera, Sergio OTY 4392;

Castillo, Abdul Ivan OTY 4332; Sanchez, Alonso OTY 4306

Subject: DEV24-0439 for approval

Attachments: DEV24-0439 Start-Up pressure 25psi.xls.xlsm

Importance: High

Tracking: Recipient Response

Gruslin, Marc SOPT 6521 Approve: 12/28/2024 8:48 AM
Bermudez, Sergio SOPT 24 HR RULE INVOKED

Borquez, Jorge OTY 4398 ADDED BELOW

Escalante, Luis Gerardo OTY 4307 Approve: 12/30/2024 8:38 AM
Espinoza, Cinthia Yarely OTY 4340 Approve: 1/2/2025 7:43 AM
Herrera, Sergio OTY 4392 Approve: 12/30/2024 8:08 AM
Castillo, Abdul Ivan OTY 4332 24 HR RULE INVOKED

Sanchez, Alonso OTY 4306 Approve: 12/27/2024 5:19 PM

Hello team,

Please review and submit resolution for attached deviaiton at your soonest convenience. If there are any questions of concerns feel free to contact me.

Reason for deviation:

Some units of the MiniMaxi production from line 1 are reported to have a start-up pressure for forward and reverse tripping above the 20 psi MAX. The highest recorded pressure is at 25 psi for star-up, which is the lowest operating pressure for all MiniMaxi/Paw & Maxi Bird models. This deviation look to allow for the maximum start-up pressure to be raised to 25 psi while a root cause analysis is done and a revalidation of the ultrasonic welding station for the arm and cover is done.

24hr rule will apply (weekend and holidays not included)

Kind regards and thanks

Sanchez, Alonso OTY 4306

From: Borquez, Jorge OTY 4398

Sent: Friday, December 27, 2024 10:51 PM

To: Sanchez, Alonso OTY 4306; Gruslin, Marc SOPT 6521; Bermudez, Sergio SOPT;

Escalante, Luis Gerardo OTY 4307; Espinoza, Cinthia Yarely OTY 4340; Herrera, Sergio

OTY 4392; Castillo, Abdul Ivan OTY 4332

Subject: Re: DEV24-0439 for approval

Approved.

From: Sanchez, Alonso OTY 4306 < AlSanchez@rainbird.com>

Sent: Friday, December 27, 2024 5:19 PM

To: Gruslin, Marc SOPT 6521 < MGruslin@rainbird.com>; Bermudez, Sergio SOPT < sbermudez@rainbird.com>;

Borquez, Jorge OTY 4398 < jborquez@rainbird.com >; Escalante, Luis Gerardo OTY 4307

<lescalante@rainbird.com>; Espinoza, Cinthia Yarely OTY 4340 <CiEspinoza@rainbird.com>; Herrera, Sergio OTY 4392 <SHerrera@rainbird.com>; Castillo, Abdul Ivan OTY 4332 <AbCastillo@rainbird.com>; Sanchez,

Alonso OTY 4306 < AlSanchez@rainbird.com>

Subject: DEV24-0439 for approval

Hello team,

Please review and submit resolution for attached deviaiton at your soonest convenience. If there are any questions of concerns feel free to contact me.

Reason for deviation:

Some units of the MiniMaxi production from line 1 are reported to have a start-up pressure for forward and reverse tripping above the 20 psi MAX. The highest recorded pressure is at 25 psi for star-up, which is the lowest operating pressure for all MiniMaxi/Paw & Maxi Bird models. This deviation look to allow for the maximum start-up pressure to be raised to 25 psi while a root cause analysis is done and a revalidation of the ultrasonic welding station for the arm and cover is done.

24hr rule will apply (weekend and holidays not included)

Kind regards and thanks