DEV NUMBER:	ORIGINATOR:		ATE:	RAIN BIRD		BUSINESS UNIT (SBU and PLANT) W/ PRIMARY DESIGN CONTRO SHEET:				
DEV25-0100	Xavier Vela Lopez 12-Mar-25				025 OTY >>:		>>> CTR	1 OF 1		
DMR# (IF APPLICABLE): DEVIATION NEW 🗸			DEVIATION FORM (DRAWING)					1 OF 1		
3411230 TYPE: EXTENSION ☐ OF DEV#: FORM#233813-01 REV: T AFFECTED MFG PLANTS (WHERE USED):										
TOP-LEVEL SKU P/N(S) AND MODEL NUMBER(S):			EFFECTIVITY DATE:	EXPIRATION DATE:	005 LAM 🔲	013S STL	025 OTY 🗹	041 NOG 🔲		
A84666				12-Mar-25	25-May-25	008 BUY 🔲	019 AZU 🔲	028 TUC 🔲	047 TUC 🔲	
PROJECT NAME OR NO. (OPTIONAL): 013E EEX 020MX NMD								026 ELG 🔲	CHINA	
REASON FOR DEVIATION:									APPROVALS (ALL REQUIRED):	
PGS is requesting guidance because they received an RMA for parts being too light in color. The root cause appears to be a shift in color perception when switching from ACT-1 to ACT-2. ACT-									QUALITY MGR. OR QUALITY ENG.	
1, which was used previously, caused tool sticking due to pigment residue, prompting the switch to ACT-2. Now, PGS is out of ACT-2 stock and needs approval to either: Allow PGS to ship material using ACT-1, which is slightly lighter in color but previously accepted.									Arturo Ramos / Ramiro Casas	
									NGINEER	
RISK ASSESSMENT/ CORRECTIVE ACTION PLAN (NAMES & DATES)/ COMMITMENT:									Cinthia Espinoza	
LOW: Material has been in used in the past and up to recently were made aware of the need to document this in a deviation. Action Plan:									PROD. ENG. MGR. OR PLANT ENG. MGR.	
									Paul Dibene	
- Procurement of ACT-2 and arrival of material to facility PGS 04/09/25									BUYER OR BUYER/PLANNER	
									Anais Perez / Efrain Iniguez	
DRAWING NUMBE	DRAWING NUMBER: DRAWING REVISION: DEVIATION REVISION: DRAWING T			TLE/ PART DESCRIPTION:			VENDOR:	PLANT MANAGER	PLANT MANAGER	
182994	Р	P P1 Deflector RVAN 24 Full Circle			PGS	Jorge	Jorge Borquez			
						SBU PRODUCT MGF	SBU PRODUCT MGR. OR SBU ENG. MGR.			
								Arianne	Williams	
								TOOLING ENGINEER	R (MOLDED PARTS ONLY)	
								Marce	lo Foglia	
								OTHER:		
DESCRIPTION OF DEVIATION (IS/WAS CONDITION AND DRAWING ZONE FOR EACH PART NO. OR ATTACH REDLINE PRINTS):								QUALITY DIRECTOR	(REQUIRED FOR	
									CK DEVIATIONS)	
WAS:										
MATERIAL: 93491 M90UV NATURAL WITH 4% FERCO FCC -94585-ACT-2 BURGUNDY. C										
REGRIND NOT PERMITTED.										
— REORIND NOTTERMITED.										
IS:										
MATERIAL: 93491 M90UV NATURAL WITH 4% FERCO FCC -94585- ACT-1 BURGUNDY. C										
MATERIAL: 93491 M90UV NATURAL WITH 4% FERCO FCC -94585- ACT-1 BURGUNDY. C REGRIND NOT PERMITTED.										
W KEGKIND NOT PEKMITTED.										

Vela, Xavier OTY 4377

From: Vela, Xavier OTY 4377

Sent: Wednesday, March 12, 2025 5:21 PM

To: Ramos, Arturo OTY2 4313; Casas, Ramiro OTY 4364; Espinoza, Cinthia Yarely OTY 4340; Dibene, Paul OTY2 4687; Perez, Anaiz OTY 4490; Iniguez, Efrain OTY 3810; Borquez, Jorge OTY 4398; Williams, Arianne SOPT 6191; Foglia,

Marcelo SOPT 5673

Subject: For approvals: DEV25-0100 Deflector ACT1

Attachments: DEV25-0100 Deflector ACT1.xls

Tracking: Recipient Response

Ramos, Arturo OTY2 4313

Casas, Ramiro OTY 4364

Espinoza, Cinthia Yarely OTY 4340

Dibene, Paul OTY2 4687

Perez, Anaiz OTY 4490

Iniguez, Efrain OTY 3810

Approve: 3/13/2025 8:10 AM

24Hr Rule Invoked

24Hr Rule Invoked

Approve: 3/14/2025 2:17 PM

Approve: 3/12/2025 7:52 PM

Borquez, Jorge OTY 4398

Williams, Arianne SOPT 6191

Approve: 3/13/2025 9:48 AM

Foglia, Marcelo SOPT 5673 Approve: 3/13/2025 5:55 AM

Hi Everyone

Please review and approve the attached document using the voting buttons in the email at your earliest convenience.

24Hr Rule will Apply

If additional information or more time to review is needed please use the "Discuss" button to request it.

Regards and thanks

Xavier Vela

Engineering Supervisor 619-661-4377 US 664-973-4377 MX

Ensambles Hyson

Ave. Industrial 333 Seccion Dorada Mesa de Otay 22500 Tijuana, Mexico Tijuana, Mexico