Drive_SOP_v2 - Scope & Safety

Document: Drive_SOP_v2.pdf Revision: A Section: VFD Fault Trip

Scope: maintenance procedure for vfd fault trip on plant equipment.

PPE: ISI helmet, cut-resistant gloves, safety goggles. Isolate power and apply lockout/tagout (LOTO). Operator fatigue below 70%. Written supervisor approval is required before starting.

VFD Fault Trip - Procedure

Follow these steps in order:

1. Power OFF + LOTO
2. Wait 5min capacitor discharge
3. Check motor insulation
4. Inspect cable
5. Reset fault
6. Ramp test

VFD Fault Trip - Symptoms, Limits & Escalation

Symptoms and limits: VFD overcurrent trip.

Keywords: vfd, drive, trip, overcurrent, inverter

Escalate to the maintenance supervisor if the fault persists after one attempt.