Gearbox_SOP_v2 - Scope & Safety

Document: Gearbox_SOP_v2.pdf Revision: A Section: Gearbox Oil & Noise

Scope: maintenance procedure for gearbox oil & noise on plant equipment.

PPE: ISI helmet, cut-resistant gloves, safety goggles. Isolate power and apply lockout/tagout (LOTO). Operator fatigue below 70%. Written supervisor approval is required before starting.

Gearbox Oil & Noise - Procedure

Follow these steps in order:

1. Power OFF + LOTO
2. Drain and sample oil
3. Check metal particles
4. Refill ISO VG 220
5. Check backlash 0.1mm
6. Test 15min

Gearbox Oil & Noise - Symptoms, Limits & Escalation

Symptoms and limits: Gearbox whine or oil temp >90C.

Keywords: gearbox, gear, whine, oil temp

Escalate to the maintenance supervisor if the fault persists after one attempt.