				Inputs				Control Outputs											Inni	ut Bits		Output Bits		
			_					· · · · · · · · · · · · · · · · · · ·																
INUM	Instruction	Mnemonic	Format	opcode	funct3	funct7	funct6	RFW	ALUOp	ALUSrcA	ALUSrcB	PCsel	WDsel	BROp	MST	MLD	MSZ	opcode	funt3	funct7	funct6	Project06	v2.0 raw	
0	addi	ADDI	ı	0010011	000	XXXXXXX	XXXXXX	1	0000	0	001	00	00	00	0	0	00	060010011	06000	0bxxxxxxxxx	Obxxxxxx	0b1000000010000000000	0x40400	
1	add	ADDR	R	0110011	000	0000000	XXXXXX	1	0000	0	000	00	00	00	0	0	00	060110011	0b000	060000000	Obxxxxxx	0b10000000000000000000	0x40000	
2	jal	JAL	J	1101111	XXX	XXXXXXXX	XXXXXX	1	0000	1	011	01	01	00	0	0	00	0b1101111	0bxxx	Obxxxxxxxx	0bxxxxxxxx	0b1000010110101000000	0x42D40	
3	jalr	JALR	1	1100111	000	XXXXXXX	XXXXXX	1	0000	0	001	01	01	00	0	0	00	0b1100111	0b000	Obxxxxxxx	Obxxxxxxxd	0b1000000010101000000	0x40540	
4	mul	MUL	R	0110011	000	0000001	XXXXXX	1	0001	0	000	00	00	00	0	0	00	0b0110011	0b000	0b0000001	Obxxxxxx	0b10001000000000000000	0x44000	
5	sub	SUBR	R	0110011	000	0100000	XXXXXX	1	0010	0	000	00	00	00	0	0	00	0b0110011	0b000	0b0100000	Obxxxxxx	0b10010000000000000000	0x48000	
6	sll	SLL	R	0110011	001	0000000	XXXXXX	1	0011	0	000	00	00	00	0	0	00	0b0110011	0b001	060000000	Obxxxxxxx	0b10011000000000000000	0x4C000	
7	srl	SRL	R	0110011	101	0000000	XXXXXX	1	0100	0	000	00	00	00	0	0	00	0b0110011	0b101	0ь0000000	Obxxxxxx	0ь1010000000000000000	0x50000	
8	sIlii	SLLI	1	0010011	001	0000000	shamt	1	0101	0	001	00	00	00	0	0	00	0b0010011	0b001	0ь0000000	Obshamt	0b1010100010000000000	0x54400	
9	srli	SRLI	1	0010011	101	0000000	shamt	1	0110	0	001	00	00	00	0	0	00	0b0010011	0b101	0ь0000000	Obshamt	0b1011000010000000000	0x58400	
10	srai	SRAI	1	0010011	101	0100000	shamt	1	0111	0	001	00	00	00	0	0	00	0b0010011	0b101	0b0100000	Obshamt	0ь1011100010000000000	0x5C400	
11	beq	BEQ	В	1100011	000	XXXXXXXX	XXXXXX	0	0000	1	010	10	01	00	0	0	00	0b1100011	06000	Obxxxxxxxx	Obxxxxxxx	050000010101001000000	0x2A40	
12	bne	BNE	В	1100011	001	XXXXXXXX	XXXXXX	0	0000	1	010	10	01	01	0	0	00	0b1100011	0b001	Obxxxxxxxx	Obxxxxxx	050000010101001010000	0x2A50	
13	blt	BLT	В	1100011	100	XXXXXXXX	XXXXXX	0	0000	1	010	10	01	10	0	0	00	0b1100011	0b100	Obxxxxxxxx	Obxxxxxx	050000010101001100000	0x2A60	
14	bge	BGE	В	1100011	101	XXXXXXXX	XXXXXX	0	0000	1	010	10	01	11	0	0	00	0b1100011	0b101	Obxxxxxxxx	Obxxxxxx	050000010101001110000	0x2A70	
15	ld	LD	1	0000011	011	XXXXXXXX	XXXXXX	1	0000	0	001	00	10	00	0	1	00	060000011	0b011	Obxxxxxxxx	Obxxxxxx	оь1000000010010000100	0x40484	
16	lw	LW	1	0000011	010	xxxxxxx	XXXXXX	1	0000	0	001	00	10	00	0	1	01	060000011	0b010	Obxxxxxxxx	Obxxxxxx	оь1000000010010000101	0x40485	
17	lb	LB	i	0000011	000	XXXXXXXX	XXXXXX	1	0000	0	001	00	10	00	0	1	10	0b0000011	0b000	Obxxxxxxxx	Obxxxxxx	оь1000000010010000110	0x40486	
18	sd	SD	S	0100011	011	XXXXXXX	XXXXXX	0	0000	0	100	00	00	00	1	1	00	0b0100011	0b011	Obxxxxxxx	Obxxxxxx	060000001000000001100	0x100C	
10	SW	SW	9	0100011	010	XXXXXXX	XXXXXX	10	0000	0	100	00	00	00	1	1	01	0b0100011	0b010	Obxxxxxxx	Obxxxxxx	060000001000000001101	0x100D	
20	eh.	SB	S	0100011	000	XXXXXXX	XXXXXX	0	0000	0	100	00	00	00	1	1	10	0b0100011	0b000	Obxxxxxxx	Obxxxxxx	060000001000000001110	0x100E	
24	and	AND		0110011	111	0000000	XXXXXX	Ĭ,	1000	0		00	00	00				060110011	0b111	060000000	Obxxxxxx	0b110000000000000000000	0x60000	
21		OR	R		111			L'	1000	0	000		00	00	0	0	00						0x60000 0x64000	
22	or	OR	R	0110011	110	0000000	XXXXXX	1	1001	U	000	00	00	00	0	U	00	0b0110011	0b110	0b0000000	Obxxxxxx	0b11001000000000000000	UX64000	