
Compensators of general form:

$$H(s) = K \left[\frac{\beta T s + 1}{T s + 1} \right]$$
 with $\begin{cases} \frac{37}{\beta} > 0 \\ \frac{37}{\beta} > 1 \end{cases}$

$$\Rightarrow 2c = -\frac{1}{\beta}T$$
, $P_c = -\frac{1}{\gamma}T$ so $|2c| < |P_c|$ (Zero closer to image axis) and $\beta = \frac{P_c}{2c}$ ("lead ratio")

Are called "lead compensators", since & H(jw)>0 for all w>0 (positive phase is called "lead").



Note here that:

$$U(s) = H(s)E(s) = \left\{ \begin{bmatrix} \beta \tau s + i \\ \tau s + i \end{bmatrix} E(s) \right\}$$

$$= \left\{ \begin{bmatrix} \beta - \frac{\beta - 1}{\tau s + i} \end{bmatrix} E(s)$$

$$= \times (t) = K\beta e(t) + K(i - \beta) \times_i(t) \quad \text{Corresponding}$$

$$\gamma \times_i(t) = - \times_i(t) + e(t) \quad \text{implementation equations}$$

So that |u(t)|or β generally. Want to find smallest value of $\beta = \frac{Pe}{z_c}$ which ensures $\phi_{max} \ge \phi_{reg}$.

We can compute:
$$\Phi_{\text{max}} = \sin^{-1} \left[\frac{\beta - 1}{\beta + 1} \right]$$

Which is an increasing function of B>1

$$\Phi_{\text{max}} = \Phi_{\text{req}}$$

Selection of T can then be achieved using analytical result

Revisit-previous example:

G(s) = 5(3+2) Want 8 Des=60°, Was=6

for which
$$\Phi_{reg} = 41.56°$$

Previous design used
$$H(s) = 93.4$$
 $\frac{5+5.54}{5+60}$ ($\beta = 10.8$)

New design:

Then
$$6 = \omega_{\text{Des}} = \omega_{\text{max}} = \frac{1}{\tau_{\text{J}\beta}} = \tau = \omega_{\text{Des}} = \omega_{\text{Des}}$$

and thus
$$H(s) = K\left[\frac{0.3755 + 1}{0.0755 + 1}\right] \quad (z_c = -2.67)$$

Then take
$$K = \frac{1}{|L_{olj}u_{bes}|} = 5.63$$
 here

Comparison of Designs:

For a unit step ya(t):

<u>Old design</u>: t= 0.96 sec, Mp=15%, Umex = 92

New design: £ = 0.86 sec, Mp = 10%, Umax = 27

New design is essentially the same (a little better) in transient performance, and requires a factor of 3 less maximum control effort.

=> minimizing & is very beneficial!

Another Example

Suppose
$$G(s) = \frac{3}{5(s-2)}$$

and we again want 8 Des = 45° with Whes = 6, which we know is assured if:


$$L(s) = \frac{6^2 \sqrt{2}}{5 (5+6)}$$


You might be tempted to try
$$H(s) = \left(\frac{6^2\sqrt{\Sigma}}{3}\right)\left[\frac{5-2}{5+6}\right]$$

Don't do it! Pole-zero concellation Cannot be guaranteed to be exact here, and CL system will have an unstable pole (try it! Use (5-2.1) in numerator and see what happens).


Instead, meet targets using only LHP poles/zeros.

Check Nyquist: Ensure 8>0 still stabilizing





Will stabilize if - I in shaded area!



With -I in desired region, Phase mangin will be

Positive => agrees with our basic design guideline

Positive & is stabilizing here!

$$=> 2c = -\left[\frac{\omega_{DCS}}{\tan \Phi_{reg}}\right] = -3$$

For an implementable design, simple approach is again to put Pole at -lownes, increase Area by 5.70, giving

$$H(s) = 1/8.79 \left[\frac{(s+2.27)}{(s+60)} \right]$$

Or, we could do a lead comp design, if the above requires excessively large u(+).

$$G(5) = \frac{3}{5(5-2)}$$

Suppose we want instead Ypes = 70° at whee = 6

 $\Phi_{reg} = 70-180-4G(j) = 88.43^{\circ}$, Add +5.7° for pole, need $4(j\omega_{ses}-2e) = 94.13^{\circ}$

This condition connot be satisfied with a single LHP zero New 2 zeros here.

With 2 zeros, can add up to +1800 to 4LLjwl. Lots of choicer for 2 zeros adding up to 94.130 at w=6. Can simplify design if we assume zeros/poles repeated

$$H(s) = K \left[\frac{(s-2c)^2}{(s-2c)^2} \right]$$

 $50 \times H(j\omega) = 2 \times (j\omega - 2c) - 2 \times (j\omega - Pc)$ $=> \times (j\omega_{es} - 2c) = \frac{\phi_{reg}}{2} + \times (j\omega_{bes} - Pc)$

for example, using
$$P_c = -10\omega_{Des} = -60$$
 again

and
$$H(s) = 747.89 \left[\frac{(5+5.05)^2}{(5+60)^2} \right]$$

(Again, could instead do a lead comp design -See next page).

Note: Above considerations apply any time we would near $2H(j\omega_{Des}) > 90^{\circ}$. Not specific to this example.

We can apply similar thinking for more complicated situations: i.e. if we would need

xH(judes)>180°

Then we need 3 LHP zeros in H(s), etc.

Alternate lead comp design for above

Using again
$$3_{\text{des}} = 70^{\circ}$$
, $\omega_{\text{des}} = 6$
Set $\Phi_{\text{max}} = \frac{\Phi_{\text{reg}}}{2} => \beta = 5.61$

$$\omega_{max} = 6 = > 7 = .07$$

$$H(s) = K \left[\frac{(.395s+1)^2}{(.07s+1)^2} \right]$$

$$K = \frac{1}{1L_0(6j)1} = 2.255$$

Comparison of different designs

8=45°: Zerolfarpole: ts=1.95sec, Mp=51%, umax=119

Lead: ts=1.4sec, Mp=53%, Umax=52

8=70°

Zerolfarpole: ts=3.0 sec, Mp=40%, umax=700

Lead: ts = 3.9 sec, Mp = 47%, Umax = 71

Which is better ...? That becomes a judgement call Also need to consider tracking, bandwidth, robustness, and how "tight" your requirements actually are...

Suppose again we had wanted $X=45^{\circ}$, $W_{8}=6$ and we (naively) ignored my caved and chose

$$H(s) = \left(\frac{6^2\sqrt{2}}{3}\right)\left(\frac{5-2}{5+6}\right)$$

If the G(s) really is:

$$G(s) = \frac{3}{5(s-1.9)}$$
 [5% uncertainty in unstable pole location]

we'd have CL poles at: -3.04 ± 6.5j, 1.97 unstable!

With the two designs above, we'd instead have CL poles: