

BRIDGE INSPECTION RECORD



Bridge Number 081280AA0208001
Facility Carried CR 115
Feature Intersected DRY CALIFORNIA CREEK

Inspector Barnett, Jason
Inspection Completion Date 04/27/2026
Maint. Section

Condition Rating

Description*

- N NOT APPLICABLE - Component does not exist.
- 9 EXCELLENT - Isolated inherent defects.
- 8 VERY GOOD - Some inherent defects.
- 7 GOOD - Some minor defects.
- 6 SATISFACTORY - Widespread minor or isolated moderate defects.
- 5 FAIR - Some moderate defects; strength and performance of the component are not affected.
- 4 POOR - Widespread moderate or isolated major defects; strength and/or performance of the component is affected.
- 3 SERIOUS - Major defects; strength and/or performance of the component is seriously affected. Condition typically necessitates more frequent monitoring, load restrictions, and/or corrective actions.
- 2 CRITICAL - Major defects; component is severely compromised. Condition typically necessitates frequent monitoring, significant load restrictions, and/or corrective actions in order to keep the bridge open.
- 1 IMMINENT FAILURE - Bridge is closed to traffic due to component condition. Repair or rehabilitation may return the bridge to service.
- 0 FAILED - Bridge is closed due to component condition, and is beyond corrective action. Replacement is required to restore service.

**These descriptions are for B.C.01 through B.C.07 by correlating field observations with Table 20 in SNBI. Code B.C.08 through B.C.11 using the tables embedded in the component descriptions.*

Bridge Description:

6 - Barrel Concrete Box Culvert @ No Skew (10' x 8' x 26.0')

General Comments:

Bridge nomenclature is from north to south as per the previous inspection.

Note: Elements below component rating does not affect overall component condition rating.

**DECK
(B.C.01)**

Bridge Number: 081280AA0208001 Inspection Completion Date: 04/27/2026
DO NOT DISCLOSE. THIS INFORMATION IS CONFIDENTIAL UNDER THE TEXAS HOMELAND SECURITY ACT & 23 U.S.C SECTION 409, SAFETY SENSITIVE INFORMATION.

Element/Component	Description	Min.	Rating	Comment
Deck - Component Rating		0	N	
Wearing Surface	No Separate Wearing Surface	0	N	
Surfacing Thickness:	inches			
Fill Height:	inches			
Drainage System		0	7	Minor dirt and gravel accumulation along shoulders slightly hinders proper drainage.
Curbs & Sidewalks		0	N	
Delineation		0	N	
Other	Vegetation	0	7	Tree branches encroach over the roadway at the northeast, northwest, and southeast bridge corners.

**SUPERSTRUCTURE
(B.C.02)**

Bridge Number: 081280AA0208001 Inspection Completion Date: 04/27/2026
DO NOT DISCLOSE. THIS INFORMATION IS CONFIDENTIAL UNDER THE TEXAS HOMELAND SECURITY ACT & 23 U.S.C SECTION 409, SAFETY SENSITIVE INFORMATION.

DO NOT DISCLOSE. THIS INFORMATION IS CONFIDENTIAL UNDER THE TEXAS HOMELAND SECURITY ACT & 23 U.S.C SECTION 409, SAFETY SENSITIVE INFORMATION.

Element/Component	Description	Min.	Rating	Comment
Main Members - Steel		0	N	
Main Members - Concrete		0	N	
Main Members - Timber		0	N	
Main Members - Connections		0	N	
Floor System Members		0	N	
Floor System Connections		0	N	
Secondary Members		5	N	
Secondary Mem. Connections		5	N	
Other		0	N	
Overall Component Rating			N	
Steel Protective Coating		0	N	

SUBSTRUCTURE (B.C.03)

Bridge Number: 081280AA0208001 Inspection Completion Date: 04/27/2026
DO NOT DISCLOSE. THIS INFORMATION IS CONFIDENTIAL UNDER THE TEXAS HOMELAND SECURITY ACT & 23 U.S.C SECTION 409, SAFETY SENSITIVE INFORMATION.

Element/Component	Description	Min.	Rating	Comment
Abutment Caps		0	N	
Above Ground		0	N	
Below Ground or Foundation		0	N	
Backwalls & Wingwalls		5	N	
Intermediate Supports:				
Caps - Concrete		0	N	
Caps - Steel		0	N	
Caps - Timber		0	N	
Above Ground - Concrete		0	N	
Above Ground - Steel		0	N	
Above Ground - Timber		0	N	
Above Ground - Masonry		0	N	
Below Ground or Foundation		0	N	
Other		0	N	
Overall Component Rating			N	
Collision Protection System		0	N	
Steel Protective Coating		0	N	

CULVERT (B.C.04)

Bridge Number: 081280AA0208001 Inspection Completion Date: 04/27/2026
DO NOT DISCLOSE. THIS INFORMATION IS CONFIDENTIAL UNDER THE TEXAS HOMELAND SECURITY ACT & 23 U.S.C SECTION 409, SAFETY SENSITIVE INFORMATION.

Element/Component	Description	Min.	Rating	Comment
Top Slabs		0	7	The top surface of top slab exhibits medium (<1/32" wide) transverse cracks, minor wear/scaling, and minor edge spalls along approach roadway interfaces. Top slab soffits have insignificant longitudinal cracks. Top slab soffits at the culvert corners exhibit medium (up to 1/32" wide) cracks and minor delaminations/spalls, some with exposed reinforcement.
Bottom Slab or Footing		0	8	
Abutments, Intermed. Supports		0	7	Culvert walls have insignificant vertical cracks.
Headwalls & Wingwalls		5	7	Northeast wingwall has a minor delamination along the top. Wingwalls have insignificant vertical and diagonal cracks.
Other		0	N	
Overall Component Rating			7	

RAILINGS (B.C.05)

Bridge Number: 081280AA0208001 Inspection Completion Date: 04/27/2026
DO NOT DISCLOSE. THIS INFORMATION IS CONFIDENTIAL UNDER THE TEXAS HOMELAND SECURITY ACT & 23 U.S.C SECTION 409, SAFETY SENSITIVE INFORMATION.

Element/Component	Description	Min.	Rating	Comment
Median Barrier		0	N	
Railings		0	7	Steel rails have isolated minor impact scrapes.
Railing Type:	T6			
Measured Rail Height:	27	inches		
B.RH.01 Bridge Railings:	I			

DO NOT DISCLOSE. THIS INFORMATION IS CONFIDENTIAL UNDER THE TEXAS HOMELAND SECURITY ACT & 23 U.S.C SECTION 409, SAFETY SENSITIVE INFORMATION.

Other	0	N
Overall Component Rating	7	
Railing Protective Coating	0	8
Pedestrian Railing	0	N

RAILING TRANSITIONS (B.C.06)

Bridge Number: 081280AA0208001 Inspection Completion Date: 04/27/2026
DO NOT DISCLOSE. THIS INFORMATION IS CONFIDENTIAL UNDER THE TEXAS HOMELAND SECURITY ACT & 23 U.S.C SECTION 409, SAFETY SENSITIVE INFORMATION.

Element/Component	Description	Min.	Rating	Comment
Transition Railings		0	8	
Railing Transition Type:	Not Listed Other			
B.RH.02 Transitions:	I			
Other		0	N	
Overall Component Rating			8	
Railing Transitions Protective Coating		0	8	

BEARINGS (B.C.07)

Bridge Number: 081280AA0208001 Inspection Completion Date: 04/27/2026
DO NOT DISCLOSE. THIS INFORMATION IS CONFIDENTIAL UNDER THE TEXAS HOMELAND SECURITY ACT & 23 U.S.C SECTION 409, SAFETY SENSITIVE INFORMATION.

Element/Component	Description	Min.	Rating	Comment
Expansion Bearings		0	N	
Fixed Bearings		0	N	
Other		0	N	
Overall Component Rating			N	

JOINTS (B.C.08)

Bridge Number: 081280AA0208001 Inspection Completion Date: 04/27/2026
DO NOT DISCLOSE. THIS INFORMATION IS CONFIDENTIAL UNDER THE TEXAS HOMELAND SECURITY ACT & 23 U.S.C SECTION 409, SAFETY SENSITIVE INFORMATION.

Element/Component	Description	Min.	Rating	Comment
Joints, Expansion, Open		0	N	
Joints, Expansion, Sealed		0	N	
Joints, Other		0	N	
Overall Component Rating			N	

CHANNEL (B.C.09)

Bridge Number: 081280AA0208001 Inspection Completion Date: 04/27/2026
DO NOT DISCLOSE. THIS INFORMATION IS CONFIDENTIAL UNDER THE TEXAS HOMELAND SECURITY ACT & 23 U.S.C SECTION 409, SAFETY SENSITIVE INFORMATION.

Element/Component	Description	Min.	Rating	Comment
Channel Banks		0	7	Downstream channel banks have minor erosion. There is extensive undergrowth and moderate drift accumulation near a fence in the upstream channel.
Channel Bed		0	6	Minor scour in the channel bed along the upstream and downstream side of the culvert. Upstream and downstream bottom slab toe walls are exposed up to 1.5' high at Barrels 3 and 4 due to scour. Minor drift accumulation is caught on Wall 4 along the upstream side of the culvert.
Other		0	N	
Overall Component Rating			6	

CHANNEL PROTECTIONS (B.C.10)

Bridge Number: 081280AA0208001 Inspection Completion Date: 04/27/2026
DO NOT DISCLOSE. THIS INFORMATION IS CONFIDENTIAL UNDER THE TEXAS HOMELAND SECURITY ACT & 23 U.S.C SECTION 409, SAFETY SENSITIVE INFORMATION.

Element/Component	Description	Min.	Rating	Comment
Rip Rap, Toe Walls & Apron		0	N	
Dikes		0	N	
Jetties		0	N	
Gabion		0	N	
Other		0	N	
Overall Component Rating			N	

SCOUR

Bridge Number: 081280AA0208001 Inspection Completion Date: 04/27/2026

DO NOT DISCLOSE. THIS INFORMATION IS CONFIDENTIAL UNDER THE TEXAS HOMELAND SECURITY ACT & 23 U.S.C SECTION 409, SAFETY SENSITIVE INFORMATION.

(B.C.11)**DO NOT DISCLOSE. THIS INFORMATION IS CONFIDENTIAL UNDER THE TEXAS HOMELAND SECURITY ACT & 23 U.S.C SECTION 409, SAFETY SENSITIVE INFORMATION.**

Element/Component	Description	Min.	Rating	Comment
Abutment				
Wall & Footing		0	N	
Unprotected Slope		0	N	
Protected Slope		0	N	
Interior Bent				
Spread Footing		0	N	
Piling/Drilled Shaft		0	N	
Culvert				
Pipe		0	N	
Box		0	6	Minor scour in the channel bed along the upstream and downstream side of the culvert. Upstream and downstream bottom slab toe walls are exposed up to 1.5' high at Barrels 3 and 4 due to scour.
Bottomless		0	N	
Other		0	N	
Overall Component Rating			6	

APPROACHES

Bridge Number: 081280AA0208001 Inspection Completion Date: 04/27/2026
DO NOT DISCLOSE. THIS INFORMATION IS CONFIDENTIAL UNDER THE TEXAS HOMELAND SECURITY ACT & 23 U.S.C SECTION 409, SAFETY SENSITIVE INFORMATION.

Element/Component	Description	Min.	Rating	Comment
Embankments		0	7	Minor erosion gully along the northwest roadside ditch.
Embankment Retaining Walls		4	N	
Slope Protection		5	7	See Embankments comment.
Roadway		5	7	Approach roadways have been regraded since prior inspection. Gravel approaches are slightly uneven with minor rutting.
Relief Joints		6	N	
Drainage		6	8	
Guardfence		6	8	
Delineation		7	7	No object markers are present at the ends of the northwest and southeast guardfences. Object marker at the end of the northeast guardfence is damaged.
Sight Distance		7	8	
Other	Vegetation	0	7	Tree branches overhang the roadway along the northeast, northwest, and southeast guardfences.
Overall Component Rating			7	

MISCELLANEOUS

Bridge Number: 081280AA0208001 Inspection Completion Date: 04/27/2026
DO NOT DISCLOSE. THIS INFORMATION IS CONFIDENTIAL UNDER THE TEXAS HOMELAND SECURITY ACT & 23 U.S.C SECTION 409, SAFETY SENSITIVE INFORMATION.

Element/Component	Description	Min.	Rating	Comment
Signs		7	N	
Illumination		7	N	
Warning Devices		7	N	
Utility Lines		7	N	
Other		0	N	

APPRAISAL & WORK EVENTS

Bridge Number: 081280AA0208001 Inspection Completion Date: 04/27/2026
DO NOT DISCLOSE. THIS INFORMATION IS CONFIDENTIAL UNDER THE TEXAS HOMELAND SECURITY ACT & 23 U.S.C SECTION 409, SAFETY SENSITIVE INFORMATION.

B.AP.01: Approach Roadway Alignment	G - Good
B.AP.02: Overtopping Likelihood	2 - Very Low - once every 51 to 99 years
B.AP.03: Scour Vulnerability	A - Scour appraisal completed. Bridge determined to be stable for scour.
B.AP.04: Scour Plan of Action	0 - A scour POA is not required.
B.AP.05: Seismic Vulnerability	N - Bridge does not require seismic evaluation due to low anticipated ground motion or agency prioritization.
B.W.01: Year Built	2001

DO NOT DISCLOSE. THIS INFORMATION IS CONFIDENTIAL UNDER THE TEXAS HOMELAND SECURITY ACT & 23 U.S.C SECTION 409, SAFETY SENSITIVE INFORMATION.

Work Event 1

B.W.02: Year Work Performed ... 2025
B.W.03: Work Performed 0

Work Event 2

B.W.02: Year Work Performed ... 2026
B.W.03: Work Performed ["0"]