Yamaha USB-MIDI Driver V1.3.2 for Mac OS X Release Notes

Contents

System Requirements for Software

OS	Mac OS X 10.5–10.8.x
Computer	Mac computer and a USB port with a Power Mac G4 or higher, or using Intel Processor
Available Memory	512 MB or more
Hard Disk	2 MB or more

NOTE

- Keep in mind that the software is often updated and the system requirements are subject to change. You can check the latest version information of each software and its system requirements at the following website.

  http://www.global.yamaha.com/download/usb_midi/

- For ProAudio products, please refer to the following website:

  http://www.yamahaproaudio.com/downloads/

- The system requirements may differ slightly depending on the particular computer.

Main Revisions and Enhancements

V1.3.1 → V1.3.2

- Now supports Mac OS X 10.8.

Previous Updates

V1.3.0 → V1.3.1

- An uninstaller function is included. For details about using it, refer to the included Installation Guide.
- Changed the function in which the "Old style port name" checkbox works when "YAMAHA USB-MIDI Control Panel" under "System Preferences" is active. For details about this function, refer to the included Installation Guide.
- Solved some minor problems.

V1.2.2 → V1.3.0

- Now supports Mac OS X 10.7.
- Now supports 64-bit native.
- Modified the installer to display "Software License Agreement" while installing.
- Minor bug fixes.

V1.2.1 to V1.2.2

- Minor bug fixes.

V1.2.0 to V1.2.1

- Now supports Mac OS X 10.6.
- Changed the specification so that the driver now supports Mac OS X 10.4.11 or later.
- Minor bug fixes.

V1.1.1 to V1.2.0

- Changed the specification so that MIDI Port names did not show any device names.
- The MIDI Patch function and the MIDI Thru function have been removed.
- Minor bug fixes.

V1.1.0 to V1.1.1

- A problem in which the driver did not operate properly in some language environments has been corrected.
- Minor bug fixes.

V1.0.4 to V1.1.0

- Support for Macintosh computers using Intel processors has been added.

V1.0.3 to V1.0.4

- Problems in which the MIDI driver occasionally hangs up during transmission and reception of MIDI data when using a dual CPU Macintosh have been corrected.

V1.0.1 to V1.0.3

- Handling of system exclusive message errors has been improved.

V1.0.0 to V1.0.1

- Problems in opening the audio port of the UW500/UW10 when using Emagic Logic have been

corrected.

V1.0.0b1 to V1.0.0

- Design of icons has been changed.

Information

The installer of this software component has been digitally-signed. When the certification expires, the installer will operate as follows depending on the OS version.

Mac OS X 10.5	The software will be installed as usual.
Mac OS X 10.6	The software will be installed as usual. Please note that updating the OS to the latest version is necessary.
Mac OS X 10.7	The window which indicates the expiration of the certification will be displayed. To install the software, click [Continue].
Mac OS X 10.8	The software will be installed as usual.

To confirm the expiration date of the certification, click the certification icon or key icon on the upper right of the installation window.